

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Ferguson Construction Co.	Contact	Misty Hein
Address	200 South Commercial, Lovington, NM 88260	Telephone No.	(575) 396-3689
Facility Name	SHU #3 10" Fiberglass Pipeline	Facility Type	Pipeline
Surface Owner	Oxy	Mineral Owner	
		API No.	30-025-07569

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	34	18S	38E					Lea County, NM

Latitude N 32.70185° Longitude W 103.14348°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5 bbls oil, 395 bbls produced water	Volume Recovered	190 bbls
Source of Release	Contractor struck line during backhoe operations	Date and Hour of Occurrence	07/30/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, NMOCD		
By Whom?	Tony Aguilar	Date and Hour	07/30/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	<div style="border: 2px solid blue; border-radius: 15px; padding: 10px; display: inline-block;"> <p>RECEIVED By OCD District 1 at 10:40 am, Aug 11, 2015</p> </div>				

Describe Cause of Problem and Remedial Action Taken.*

Ferguson Construction Co. struck a 10" fiberglass pipeline during backhoe operations causing 5 bbls of oil and 395 bbls of produced water to leak onto the ground. A vacuum truck recovered 190 bbls and the pipeline was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 240' x 150' with most of the leak settling in the trench area. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Misty Hein

Printed Name: Misty Hein

Approved by Environmental Specialist:

Kellie Jones

Title: Vice President

Approval Date: 08/11/2015

Expiration Date: 10/11/2015

E-mail Address: mistyh@fergusoncc.com

Conditions of Approval:

Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.

Attached
IRP-3794

Date: 8-7-2015 Phone: (575) 396-3689

* Attach Additional Sheets If Necessary

nKJ1522339621
pKJ1522347128