

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Covington A Federal #9 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-25-32036

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	25	22S	32E					Lea County, NM

Latitude N 32.35671° Longitude W 103.63024°

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	3 bbls oil, 10 bbls produced water	Volume Recovered	10 bbls
Source of Release	Corrosion of 2" steel production line	Date and Hour of Occurrence	7/22/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes, & Tomas Oberding-NMOCD; Shelly Tucker & James Amos-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/22/2015 @ 4:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

**RECEIVED**


By OCD District 1 at 8:51 am, Aug 18, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Corrosion of a 2" steel production line caused 3 bbls of oil and 10 bbls of produced water to leak onto the ground. A vacuum truck recovered 10 bbls of fluids and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 85' x 25' inside the containment on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by Environmental Specialist: 			
Title:	HES Lead	Approval Date:	08/18/2015	Expiration Date:	10/18/2015
E-mail Address:	Chancey_Summers@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.			Attached <input type="checkbox"/>
Date:	7-13-15	Phone:	(432) 685-5824	1RP-3806	

\* Attach Additional Sheets If Necessary

nKJ1523032398  
pKJ1523032646