

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Madera 17 Federal #1H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-25-41059

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	17	26S	35E					Lea County, NM

Latitude N 32.04947° Longitude W 103.38851°

### NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	135 bbls oil, 20 bbls produced water	Volume Recovered	130 bbls oil, 13 bbls produced water
Source of Release	Over-pressure of a line caused the heater treater fire tube gasket to fail	Date and Hour of Occurrence	07/21/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones- NMOCD; Shelly Tucker and James Amos- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	07/21/2015 @ 4:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 9:14 am, Aug 18, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Over-pressure of a line caused the heater treater fire tube gasket to fail thus spilling 135 bbls of oil and 20 bbls of produced water onto the ground. A vacuum truck recovered 130 bbls of oil and 13 bbls of produced water and the gasket was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 250' x 50' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers		Approved by Environmental Specialist: 	
Title: HES Lead		Approval Date: 08/18/2015	Expiration Date: 10/18/2015
E-mail Address: Chancey_Summers@oxy.com		Conditions of Approval:	
Date: 8-13-15	Phone: (432) 685-5824	Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	
		Attached <input type="checkbox"/> 16696 IRP-3807	

\* Attach Additional Sheets If Necessary

nKJ1523033395  
pKJ1523033577