

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Tuesday, October 13, 2015 7:06 AM
To: 'Everhart, Harley'
Subject: RE: Cedar Brakes Spill / Unit 3685_10.9.15

Harley,

Yes, OCD does request the visually identifiable impact shown in the photograph to be removed. Typically, staining like this is indicative of lighter end hydrocarbon impact. Once removed, a confirmation sample is requested.

Thank you,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Everhart, Harley [mailto:heverhart@akaenergy.com]
Sent: Friday, October 09, 2015 7:15 AM
To: Bratcher, Mike, EMNRD
Subject: RE: Cedar Brakes Spill / Unit 3685_10.9.15

Hello Mike

Just to clarify, you are you requesting Frontier Field Services to remediate the area just past sample #5 marker, correct? Will you require additional sampling in this small surficial area after remediation or will a picture be adequate?

Respectfully,

Harley Everhart

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Thursday, October 08, 2015 7:05 AM
To: Everhart, Harley <heverhart@akaenergy.com>
Cc: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>
Subject: RE: Cedar Brakes Spill / Unit 3685_10.7.15

Harley,

I would prefer to just get it out of there. It looks like a relatively small surficial area, but the source could be larger.

Thanks,

Mike Bratcher

NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Everhart, Harley [<mailto:heverhart@akaenergy.com>]
Sent: Wednesday, October 07, 2015 3:58 PM
To: Bratcher, Mike, EMNRD
Subject: RE: Cedar Brakes Spill / Unit 3685_10.7.15

Hello Mike

The hydrocarbon leaching did not appeared to go beyond sample #5, going south. As a result, I did not sample anything preceding that point. I do have a MiniRAE 3000 VOC tester, I can go out and test the SW wall, if that would be suitable to clear up any concerns? The spill was a result of a café rubbing up against a valve that went to a tank positioned just west from sample 6, on the surface. The tank was permanently taken out of service; in addition, installed handles were detached from this location and from other locations to avert any reoccurrence.

Thank you for your leadership on this matter.

Harley Everhart
Environmental, Health, and Safety

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]
Sent: Wednesday, October 07, 2015 2:48 PM
To: Everhart, Harley <heverhart@akaenergy.com>
Cc: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Jones, Kellie, EMNRD <Kellie.Jones@state.nm.us>; Keyes, Jamie, EMNRD <Jamie.Keyes@state.nm.us>
Subject: RE: Cedar Brakes Spill / Unit 3685_10.7.15

Harley,

It did get processed in District 1, but not an issue, we can deal with that. I am not up to speed on this, and the analytical data looks good, but in the photo, the area behind the "5" looks like hydrocarbon leaching. Has that specific area been excavated and tested?

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Everhart, Harley [<mailto:heverhart@akaenergy.com>]
Sent: Wednesday, October 07, 2015 10:02 AM
To: Bratcher, Mike, EMNRD
Subject: FW: Cedar Brakes Spill / Unit 3685_10.7.15
Importance: High

Hello Mike

I believe this was initially sent to Kellie Jones and she started processing; however, it was later decided that this needed to be forward to you. Please review. Frontier Field Services is respectfully requesting approval to backfill the emediaiton site using clean soil.

Reference; Cedar Brakes Spill / Unit 3685_10.6.15

3685	6/23/2015	Ini c-141	Frontier Field Services	Maljamar Gas plant	18S 31E 14	
-------------	-----------	-----------	-------------------------------	--------------------	------------	--

Fri 10-2-2015

Harley - based on these lab results, I give BLM's approval to backfill the emediaiton site. please use clean - not remediated - fill.

Randal "Randy" Pair
Envir. Protection Specialist - Realty Compliance
office: 575.234.6240
cell: 575.361.0062
email: rpair@blm.gov

From: Everhart, Harley
Sent: Tuesday, June 23, 2015 8:42 AM
To: Jones, Kellie, EMNRD (Kellie.Jones@state.nm.us) <Kellie.Jones@state.nm.us>; 'rpair@blm.gov' <rpair@blm.gov>
Cc: Busch, Greg <gbusch@akaenergy.com>; Prentiss, John <jprentiss@akaenergy.com>; Quiroz, Rudy <rquiroz@akaenergy.com>
Subject: Initial C-141_Cedar Brakes Spill_6.23.2015

NMOCD/BLM;

Attached is the initial C-141 for the Cedar Brakes Spill located at **Latitude** 32° 75' 43.16" N **Longitude** -103° 84' 19.31" W.

The cause and conditions of the spill was identified and alleviated. Excavation will commence until TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". Impacted soils will be transported to an OCD approved facility for disposal and the area will be backfilled with clean soil.

Should you have any comments or concerns, please do not hesitate to contact me anytime.

Thank you for your leadership on this matter.

Respectfully,

Harley Everhart

EH&S Compliance

(575) 677-5140 - Direct

(575) 513-4922 - Cell

(575) 676-2401 - Fax

heverhart@akaenergy.com



CONFIDENTIALITY NOTICE:

This email, including attachments, may include confidential and/or proprietary information, and may be used only by the person or entity to which it is addressed. Please do not read, copy or disseminate this communication unless you are the intended addressee. If you have received this communication in error, please permanently delete and call (575) 677-5140 immediately and ask to speak to the sender of this communication. Also, please notify immediately via email that you have received this message in error.