

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

OCT 30 2015

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

X ☐ Initial Report ☐ Final Report

Name of Company: Holly Energy Partners	Contact: Keith Gerace-Compliance Auditor/Lead	
Address: 1602 W. Main Street, Artesia, NM, 88210	Telephone No.: 575-748-4083	
Facility Name: Maljamar Park Lact 584	Facility Type: Truck LACT Unloading/Crude Storage facility	
Surface Owner: Holly Energy Partners	Mineral Owner	API No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Lea County
-------------	---------	----------	-------	---------------	------------------	---------------	----------------	-----------------------------

Latitude **32.857697** Longitude **103.796564**


NATURE OF RELEASE

Type of Release: Crude	Volume of Release: Estimated 25 Barrels	Volume Recovered: 18 barrels
Source of Release: Crude Storage Tanks	Date and Hour of Occurrence: 10/26/15 @ 05:04 AM	Date and Hour of Discovery: 10/26/15 @ 05:04 AM
Was Immediate Notice Given? X ☐ Yes ☐ No ☐ Not Required	If YES, To Whom? Heather Paterson 575-748-1283, and Jamie Keys at 575-393-6161 X 113 at 14:15 PM 10/26/15	
By Whom? Keith Gerace	Date and Hour: 10/26/15 05:28 AM	
Was a Watercourse Reached? ☐ Yes ☐ No	If YES, Volume Impacting the Watercourse: NA	
If a Watercourse was Impacted, Describe Fully. * No watercourse impacted		

Describe Cause of Problem and Remedial Action Taken. * **HEP I & E technicians traced the cause of overfill & release of 25 barrels from the tanks to equipment failure. A relay that would automatically shut down the truck unloading LACT to the tanks at high level failed. Repairs were completed (Relay replaced), tested, and the station was put back into service.**

Describe Area Affected and Cleanup Action Taken. * **Contaminated soil was placed on plastic for proper removal and disposal. Affected area had microbes applied, raked into area, water applied to microbes, and will continue to monitor area.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Keith Gerace		Approved by Environmental Specialist: 	
Title: Compliance Auditor/Lead		Approval Date: 11/24/2015	Expiration Date: 01/24/2016
E-mail Address: keith.gerace@hollyenergy.com		Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines.	
Date: 10/29/2015 Phone: 575-748-4083		Attached ☐ 1RP 3998	

* Attach Additional Sheets If Necessary

nJXK1532855980
pJXK1532856095