

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 10:33 am, Nov 30, 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

<b>Name of Company:</b> Chevron USA Inc.	<b>Contact:</b> Nick Hampton
<b>Address:</b> 15 Smith Rd., Midland, TX, 79705	<b>Telephone No.:</b> wk: 575-704-3143 cell: 985-502-2342
<b>Facility Name:</b> West Dollarhide Drinkard Unit Sat #6 to WDDU Central Battery Line	<b>Facility Type:</b> Battery

<b>Surface Owner:</b> State surface	<b>Mineral Owner</b> (QLS-091040 – State of New Mexico B-9613 LSE)	<b>API No.:</b> N/A
-------------------------------------	--	---------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	24-S	38E					Lea

Latitude: 32 deg 9.788 minutes north / Longitude: -103 deg 5.218 minutes west

### NATURE OF RELEASE

<b>Type of Release:</b> Spill	<b>Volume of Release:</b> 50.38 bbls total fluid	<b>Volume Recovered:</b> 50.38 bbls total fluid
<b>Source of Release:</b> Fiberglass line	<b>Date and Hour of Occurrence</b> 11/24/2015 12:45pm	<b>Date and Hour of Discovery</b> 11/24/2015 12:45pm
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Kellie Jones	
<b>By Whom?</b> Nick Hampton	<b>Date and Hour:</b> 11/24/2015 4:56PM	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse.</b>	

**If a Watercourse was Impacted, Describe Fully.\***

N/A


**Describe Cause of Problem and Remedial Action Taken.\***

Track hoe struck an unmarked 4" fiberglass line while digging ditch for new injection lateral line. The strike resulted in release of 46.22 bbls produced water and 4.16 bbls oil. Vacuum truck immediately recovered produced water and oil from ditch and further remediation is in progress.

**Describe Area Affected and Cleanup Action Taken.\***

Area inside ditch excavated by track hoe was affected. Further remediation is in progress.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> Nick Hampton	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Nick Hampton	<b>Approved by Environmental Specialist:</b> 	
<b>Title:</b> HE Specialist	<b>Approval Date:</b> 11/30/2015	<b>Expiration Date:</b> 01/30/2016
<b>E-mail Address:</b> cikb@chevron.com	<b>Conditions of Approval:</b>	
<b>Date:</b> 11/29/2015 <b>Phone:</b> 985-502-2342	Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos recommended.	<b>Attached</b> <input type="checkbox"/> IRP 4002

\* Attach Additional Sheets If Necessary