Gandy Corporation Nuckols 24 #1 Site Investigation Section 24, Township 7S, Range 31E Chaves County, New Mexico

April 12, 2016



Prepared for:

Gandy Corporation 1623 South Main Lovington, New Mexico 88260

By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Hobbs, New Mexico 88240 (505) 397-0510

TABLE OF CONTENTS

I.	COMPANY CONTACTS	. 1
II.	BACKGROUND	. 1
III.	SURFACE AND GROUND WATER	. 1
IV.	SOILS	. 1
		•
٧.	WORK PERFORMED	. 1
VI.	FIGURES & APPENDICES	. 1

I. Company Contacts

Bob Allen	505-397-0510	ballen@sesi-nm.com						
Steve Houston	432-684-4293	Stevehouston@gandycorporation.com						

II. Background

SESI was contracted to perform a site investigation to determine the vertical extent of contamination at the Nuckols 24 #1 location. The subject area is located in Section 24, Township 7S, Range 31E in Chaves County, New Mexico.

II. Surface and Ground Water

The nearest groundwater water of record with the New Mexico State Engineer's Office is in section 26, township 07S and range 31E. The depth to water for this well is 120 feet bgs. However, there is no record of groundwater in the immediate vicinity. The average depth to water for this area is 238' bgs (Appendix A).

III. Soils

The soils in the area are predominantly sand and sandy loam.

IV. Work Performed

On April 11, 2016 SESI personnel, Gandy personnel together with a backhoe and operator, as well as a Rocky Mountain representative were on site to assess the spill area at this location. Heavy hydro carbon staining on the area were present (Figure 2). The location and spill area were mapped using a handheld Juno 3B (Figure 1). The spill area measured approximately 4,440.88 sq. ft. The backhoe operations included but were not limited to surface scraping of visual staining followed by the installation of test trenches. The results are recapped in the following table:

Date	ID	Depth	CI ⁻	TPH			
4-11-16	TT-1	6"	156	.06			
4-11-16	TT-1	1.5'	108	No test			
4-11-16	TT-2	6"	<108	.06			
4-11-16	TT-2	1.5'	<108	No test			

VI. Figures & Appendices

Figure 1 – Site Plan
Figure 2 – Photo Documentation
Appendix A - Groundwater

Figure 1 Site Plan




Figure 2 Photo Documentation



Sign marking location



Release Point Area



Pasture Impact



Release Point



Impacted area West side of location



Fluid run Southwest pasture area



Spill run impacting pasture



Impacted area west of location



Spill run looking south



Spill traverse west onto lease road



Spill Run North side



Surface Removal of north side



Standing fluid west of pad







Impact inside bermed area



Removal of surface impact



Surface removal





Surface removal at release point



Stockpiled soil



Test Trench



Appendix A Groundwater



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a (R=POD has been replaced, O=orphaned,

& no longer serves a C=the file is water right file.) Closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

	POD Sub-	Q	Q	O							Denth	Denth	Water
POD Number	Code basin County				Sec	Tws	Rng	;	Χ	Y	-	-	Column
RA 11245 POD1	CH	3	3	1 2	20	07S	31E	610806	3	3728777* 🎒	220	180	40
RA 11251 POD1	СН	1	2	4	10	07S	31E	615240)	3731841* 🎒	210	190	20
RA 11252 POD1	СН	2	4	2	10	07S	31E	615436	3	3732243* 🌍	210		
RA 11255 POD1	СН	2	4	4 (04	07S	31E	61380	5	3733024* 🎒	450	350	100
RA 11256 POD1	СН	2	4	4 (04	07S	31E	61380	5	3733024* 🎒	450	350	100
RA 11260 POD1	СН	1	2	3 2	26	07S	31E	616038	3	3727739 🌍	158	120	38

Average Depth to Water: 238 feet

Minimum Depth: 120 feet

Maximum Depth: 350 feet

Record Count: 6

PLSS Search:

Township: 07S Range: 31E