

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeys at 3:22 pm, May 11, 2016

Form C-141  
Revised August 8, 2011

accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company: OXY USA Inc.	Contact: Zack Czelada
Address: 8913 E. Hwy 158 Goldsmith, TX 79741	Telephone No.: (432) 614-7046
Facility Name: West Dollarhide Devonian Unit	Facility Type: Tank Battery
Surface Owner: State	Mineral Owner: State
API No.:	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	33	24S	38E	260		30		Lea

Latitude: 32.170858 Longitude: -103.069788

#### NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 6 bbl Oil 12 bbl Produced Water	Volume Recovered: 5 bbl Oil 10 bbl Produced Water
Source of Release: Suction Tank	Date and Hour of Occurrence: 5/9/2016 7:00 AM	Date and Hour of Discovery: 5/9/2016 9:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keys NMOCD	
By Whom? Zack Czelada	Date and Hour 5/9/2016 2:34 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A


Describe Cause of Problem and Remedial Action Taken.\*

The transmitters on the vessel were not operational, which subsequently resulted in the tank to overflow. OXY personnel have corrected the situation by repairing the transmitters.

Describe Area Affected and Cleanup Action Taken.\*

A surface area of approximately three thousand three hundred-thirty (3,330) square feet (sq. ft.) was affected by the release. The impacted area affected OXY assets only. Specifically, a vacuum truck was dispatched immediately to the location in an effort to recover free standing fluids. American Safety Services Inc. (ASSI) will use remediation activities that follow the NMOCD Recommended Guidelines For The Remediation of Leaks and Spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Czelada	Approved by Environmental Specialist: 	
Title: HES Ops Specialist	Approval Date: 05/11/2016	Expiration Date: 07/11/2016
E-mail Address: zack_czelada@oxy.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4273
Date: 5/10/2016	Phone: 432-614-7046	

\* Attach Additional Sheets If Necessary

nJXK1613255168  
pJXK1613255280