

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

JUL 24 2017

RECEIVED

Form C-141
Revised April 3, 2017

Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Impetro Operating, LLC	Contact	George M. Placke, PE – Operations Manager
Address	300 E. Sonterra Blvd., Suite 1220 San Antonio, TX 78258	Telephone No.	210-999-5400
Facility Name	Mexico P Federal #1	Facility Type	Production Well Site
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-22405

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	21	26S	35E	1980	N	1980	W	Lea

Latitude 32.0305786 Longitude -103.3745575 NAD83

NATURE OF RELEASE

Type of Release	Gas/Gas condensate to atmosphere	Volume of Release	N/A	Volume Recovered	Negligible
Source of Release	Well	Date and Hour of Occurrence	7/5/17 19:45	Date and Hour of Discovery	7/5/17 19:45
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	K. Vasenden with the BLM		
By Whom?	George Placke	Date and Hour	7/5/17 20:45		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

RECEIVED

By Olivia Yu at 8:54 am, Jul 27, 2017

Describe Cause of Problem and Remedial Action Taken.*



Lubricator pack off failed during wireline operations. Well was Shut-In after finishing out of the well with wireline.

Describe Area Affected and Cleanup Action Taken.*

Well site and road was covered with mist of condensate. Rain puddles with film of condensate were vacuumed clean. Area off well site that was affected by mist is starting to show browning of mesquite bush leaves. Will monitor to watch for recovery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: George M. Placke, PE	Approval Date: 7/27/2017	Expiration Date:
Title: Operations Manager	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: GPlacke@lilisenergy.com	Confirmatory laboratory analyses of discrete soil samples (0-6" bgs) from the impacted area off well site.	
Date: 7/14/17 Phone: 210-999-5400 ext. 36		

* Attach Additional Sheets If Necessary

1RP-4770

nOY1720837272

pOY1720837541