

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	EOG Resources Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	(432) 686-3667
Facility Name	Lomas Rojas 26 #703 spill area (1RP-4190)	Facility Type	6" Water Line Riser

Surface Owner	State	Mineral Owner	State	API No.
---------------	-------	---------------	-------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	26	25S	33E	770	North	1815	East	Lea

Latitude 32.10666 Longitude -103.5405

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	Approx. 300 bbls	Volume Recovered	120 BBLs
Source of Release	Poly line rupture	Date and Hour of Occurrence	2/18/16 approximately 12:00 am	Date and Hour of Discovery	2/18/16 approximately 12:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

APPROVED

By Olivia Yu at 12:08 pm, Feb 21, 2018



Describe Cause of Problem and Remedial Action Taken.*

A poly flow line was being moved when it contacted a 6-inch diameter poly water line riser. The riser broke at the tee. The on-site crew had a backhoe available. They were able to berm the release to keep it from spreading. Free fluids were removed with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

Impacted soil in the area of the release was excavated to an approximate depth of four to five feet below ground surface. Impacted soil was disposed of at an approved landfill. A 20 mil polyethylene liner was placed in the bottom of the excavation. The lined area was backfilled with clean soil, wheel compacted to grade, and revegetated with BLM seed mix.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				OIL CONSERVATION DIVISION	
Printed Name:	Zane Kurtz			Approved by Environmental Specialist: 	
Title:	Sr. Safety and Environmental Rep., EOG Resources, Inc.			Approval Date:	2/21/2018
E-mail Address:	zane_kurtz@eogresources.com			Expiration Date:	xx/xx/xxxx
Date:	2-20-2018			Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-425-2023				

* Attach Additional Sheets If Necessary

1RP-4190