

FAX NO. - 575-393-0720

HOBBS OCD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

APR 25 2018

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141  
Revised April 3, 2017

RECEIVED

## Release Notification and Corrective Action

Initial only

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Transwestern Pipeline Company	Contact	Larry Campbell
Address	6381 North Main Street	Telephone No	575 625 8022.
Facility Name	Pipeline Right of Way	Facility Type	Pipeline Right of Way
Surface Owner	BLM	Mineral Owner	Federal
		API No.	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	NE/4 SW/4 30	T25S	R34E					Lea

Latitude 32.099416 Longitude -103.511634 NAD83

## NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	35,029 mcf	Volume Recovered	0 mcf
Source of Release	Pipeline	Date and Hour of Occurrence	14:07 4/24/2018	Date and Hour of Discovery	14:07 4/24/2018
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCDC Hobbs District Office		
By Whom?	Larry Campbell	Date and Hour	11:51 4/25/2018		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\* N/A

RECEIVED



By Olivia Yu at 10:48 am, Apr 27, 2018

Describe Cause of Problem and Remedial Action Taken.\* A 3<sup>rd</sup> party contractor was trenching under and hit the Transwestern Pipeline causing the release of 35,029 mcf of pipeline quality natural gas. The valves upstream and downstream of the "hit" were closed and the natural gas vented to the atmosphere. The damaged section of pipeline was removed and a replacement section of pipeline was welded in place

The pipeline was re-pressurized and placed back into service.

Describe Area Affected and Cleanup Action Taken.\* No cleanup actions were taken as the natural gas was vented to the atmosphere. The construction area where the replacement pipe section was installed was graded and shaped to original contour of the land.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCDC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCDC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCDC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Larry Campbell	Approved by Environmental Specialist: 	
Title: Sr. Environmental Specialist	Approval Date: 4/27/2018	Expiration Date:
E-mail Address: larry.campbell@energytransfer.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/25/2018	Phone: 575 625 8022	

fOY1811739286

nOY1811739473

pOY1811739969

Photo documentation that natural gas emission from damaged pipeline did not have impact soil.

1RP-5031