
State of New Mexico Energy, Minerals and Natural Resources Department

Santa Fe, New Mexico 87503 Santa Fe, New Mexico 87503 Sonticate Dyne of Lease FED STATE FEE STATE FE	<u>DISTRICT I</u>	OIL CONSERVA	ATION DIVISIO	ON		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPAGASA TO DERLI, OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PREMIT" (PORM C-101 FOR SUCH PROPOSALS.) 1. Type of Well: (PORM C-101 FOR SUCH PROPOSALS.) 2. Name of Operator Occidental Permian, LTD. 3. Address of Operator Occidental Permian, LTD. 4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and L480 Feet From The WEST Line Section 30 Township IS-S Range SE NMFM LEA County 10. Evastion (Show whether DF, RKR, RT GR, etc.) 3.652° GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ABANDON CHANGE PLANS COMMENCE DRILLING OPPS. TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPPS. PULL OR ALTER CASING CHANGE PLANS CH	1625 N. French Drive , Hobbs, NM 88240	·		WELL API NO.	30-025- 05470 289 42	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPAGASALS TO DRILL OR TO DEEPIN OR PLUG BACK TO A DHIS FRIGHT RESISTAVOR. USE "APPLICATION FOR PERMIT" (NORTH HOBBS (G/SA) UNIT 1. Type of Well: (NORTH HOBBS (G/SA) UNIT 1. Type of Well: (NORTH HOBBS (G/SA) UNIT SECTION 30 2. Name of Operator Occidental Permian, LTD. 3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range				5. Indicate Type	of Lease	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SLOCK) PROPOSALS. 1. Type of Well: 2. Name of Operator Occidental Permian, L.TD. 3. Address of Operator Occidental Permian, L.TD. 3. Address of Operator Lini Letter K: 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3E NMFM LEA County 10. DELEVATION (Show whether DF, REB, RT GR, etc.) 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMAINS CASING TEST AND CEMENT JOB ABANDON CHANGE PLANS OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: TOTHER ABANDON SIDE ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: TOTHER ABANDON SIDE ABANDONMENT CASING TEST AND CEMENT JOB COMPLETE ABANDONMENT OTHER: OTHE				FED	STATE FEE X	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEFERENT RESERVOIR USE "APPLICATION FOR FERMIT" (FORM C-101 FOR SUCI) PROPOSALS.) 1. Type of Well: Qis Well Qas Well Other SECTION 30 2. Name of Operator Occidental Permian, LTD. S. Well No. 233 3. Address of Operator 1017 W STANOLIND RD. 9. Pool name or Wildcat HOBBS (G/SA) UNIT 4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3/F E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT OR, etc.) 10. Elevation (Show whether DF, RKB, RT OR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON CMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHE				6. State Oil & Ga	s Lease No.	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SLECH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator Occidental Permian, LTD. 3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter K: 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3 E NMPM LEA County 10. Elevation (Show whether DF, RRB, RT GR, etc.) 3.6527 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ABANDON ABANDON ABANDON CHANGE PLANS COMMENCE DRILLING OPIN. PULL OR ALTER CASING COMPLETED OF THE CASING COMPLETED O	SUNDRY NOTICE	S AND REPORTS ON W	ELLS			
1. Type of Well: Oil Well X Gas Well Other	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					
2. Name of Operator 2. Name of Operator 2. Name of Operator 1017 W STANOLIND RD. 3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S. Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3652° GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLJG AND ABANDON REPORT OF: REMEDIAL WORK X ALTERING CASING COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: COMMENCE DRILLING OPNS. PLUG & ABANDONMENT		1 FOR SUCH PROPOSALS.)		SECTION 30		
3. Address of Operator 1017 W STANOLIND RD. 9. Pool name or Wildcat HOBBS (G/SA) 4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, ac.) 36527 Cl. 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND CASING COMMENCE DRILLING OPNS. PLUG & ABANDON CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338* to 4240*. Sqc San Andres perfs 4148* 4240*. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson S.5" Uni VI packer @ 4114*. Circ cag with inhibited fluid. Rig Up Date: 03/09/2004 Rig Up Date: 03/09/2004 Rig Up Date: 03/09/2004 Rig Up Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WHAT AM A STAR STAR STAR STAR STAR STAR STAR ST) ——	Gas Well Other		SECTION 30		
4. Well Location Unit Letter K : 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3FE NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3652' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND REMEDIAL WORK X ALTERING CASING TEMPORABILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPNS PLUG & ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD (94338' to 4240'. SQc San Andres perfs 4148' 4-2440'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson S." Unit VI packer (94114'. Circ csg with inhibited fluid . Perforate Complete Comple	2. Name of Operator Occidental 1	Permian, LTD.		8. Well No.	233	
Unit Letter K: 2455 Feet From The SOUTH Line and 1480 Feet From The WEST Line Section 30 Township 18-S Range 3 E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3652' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG & ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB THER: 12. DESCRIBE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqc San Andres perfs 4148' -4240'. Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate wPlp plar w2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ seg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE County Title WO Completion Specialist DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert PHON 505-397-8206 (This space for State Use) APPROVED BY Lace 1.50 The NAME Robert Gilbert PHON 505-397-8206	3. Address of Operator 1017 W STAN	IOLIND RD.				
Section 30 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND RABANDON CHANGE PLANS COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338 to 4240°. Sqx San Antes perfs 4148° 4240°. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @4114°. Circ esg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the inforgation above is true and complete to the best of my knowledge and belief. SIGNATURE Work and the information above is true and complete to the best of my knowledge and belief. SIGNATURE DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY ATERIOR SPECIAL SP	4. Well Location			.		
10. Elevation (Show whether DF, RKB, RT GR, etc.)	Unit Letter K : 2455 F	Feet From The SOUTH	Line and 1480	Feet From The	WEST Line	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CASING FEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate wPPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5' Unit 17 packer @ 4114'. Circ esg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RPJPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Work of State Use) APPROVED BY Market Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY Market Gilbert PHONE NO. 505-397-8206		•		3 8 -E NMPM	LEA County	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqx San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ esg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert THE WO Completion Specialist PHONE NO. 505-397-8206 THE FIELD REPRESENTATIVE II/STAFF MANAGER DATE			RKB, RT GR, etc.)			
PERFORM REMEDIAL WORK PLUG AND REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqx San Andres perfs 4148' - 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate whyelp plar wi2" spacing using 3400g 15% NEFE HCL acid Sct Guiberson 5.5" Uni VI packer @ 4114'. Circ csg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	onto in a properties a second of the second					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: OTH	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqz San Andres perffs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ csg with inhibited fluid. Test csg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	1 1		REMEDIAL WORK	X	ALTERING CASING	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate wPPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ esg with inhibited fluid. Test esg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY HOME NO. 505-397-8206	TEMPORARILY ABANDON C	HANGE PLANS	COMMENCE DRILLI	NG OPNS.	PLUG & ABANDONMENT	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PFl pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ csg with inhibited fluid. Test csg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY HONE NO. 505-397-8206	PULL OR ALTER CASING		CASING TEST AND	CEMENT JOB		
Pull unjection equipment. Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148' 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ csg with inhibited fluid . Test csg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	OTHER:		OTHER:			
Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4184-89, and 4195-98 using 4" gun, 2 JSPF, 120 deg phasing. Re Perforate 4281-91 using 4" gun, 2 JSPF, 120 deg phasing. Stimulate w/PPI pkr w/2" spacing using 3400g 15% NEFE HCL acid Set Guiberson 5.5" Uni VI packer @ 4114'. Circ csg with inhibited fluid . Test csg for 30 min and chart for the NMOCD. RDPU. Clean Location. Rig Up Date: 03/09/2004 Rig Down Date: 03/18/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE						
Rig Down Date: 03/18/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 03/25/2004 TYPE OR PRINT NAME Robert Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY THE FIELD REPRESENTATIVE II/STAFF MANAGER DATE	Spot sand from PBTD @4338' to 4240'. Sqz San Andres perfs 4148'- 4240'. Perforate the following intervals 4175-80, 4 Re Perforate 4281-91 using 4" gun, 2 JSPF Stimulate w/PPI pkr w/2" spacing using 34 Set Guiberson 5.5" Uni VI packer @ 4114 Circ csg with inhibited fluid. Test csg for 30 min and chart for the NMO	F, 120 deg phasing. 400g 15% NEFE HCL acid V.	i" gun, 2 JSPF, 120 deş	g phasing.		
SIGNATURE						
TYPE OR PRINT NAME Robert Gilbert PHONE NO. 505-397-8206 (This space for State Use) APPROVED BY You W. W. THE FIELD REPRESENTATIVE II/STAFF MANAGER DATE	I hereby certify that the information above is true	e and complete to the best of my	knowledge and belief.			
(This space for State Use) APPROVED BY HOLD FIELD REPRESENTATIVE II/STAFF MANAGER DATE	SIGNATURE Kefut L	that	TITLE WO Con	pletion Specialist	DATE 03/25/2004	
APPROVED BY HOLL WILL THE FIELD REPRESENTATIVE II/STAFF MANAGER DATE				PHON	IE NO. 505-397-8206	
	APPROVED BY TOC FIELD REPRESENTATIVE II/STAFF MANAGER					
		- NAC INDE		D		



OXY NHU 30-233W

SERIAL # 11853 CALIBRATED Z/19/04 1000 # CHART Recorder

Billy Freis