Energy, Minerals and Natural Resources March Marc	Office	··· State o	I New IV	16XICO		rom (
Idea Precious Pr		Energy, Mineral	Energy, Minerals and Natural Resources					
### Section 17 Township 16s Range 32E NMPM Lea County County	1625 N. French Dr., Hobbs, NM 87240	0						
District III 1000 Rub Brazes Rd. Actes, IMS #7410 District IX 2040 South Pacheco Santa Fe, NM 87505 Suel Santa Fe, NM 87505 Su								
Santa Fe, NM 87505 Santa Fe, NM 87505 G. State Oil & Gas Lease No. K-867	911 Donni I 1194 Vitentia 1414 0.510				· -			
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS ON NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DEFERENT ROOM FOR PROPOSALS. 1. Type of Well: Oil Well	1000 Pio Responded Artes, NM 87410				STATE	X FEE 🗆	_	
SUNDRY NOTICES AND REPORTS ON WELLS ONNOT USE THIS FORM FOR PROPERS AND REPORTS ON WELLS ONNOT USE THIS FORM FOR PROPERS AS TO DEBETE OR PLUG BACK TO ADDIFFER ON REPORTS AND THE PROPOSALS. I. Type of Well: Oil Well Gas Well Other Water Injection Well Ness Queen Unit 2. Name of Operator Section 10 3. Address of Operator 9. Pool name or Wildcat PO Box 352 Midland, Texas 79702 9. Pool name or Wildcat Address of Operator 9. Pool name or Wildcat Well Location 10 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3. Address of Operator 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4. Well Location 11 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4. Well Location 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT CASING TEST AND CHANGE PLANS COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT CASING TEST AND CHANGE PLANS COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT CASING TEST AND CHANGE PLANS COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT COMMENCE DRILLING OPPNS PLUG AND ABANDONMENT CASING TEST AND CHANGE PLUG AND ABANDONMENT CASING	* * * * * * * * * * * * * * * * * * *				6. State Oil &	Gas Lease No.		
GO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPERN OF RUG BACK TO A DIFFERENT RESERVOYR. USE "APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROVISALS.) DiffERENT RESERVOYR. USE "APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROVISALS.) Cold Well Gas Well Cold Other Water Injection S. Well No. 10	2040 South Pacheco, Santa Fe, NM 873							
2. Name of Operator Xeric 011 & Cas Corporation 3. Address of Operator PO Box 352 Midland, Texas 79702 9. Pool name or Wildcat PO Box 352 Midland, Texas 79702 9. Pool name or Wildcat Well Cocation Unit Letter L 1650 feet from the South line and 990 feet from the West line Section 17 Township 16S Range 32E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSECULENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND AGANDON REMEDIAL WORK PLUG AND AGANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CEMENT JOB OTHER: CASING TEST AND CHANGE PLANS ABANDON ABANDONMENT OF STARTING ABANDONMENT COMPLETION OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NNOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary \$1.5 fold. Abandonment Expires THEE SR. Production Analyst DATE \$1/18/01 Type or print name Glends Hunt TITLE SR. Production Analyst DATE \$1/18/01 Type or print name Glends Hunt TITLE SR. Production Analyst DATE \$1/18/01 Type or print name Glends Hunt TITLE DATE. PAPPROVED BY Appended the print TITLE DATE. PAPPROVED BY Appended the print TITLE SR. Production Analyst DATE \$1/18/01 TITLE DATE.	(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "AP PROPOSALS.) 1. Type of Well:	OPOSALS TO DRILL OR TO DEI PLICATION FOR PERMIT" (FOR	EPEN OR PI RM C-101) I	LUG BACK TO A FOR SUCH		-	lame:	
Xeric Oil & Gas Corporation 10 10 10 10 10 10 10 1								
## PO Box 352 Midland, Texas 79702 Mesa Quern Assoc. 4. Well Location Unit Letter L 1650 feet from the South line and 990 feet from the West line		1 1						
Unit Letter L 1650 feet from the South line and 990 feet from the West line Section 17 Township 168 Range 328 NMPM Lea County		9. Pool name or Wildcat						
Unit Letter L 1650 feet from the South line and 990 feet from the West line Section 17 Township 16S Range 32E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4355 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TSTAND CASING T		and, Texas 79702			Mesa Queer	n Assoc.		
Section 17 Township 16S Range 32E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4355' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLUG AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING DEMONSTRATED COMPLETION TEMPORARILY ABANDON CHANGE PLANS COMPLETION CASING TEST AND CHANGE DRILLING OPNS. PLUG AND ABANDONMENT DOWN TO THERE. OTHER: OTHER: OTHER Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500% for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary \$\int 25\int 60\int 80\int 1000 \text{ Truck}. SIGNATURE Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Type or print name Glends Hunt Title SR. Production Analyst PATE \$\int 1840 TITLE SR. Production Analyst PATE \$\int 1840 \text{ Title SR. Production Analyst PATE \$\int 1840 \text{ Title SR. Production Analyst PATE \$\int 1840 \text{ Title SR. Production PNO. PATE \$\int 1840 \text{ TITLE SR. PRODUCTION PATE \$\int 1840 \text{ PATE \$\int 1840 \text{ TITLE SR. PRODUCTION PATE \$\int 1840 \text{ TITLE SR. PATE \$\int 1840 \text{ PATE \$\int 1840 \	4. Well Location				•		1	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4355' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/06. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	Unit Letter La	: 1650 feet from the	South	line and 99	90 feet fro	m the <u>West</u>	_line	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4355' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/06. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE							-	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Re-instate TA status OTHER: OTHER: Re-instate TA status OTHER: Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/olc Abandonment Expires	Section 17					County		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER Re-instate TA status OTHER Reported operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/dle. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE			vhether D	R, RKB, RT, GR, etc.,)			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER Re-instate TA status OTHER Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMCCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. circulate casing with treated water. 4. Pressure test to 500% for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/04c Abandonment Expires This Approval of Temporary 5/25/04c Approval of Temporary 5/25/04c Approval of Temporary 5/25/04c Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE			11		2.1	- ·		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT CASING TEST AND CEMENT JOB OTHER: CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Re-instate TA status OTHER:								
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/ole Abandonment Expires			_					
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Re-instate TA status 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/ole Abandonment Empires This Approval of Temporary 5/25/ole	PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASIN	iG ∟	
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: Re-instate TA status OTHER	TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🔲			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/ole Abandonment Expires I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE TITLE SR. Production Analyst DATE 5/18/01 Type or print name Glenda Hunt FIELD REPRESENTATIVE II MAY 2 5 2006 APPPROVED BY APPPROVED BY HALL ALL ALL ALL ALL ALL ALL ALL ALL ALL	PULL OR ALTER CASING [ADANDONNEN		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/ole Abandonment Expires Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Type or print name Glenda Hunt TITLE SR. Production Analyst PATE 5/18/01 Type or State use) FIELD REPRESENTATIVE II MAY 2 5 2006 APPPROVED BY APPPROVED BY Hary Williams TITLE DATE MAY 2 5 2006	OTHER:			OTHER: Re-ins	state TA stat	tus		
SIGNATURE SIGNAT	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Contact NMOCD to witness pressure test (give 24 hr advance notice). 2. Nipple up to injection head with kill truck. 3. Circulate casing with treated water. 4. Pressure test to 500# for 30 minutes recording results on chart. 5. Nipple down injection head from kill truck. 6. Re-instate Temporarily Abandon Status. This Approval of Temporary 5/25/ole Abandonment Expires							
Type or print name Glenda Hunt Telephone No. (This space for State use) APPPROVED BY Lary W. Winks TITLE DATE OATE	I hereby certify that the information	on above is true and complet	e to the b	est of my knowledge	and belief.			
APPPROVED BY Lary W. Winks TITLE PARESENTATIVE II MAY 25 2001	SIGNATURE BLE	a yout	ritle <u>s</u> i	R. Production	Analyst	_DATE_5/18/01		
APPPROVED BY Lary W. Winks TITLE PATE DATE MAY 25 2001	Type or print name C1 4	a. Uumt			915-6	83-3650		
APPPROVED BY Hayw. Winks TITLE DATE DATE		a nunt						
ATTROVED BY TO STOCK OF THE BOATE	(1 nis space for State use)	1	FIELD	REPRESENT	ATIVE LI	MAY 9 E -		
		W. Wink T	TTLE		.,	_DATE	101	

