Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103 Revised May 08, 2003	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL API NO. 30-025-05738	
District II 1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE X FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				B-1330-1	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				North Monument G/SA Unit Blk. 11	
PROPOSALS.) 1. Type of Well:				8. Well Number	
Oil Well Gas Well Other Injection Well				001	
Name of Operator Amerada Hess Corporation				9. OGRID Number 000495	
3. Address of Operator P.O. Box 840 Seminole, TX 79360				10. Pool name or Wildcat Eunice Monument G/SA	
4. Well Location				Editice Mont	intent G/SA
Unit Letter A: 660 feet from the North line and 660 feet from the East line					
Section 29 Township 19S Range 37E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF IN		dicate N		Report or Othe SEQUENT RI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND 🗆	, <u></u> ,
OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
4/7/2004 thru 4/11/2004					25262728
MIRU Tyler Well Svc. Installed 6" 900 BOP. TOH w/tbg and pkr. Found cement loose inside tbg? Primary					
failure was grooved Breech-Loc Mandrel. TIH w/cement lined tbg, pkr and Breech-Loc. Removed 6" 900 BOB & Solution & Solut					
Chart attached.					
				15/2	Relation 800
					3/151314
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
/ A L 10 W MADE 2					
SIGNATURE (MODE)	7			ulatory	DATE_4/15/2004
Type or print name Carol J. Moore) cm	oore@he	SS.COM	Telej	phone No. (432)758-6738
(This space for State use) APPPROVED BY Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STARF AND ASSER 2004					
APPPROVED BY Conditions of approval, if any:	urwak 1	TITLE		····· [II/\$]	ARTAN ASER 2004

