Office Office	State of			Form C-103
District I	Energy, Minerals	and Nati	ural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-05493
301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410		STATE FEE		
District IV	Santa Fe	e, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOTIC	TES AND DEDODTS OF	NIWELLS	<u>c</u>	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name of Offit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Hobbs	
PROPOSALS.) 1. Type of Well:				8. Well Number
	Other SWD Well			P-25
2. Name of Operator				9. OGRID Number
2. Name of Operator Rice Operating	g Co			9. OGRID Number
3. Address of Operator	g Cu.			9. Pool name or Wildcat
122 W. Taylo	or			Hobbs
4. Well Location				
Unit LetterP:_	_330'feet from the	SOL	<u>JTH</u> line and	330'feet from theEASTline
Section 25			Range 3	
	11. Elevation (Show wi)
Pit or Below-grade Tank Application (For		T/Flange		4)
}				
1				Distance from nearest fresh water well
Distance from nearest surface water			SectTwp	Rng ;
feet from theline and	feet from the	line		
				2576272
				10 K 20 20 21 < 8 2
12 Check A	nnronriate Box to Ir	ndicate N	Nature of Notice	Report or Other Data
12. Check A	appropriate Box to Ir	ndicate l	Nature of Notice,	Report or Other Data
			1	Report or Other Data SEQUENT REPORT OF: SEQUENT REPORT OF:
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK			REMEDIAL WORK	CO CAPTERING CASING
PERFORM REMEDIAL WORK			1	CO CAPTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK	LING OPHIS RING MAD CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE		REMEDIAL WORK COMMENCE DRIL CASING TEST AN	LING OPNS ABANDOWMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK	LING OPNS ABANDOWMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE		REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB	LING OPNIS RIJUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION		REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Te	LING OPINS PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl	□ □ □ □ v state all	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Te	LING OPNS. PLING OND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearl rk). SEE RULE 1103.	y state all	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At	LING OPNS. PLUC AND ABANDONMENT: Demp. Abandon Id give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Pulled tub	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clearl rk). SEE RULE 1103. I	y state all For Multi	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Te pertinent details, an ple Completions: At	LING OPINS RILIG AND ABANDONMENT ABANDON
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clearl rk). SEE RULE 1103. I	y state all For Multi	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Te pertinent details, an ple Completions: At	LING OPNS. PLUC AND ABANDONMENT: Demp. Abandon Id give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. Pulled tub	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION letted operations. (Clearl rk). SEE RULE 1103. I	y state all For Multi	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Te pertinent details, an ple Completions: At	LING OPNS. PLUC AND ABANDONMENT: Demp. Abandon Id give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wood or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed,	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It sing, left packer in hole a witnessed by Gary Wink	y state all For Multi at 4409'. S	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D.	ALING OPINS RILIG AND ABANICONMENT ABANICONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information as	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It sing, left packer in hole a witnessed by Gary Wink above is true and comple	y state all For Multi at 4409'. State to the letter to the	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left Left well TA'D.	ABANDONMENT D ABANDONMENT ABANDONMENT D D D D D D D D D D D D D
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information agrade tank has been/will be constituted or the constit	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It sing, left packer in hole a witnessed by Gary Wink above is true and comple	y state all For Multi at 4409'. State to the leguidelines	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left Left well TA'D. best of my knowledg , a general permit	ABANDONMENT Bemp. Abandon d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion oad hole with packer fluid and run MIT ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information as	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It sing, left packer in hole a witnessed by Gary Wink above is true and comple	y state all For Multi at 4409'. State to the leguidelines	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left Left well TA'D.	ABANDONMENT Bemp. Abandon d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion oad hole with packer fluid and run MIT ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, or grade tank has been/will be fonsty fixed or SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD	y state all For Multi at 4409'. S 5-19-04 ete to the leading of the second of the seco	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg , a general permit	ELING OPINS. PILIC AND ABANDONMENT. ABANDONME
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information agrade tank has been/will be constituted or the constit	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD	y state all For Multi at 4409'. State to the leguidelines	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg , a general permit	ABANDONMENT Bemp. Abandon d give pertinent dates, including estimated date ttach wellbore diagram of proposed completion oad hole with packer fluid and run MIT ge and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information a grade tank has been/will be constituted or SIGNATURE Type or print name Scott Curtis	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD	y state all For Multi at 4409'. S 5-19-04 ete to the leading of the second of the seco	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg , a general permit	ELING OPINS. PILIC AND ABANDONMENT. ABANDONME
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information agrade tank has been/will be constructed or SIGNATURE Type or print name Scott Curtis (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearlerk). SEE RULE 1103. It ing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD E-mail	y state all For Multi at 4409'. S 5-19-04 ete to the leading of the second of the seco	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tell pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg , a general permit	ELING OPINS. PILIC AND ABANDONMENT. ABANDONME
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Scott Curtis (This space for State use) ORIGINA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD E-mail	y state all For Multi at 4409'. S 5-19-04 ete to the leguidelines TITLE_0 1 address:	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tel pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg \(\square\), a general permit \(\square\) OperatioOn Manager Telepl	ELING OP NS. RILIG AND ABANDONMENT. ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Scott Curtis (This space for State use) ORIGINA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD E-mail	y state all For Multi at 4409'. S 5-19-04 ete to the leguidelines TITLE_0 1 address:	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tel pertinent details, an ple Completions: At Set CIBP at 4170'. Left well TA'D. best of my knowledg \(\square\), a general permit \(\square\) OperatioOn Manager Telepl	ELING OPINS. PILIC AND ABANDONMENT. ABANDONME
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information agrade tank has been/will be constructed or SIGNATURE Type or print name Scott Curtis (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD E-mail	y state all For Multi at 4409'. S 5-19-04 ete to the leguidelines TITLE_0 1 address:	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tel pertinent details, an ple Completions: Ad Set CIBP at 4170'. Left well TA'D. best of my knowledg a general permit	ELING OPNS. PLUG AND ABANDONMENT. ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Pulled tub To 500 Psi. for 30 min. Test passed, I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name Scott Curtis (This space for State use) ORIGINA	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION leted operations. (Clearl rk). SEE RULE 1103. It loing, left packer in hole a witnessed by Gary Wink above is true and completelesed according to NMOCD E-mail	y state all For Multi at 4409'. S 5-19-04 ete to the leguidelines TITLE_0 1 address:	REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Tel pertinent details, an ple Completions: Ad Set CIBP at 4170'. Left well TA'D. best of my knowledg a general permit	ELING OP NS. RILIG AND ABANDONMENT. ABANDONMENT

