New Mexico Oti Conservation Division, Endetci I

1625 N. French Drive Hobbs. NM 80240

Form 3160-5 (June 1990)

12

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135

		Expires:	March	31, 199	3
5.	Lease	Designat	ion and	Scrial	No.
	00				

SUNDRY NOTICES	AND	REPORTS	ON	WELLS
----------------	-----	---------	----	-------

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

	03230	<i>J</i>			
6.	If Indian,	Allottee	or Tribe	Name	

Use "APPLICATION FOR PERMIT—" for such proposals		
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Well  Oil Gas Well Well Other	8. Well Name and No. E.J. Wells #2	
2. Name of Operator Tenison Oil Co. 3. Address and Telephone No.	9. API Well No.  30-025-09743	
401 Cypress Street, Ste. 500, Abilene, TX 79601 (325)672-7281  4 Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area Jalmat	
990' FNL & 990' FEL Sec. 12, T25S, R36E	11. County or Parish, State  Lea County, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA	

TVS5 OF OUR WOODA	TYPE (	OF ACTION	
TYPE OF SUBMISSION	THE OF ACTION		
Notice of Intent	X Abandonment	Change of Plans	
	Recompletion	New Construction	

Notice of Intent	Abandonment	Li Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
•	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

\*Note: Will use above ground steel pit to circulate into.

- Spot 35 sx cmt. 3032 2750', WOC & tag.
- Circulate hole w/ 10# MLF.
- 3. Perforate 5-1/2" csg. @ 615', sqz. w/ 45 sx 615 515', WOC & tag.
- Perforate 5-1/2" csg. @ 50', sqz. w/ 25 sx 50' to surface inside & outside 5-1/2" csg. WOC & tag.
- RDMO. Cut off wellhead, install dry hole marker, & clean location.

14. I hereby certify 7-27-04 Agent (This space for Federal or State office use) JUL 29 2004 (CRIG SGD) DAVID R. GLASS Approved by (CRIC) S Conditions of approval, if any:

willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements