Submit 3 Copies To Appropriate District	State of N	lew Mexico	Form C-103
Office District I	Energy, Minerals as	nd Natural Resource	ces March 4, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II	OIL CONSERVA	ATION DIVISIO	N 30-025- 24844 24944
1301 W. Grand Ave., Artesia, NM 88210 District III		St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Pe,	14141 67303	6. State Oil & Gas Lease No. 031645
	ES AND REPORTS ON	WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEP	EN OR PLUG BACK TO	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	ATION FOR PERMIT" (FORM	C-101) FOR SUCH	AZTEC STATE
1. Type of Well:			8. Well Number —14
Oil Well X Gas Well C	Other		
2. Name of Operator	·		9. OGRID Number
ENDEAVOR ENERGY RESOURCE	EC ID		9. OGRID Number
3. Address of Operator 110 N. MA			10. Pool name or Wildcat CORBIN ABO
MIDLAND, TEXAS 79701	KILINI LLD, SOITE 200		10. Foot hame of Wildcat CORDIN ADO
4. Well Location			
Unit LetterC:	660feet from	theN line a	nd2030 _ feet from theW line
		4	
Section 36	Township		32E NMPM LEA County
	11. Elevation (Show whe	ether DR, RKB, RT, C	iR, etc.)
Pit or Below-grade Tank Application (For	nit on halom guada tank alagan		- Advanta D
1			
1			dwater83 Distance from nearest fresh water well >1000_
Distance from nearest surface water_>1	000 Below-grade Tank Loc	ation ULSect_	Twp_Rng_5';
feet from theline and	feet from the	line	Twp Rng ;
1			1 HHE 1000 1
	The state of the s	·	
12. Chools As	nneoneista Day ta Ind	inata Natara aCN	Press F COUNTY CO
12. Check A	ppropriate Box to Ind	licate Nature of N	otice, Report or Other Data
HOTICE OF IN	ENTION TO.		otice, Report or Other Data ED SUBSEQUENT REPORT OF:
HOTICE OF IN	ppropriate Box to Ind FENTION TO: PLUG AND ABANDON	icate Nature of N	otice, Report or Other Data ED SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	ENTION TO.	REMEDIA	otice, Report or Other Para ED SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIA COMMEN	otice, Report or Other Data ED SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIA	otice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND X ABANDONMENT EST AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE	☐ REMEDIA ☐ COMMEN ☐ CASING TO CEMENT.	otice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND X ABANDONMENT EST AND
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	□ REMEDIA □ COMMEN □ CASING T CEMENT. □ OTHER:	otice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. ABANDONMENT EST AND JOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly	REMEDIA COMMEN CASING T CEMENT OTHER:	otice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. ABANDONMENT EST AND JOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. Fo	REMEDIA COMMEN CASING T CEMENT OTHER: state all pertinent det r Multiple Completic	otice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB ails, and give pertinent dates, including estimated dates ons: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 – SPOT 75 SX CMT AT 620	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. Fo	REMEDIA COMMEN CASING T CEMENT OTHER: state all pertinent det Multiple Completic	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK ALTERING CASING ABANDONMENT EST AND JOB Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completions. NG AT 4800': SPOT 75 SX AT 4850: TOC 4685'
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 06/21/04 – SPOT 75 SX CMT AT 62006/24/04 – SPOT 75 SX CMT AT 43:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0	REMEDIA COMMEN CASING TO CEMENT OTHER: state all pertinent det or Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. ABANDONMENT EST AND JOB JOB Ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025': TOC 2713'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 62/06/24/04 - SPOT 75 SX CMT AT 43:06/25/04 - SPOT 75 SX CMT AT 24/	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly: k). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0	REMEDIA COMMEN CASING TO CEMENT. OTHER: State all pertinent det or Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. ABANDONMENT EST AND JOB Ails, and give pertinent dates, including estimated data ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620 06/24/04 - SPOT 75 SX CMT AT 43: 06/25/04 - SPOT 75 SX CMT AT 240 06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly state) k). SEE RULE 1103. For 100'; TOC 5780'. 06/23/050'; TOC 4004'. 06/24/060'; TOC 2210'. 06/25/010 ANNULUS TO 8 5/8"	COMMEN CASING TO CEMENT OTHER: State all pertinent det or Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. ABANDONMENT EST AND JOB Ails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620 06/24/04 - SPOT 75 SX CMT AT 430 06/25/04 - SPOT 75 SX CMT AT 240 06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8"	REMEDIA COMMEN CASING TO CEMENT OTHER: state all pertinent deter Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my known	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB Alis, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620 06/24/04 - SPOT 75 SX CMT AT 430 06/25/04 - SPOT 75 SX CMT AT 240 06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly sk). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8"	REMEDIA COMMEN CASING TO CEMENT OTHER: state all pertinent deter Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my known	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. ABANDONMENT EST AND JOB Ails, and give pertinent dates, including estimated data ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 62006/24/04 - SPOT 75 SX CMT AT 43006/25/04 - SPOT 75 SX CMT AT 2406/25/04 - SQUEEZE 230 SX CMT Interest the information alignment of the start	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. For 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8" bove is true and complete losed according to NMOCD gr	REMEDIA COMMEN CASING T CEMENT OTHER: State all pertinent det or Multiple Completic 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my kn sidelines □, a general per	SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion. NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE. owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620 06/24/04 - SPOT 75 SX CMT AT 430 06/25/04 - SPOT 75 SX CMT AT 240 06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. For 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8" bove is true and complete losed according to NMOCD gr	REMEDIA COMMEN CASING TO CEMENT OTHER: state all pertinent deter Multiple Completion 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my known	Totice, Report or Other Data SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB Alis, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620/06/24/04 - SPOT 75 SX CMT AT 240/06/25/04 - SPOT 75 SX CMT AT 240/06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8" bove is true and complete losed according to NMOCD gr	REMEDIA COMMEN CASING T CEMENT OTHER: state all pertinent det or Multiple Completic 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my knowledge ageneral per stidelines □, a general per ITLE AGENT	SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion. NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE. owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 620/06/24/04 - SPOT 75 SX CMT AT 240/06/25/04 - SPOT 75 SX CMT AT 240/06/25/04 - SQUEEZE 230 SX CMT I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8" bove is true and complete losed according to NMOCD gr	REMEDIA COMMEN CASING T CEMENT OTHER: state all pertinent det or Multiple Completic 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my knowledge ageneral per stidelines □, a general per ITLE AGENT	SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion. NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE. owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . DATE JUNE 28, 2004
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complet of starting any proposed work or recompletion. 06/21/04 - SPOT 75 SX CMT AT 62/06/24/04 - SPOT 75 SX CMT AT 43/06/25/04 - SPOT 75 SX CMT AT 24/06/25/04 - SQUEEZE 230 SX CMT I hereby certify that the information algrade tank has been/will be constructed or SIGNATURE Type or print name HOWARD BO	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Eted operations. (Clearly: k). SEE RULE 1103. Fo 00'; TOC 5780'. 06/23/0 50'; TOC 4004'. 06/24/0 60'; TOC 2210'. 06/25/0 IN ANNULUS TO 8 5/8" bove is true and complete lessed according to NMOCD gr	REMEDIA COMMEN CASING T CEMENT OTHER: state all pertinent det Multiple Completic 4 - CUT 5 ½" CASI 4 - SPOT 100 SX CI 4 - SPOT 75 SX AT x 12 ¾"; CIRCULA to the best of my knowled times □, a general partitle AGENT SS: CGIBSON@TET	SUBSEQUENT REPORT OF: L WORK CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND JOB ails, and give pertinent dates, including estimated dates. Attach wellbore diagram of proposed completion. NG AT 4800'; SPOT 75 SX AT 4850; TOC 4685'. MT AT 3025'; TOC 2713'. 1370' TO 1120'. TE TO SURFACE. owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan . DATE JUNE 28, 2004