Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Reso	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-36688
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVIS	ION 5 Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Angus 7 State
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 001
2. Name of Operator Chesapeake Operating, Inc.	9. OGRID Number 147179
3. Address of Operator P. O. Box 11050	10. Pool name or Wildcat
Midland, TX 79702-8050 4. Well Location	San Simon;Strawn, South
Unit Letter H: 1980 feet from the North li	ne and 660 feet from the East line
Section 7 Township 22S Range 35	
11. Elevation (Show whether DR, RKB, R 3609	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 mg Pit Location: ULH Sect 7 Twp 22S Rng 35E Pit type Drilling Depth to Gr	st be attached)
Distance from nearest surface water 1000+ Below-grade Tank Location UL Sec	/ (3)
feet from theline andfeet from theline	WE WED
12. Check Appropriate Box to Indicate Nature o	f Notice, Report or Other Data
17. Uneck Appropriate box to indicate Natife o	
	SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF: DIAL WORK
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME	DIAL WORK ALTERING CASING DENCE DRILLING OPNS. PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASIN	DIAL WORK ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASIN CEME	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND NT JOB R: Perf/Acid Metails, and give pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion.	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid Actails, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid String CASING DATERING CASING CASING DATERING CASING CAS
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize w/1500 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total)	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT G: Perf/Acid X details, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize w/1500 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sat 1 hereby certify that the information above is true and complete to the best of my	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid X details, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or below-
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REME TEMPORARILY ABANDON □ CHANGE PLANS □ COMM PULL OR ALTER CASING □ MULTIPLE □ CASINC CEME OTHER: □ OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410′ w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize WC w/2000 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sa 1 hereby certify that the information above is true and complete to the best of my grade tank has been/will be constructed or closed according to NMOCD guidelines \(\overline{\text{N}} \), a gener	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid X details, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan .
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REME TEMPORARILY ABANDON CHANGE PLANS COMM PULL OR ALTER CASING MULTIPLE CASING CEME OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize w/1500 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sat 1 hereby certify that the information above is true and complete to the best of my	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid X details, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan .
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REME TEMPORARILY ABANDON □ CHANGE PLANS □ COMM PULL OR ALTER CASING □ MULTIPLE □ CASIN CEME OTHER: □ OTHEI 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize w/1500 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sa I hereby certify that the information above is true and complete to the best of my grade tank has been/will be constructed or closed according to NMOCD guidelines ☑, a gener	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid Strain details, and give pertinent dates, including estimated date details. Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan .
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REME TEMPORARILY ABANDON □ CHANGE PLANS □ COMM PULL OR ALTER CASING □ MULTIPLE □ CASIN CEME OTHER: □ OTHEI 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410' w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize w/1500 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sa I hereby certify that the information above is true and complete to the best of my grade tank has been/will be constructed or closed according to NMOCD guidelines ☑, a gener	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid Metails, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan . Analyst DATE 08/27/2004
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REME TEMPORARILY ABANDON □ CHANGE PLANS □ COMM PULL OR ALTER CASING □ MULTIPLE □ CASIN CEME OTHER: □ OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Comp or recompletion. 8-17-04 Spot 500 gals 15% neFe acid @ 11,410′ w/64 bbls 2% KCL. Perf. @ 4 spf. 8-18-04 Acidize WC w/2000 gals 15% NeFe + 65 BS 8-20-04 Acidize WC w/2000 gals 25% neFe, 3000 gals 20% Ultragel, 1,000 gals 20% slick NeFe, flush w/72 bbls 2% KCL (10,000 gals total) 8-26-04 Frac34,000 gals Spectrafrac G-3000 w/47,000# Versaprop 18/40 sa 1 hereby certify that the information above is true and complete to the best of my grade tank has been/will be constructed or closed according to NMOCD guidelines □, a gener SIGNATURE □ TITLE Regulatory Type or print name Brenda Coffman E-mail address: bo	ENCE DRILLING OPNS. PLUG AND ABANDONMENT G TEST AND ABANDONMENT R: Perf/Acid Metails, and give pertinent dates, including estimated date letions: Attach wellbore diagram of proposed completion WC 11,336 - 11,341; 11,344' - 11,348', 11,408' - 11,410 gelled 20% neFe, 4,000 gals 20% Ultragel and 500 gals and. knowledge and belief. I further certify that any pit or belowal permit or an (attached) alternative OCD-approved plan . Analyst DATE 08/27/2004