Office Energy, Minerals and Natural I	0		Form C-103
District	Kesources		May 27, 2004
1625 N. French Dr., Hobbs, NM 87240 District II		WELL API NO. 30-025-09260	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
District IV)3		
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil &	Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: STATE A A/C 1	
1. Type of Well: Oil Well Gas Well Other		8. Well Number 87	
2. Name of Operator		9. OGRID Number	
MISSION RESOURCES CORPORATION		148381	
3. Address of Operator 1331 LAMAR. SUITE 1455 HOUSTON, TEXAS 77010-3039		10. Pool name or Wildcat	
1331 LAMAR. SUITE 1455 HOUSTON. TEXAS 77010-3039 JALMAT: TAN. YATES. 7-RVRS (GAS) 79240 4. Well Location			
Unit Letter G : 1980 feet from the NORTH	line and	1980 fee	t from the <u>EAST</u> line
Section 4 Township 23S Ran		NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application or Closure			
Pit type <u>Steel</u> Depth to Groundwater <u>220'</u> Distance from nearest fresh water well <u>1000'+</u> Distance from nearest surface water <u>1000'+</u>			
Pit Liner Thickness:n/a mil Below-Grade Tank: Volumebbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON RE	MEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	DMMENCE DRILLI	NG OPNS. 🔲	PLUG AND ABANDONMENT
			, in the state of
	ASING TEST AND EMENT JOB		
COMPLETION			
COMPLETION	EMENT JOB THER: ent details, and give	pertinent dates wellbore diagra	am of proposed completion
OTHER: OTHER:	EMENT JOB THER: ent details, and give empletions: Attach	wellbore diagra	am of proposed completion
OTHER: OTHER:	EMENT JOB THER: ent details, and give empletions: Attach	wellbore diagra	am of proposed completion
COMPLETION CE OTHER: OT 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1. Set CIBP above packer @ 3034' with 25 sx. cmt. on to 2. Load hole with gelled 10# brine 3. Place 100' plug from 1400'-1300'.	EMENT JOB THER: ent details, and give empletions: Attach	wellbore diagra	am of proposed completion
COMPLETION CE OTHER: OT 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1. Set CIBP above packer @ 3034' with 25 sx. cmt. on to 2. Load hole with gelled 10# brine 3. Place 100' plug from 1400'-1300'. 4. Perforate 7" casing @ 295'.	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if	wellbore diagra	am of proposed completion
OTHER: OT OTHER: OT OT OTHER: OT OT OT OTHER: OT OTHER: OT OT OTHER: OT OTHER: OTHER:	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if	wellbore diagradumped bailed	am of proposed completion
OTHER: OT OTHER: OT OT OTHER: OT OT OTHER: OT OTHER: OT OTHER: OT	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if Generat. MUST BE DR TO THE BEC	wellbore diagradumped bailed NOTIFIED 24 DINNING OF	am of proposed completion
OTHER: OT OTHER: OT OT OTHER: OT OT OTHER: OT OTHER: OT OTHER: OT	EMENT JOB THER: ent details, and give impletions: Attach op - or 35' if Cement. MUST BE DR TO THE BECOPERATIONS FQ	wellbore diagradumped bailed NOTIFIED 24 DINNING OF	am of proposed completion
OTHER: OT OTHER: OT OTHER: OT OTHER: OT OTHER: OT OTHER: OT OTHER: OTHER:	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if Comment. MUST BE DR TO THE BECOPERATIONS FOR OVED. t of my knowledge	wellbore diagradumped bailed NOTIFIED 24 HNNING OF	am of proposed completion 1200 120
OTHER: OT OTHER: OT OTHER: OT OT OTHER: OT OTHER: OT OTHER: OTHER:	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if Generations BE OR TO THE BECOPERATIONS FOR OVED. t of my knowledge], a general permit [wellbore diagradumped bailed NOTIFIED 24 HNNING OF	am of proposed completion 1200 120
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1. Set CIBP above packer @ 3034' with 25 sx. cmt. on to 2. Load hole with gelled 10# brine 3. Place 100' plug from 1400'-1300'. 4. Perforate 7" casing @ 295'. 5. Squeeze perfs @ 295' & circ. to surface WALLSTOSXALLE Cut off wellhead - Weld on P&A Marker HOURS PRICE TO BE APPRICE TO BE APPRICE TO BE APPRICED	EMENT JOB THER: ent details, and give impletions: Attach op - or 35' if General MUST BE OR TO THE BEG OPERATIONS FOR OVED. t of my knowledge], a general permit [Regulatory	wellbore diagradumped bailed NOTIFIED 24 HNNING OF THE G-193 and belief. I full or an (attached Coordinator ancy.gatti@m	rther certify that any pit or below- alternative OCD-approved plan DATE 08/31/04
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1. Set CIBP above packer @ 3034' with 25 sx. cmt. on to 2. Load hole with gelled 10# brine 3. Place 100' plug from 1400'-1300'. 4. Perforate 7" casing @ 295'. 5. Squeeze perfs @ 295' & circ. to surface WA61500sxA46. 6. Cut off wellhead - Weld on P&A Marker HOURS PRICE. 7. Clean off location OCD Inspection PLUGGING CONTROL TO BE APPROVED IN THE CONTROL OF THE CONTROL	EMENT JOB THER: ent details, and give empletions: Attach op - or 35' if General MUST BE DR TO THE BEC DPERATIONS FOR OVED. t of my knowledge], a general permit [Regulatory address: n	wellbore diagradumped bailed NOTIFIED 24 HNNING OF THE 6-193 and belief. I full or an (attached coordinator ancy. gatti@m	rther certify that any pit or below- alternative OCD-approved plan DATE 08/31/04 rcorp.com Telephone No. 713-495-3128
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Co or recompletion. 1. Set CIBP above packer @ 3034' with 25 sx. cmt. on to 2. Load hole with gelled 10# brine 3. Place 100' plug from 1400'-1300'. 4. Perforate 7" casing @ 295'. 5. Squeeze perfs @ 295' & circ. to surface WA61500sxA46. 6. Cut off wellhead - Weld on P&A Marker HOURS PRICE. 7. Clean off location OCD Inspection PLUGGING CONTROL TO BE APPROVED IN THE CONTROL OF THE CONTROL	EMENT JOB THER: ent details, and give impletions: Attach op - or 35' if Cement. MUST BE OPERATIONS FOR OVED. t of my knowledge], a general permit [Regulatory address: n	wellbore diagradumped bailed NOTIFIED 24 HNNING OF THE 6-193 and belief. I full or an (attached coordinator ancy. gatti@m	rther certify that any pit or below- alternative OCD-approved plan DATE 08/31/04 rcorp.com Telephone No. 713-495-3128

