SEP 0 1 2004

State of New Mexico Energy, Minerals and Natural Resources Department

16.25 N. French Drive, Hobbs, NM 88240 Santa Fe, New Mexico 87503 Santa Fe, New Mexico 87503 Sundry NOTICES AND REPORTS ON WELLS (IX) NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PREMIT" (ITORM C-101 FOR SUCH PROPOSALS) 1. Type of Well Case Well Other T&A'd SECTION 31 Section 31 Township 18.5 Range 38.E NMPM LEA County 10.1 Elevation (Show whether DF, RER, RT GR, etc.) 3.653° Cd. 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: REMEDIAL WORK ALTERNOCASING REMEDIAL WORK ALTERNOCASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: CASING TEST AND CEMENT JOB OTHER: A THERNOCASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: A THERNOCASING ABANDON CASING TEST AND CEMENT JOB OTHER: A THERNOCASING ABANDON CASING TEST AND CEMENT JOB OTHER: A THERNOCASING ABANDON TEMPORARILY ABANDON CHANGE PLAS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLAS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CHANGE PLAS SETTION CEMENT JOB OTHER: A THERNOCASING A THERNOCASI	DISTRICT I OIL CONSERVATION DIVISION							
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFPEN OR PLUG BACK TO A DIFFERENT RESEVOR. USE "APPLICATION FOR PREMIT" (PORM C-101 FOR SUCH PROPOSALS) 1. Type of Well	1625 N. French Drive , Hobbs, NM 88240	· · · · · · · · · · · · · · · · · · ·			WELL API	1		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS 10 DRILL OR 170 DEFPENOR RPLICT BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PREMIT" (FORM C-101 FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well Other T&A'd SECTION 31 2. Name of Operator OCCIDENTAL PERMIAN, LTD. 3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter E: 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3. 5633' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starring any proposed word; SEE RULE 1193. 13. Deepen well from 4189' to 4380', Existing open hole 4075' to 4189'. 4. Stimulate open hole w2500 g 15% NEFE HCL acid 5. RIH w'' Guidberson G-6 pe phr, XL on vioff tool w/1.875 ss "P" nipple. Packer set @4021'. 6. 130 is 2-7/8' Ducline tbg. 7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT 7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT 7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT 8. Well No. 121 8. Well No. 121 8. Well No. 121 9. Pool name or Wildest HOBBS (G/SA) UNIT 8. Well No. 121 8.		,			5. Indicate	5. Indicate Type of Lease		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (GROWN C. 10) FOR SUCH PROPOSALS. 1. Type of Well: Oil Well Gas Well Other T&A'd SECTION 3! 3. Address of Operator OCCIDENTAL PERMIAN, LTD. 3. Address of Operator Linit Letter E: 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 3! Township 18-S Range 38-E NMFM LEA County 10. Elevation (Show whether DF, RKB, RT GR. etc.) 3653* GIL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PILLG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PILLIG & ABANDONMENT THER: COMMENCE DRILLING OPNS. PILLIG & ABANDONMENT REMEDIAL WORK ALTERING CASING THERE CASING OTHER: Re-Activate well to Injector X 1. RUPU. Drill out CIBP @3955*. Deepen well from 4189* to 4380°. Existing open hole 4075* to 4189°. Storage on hole w2500 g 15% NEFE HCL acid. S. RIH w/T Guiberson G-6 pc plar, XL on/off tool w/l.875 ss "P" nipple. Packer set @4021*. 6. 130 js 2.78* Duoline tog. Rig Up Date: 08/12/2004 Rig Up Date: 08/12/2004 Type ON PRRNT NAME Robert Gilbert TITLE WO Completion Specialist DATE 08/31/2004 Type ON PRRNT NAME Robert Gilbert Fhore NO. 505-397-8206			-		FED	STATE	FEE X	
Type of Well: Oil Well Gas Well Other T&A'd SECTION 31 SECTION 31 SECTION 31 SECTION 31 Section 31 Township 18-S Range 38-E NMPM LEA County						& Gas Lease No.		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FROM C-101 FOR SUCH PROPOSALS) 1. Type of Well: Oil Well Gas Well Other T&A'd SECTION 31 2. Name of Operator OCCIDENTAL PERMIAN, LTD. 3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 36537 GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT FULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w2500 g 15% NEFE HCL acid. 5. RIH wy" Guiberson G-6 per RX, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 js 2-7/8' Duoline thg. 7. Circ esg w10berson G-6 per RX, XL on/off tool w/1.875 ss "F" nipple. 8. RDPU. Clean Location. Threeby certify that the information above is true and complete to the best of my knowledge and belief. SKNATURE WHITE MALE AND COMPRISED TO SECURITY NAME ROBERT DATE DATE OR S1/2004 TYPE OR PRINTI NAME ROBERT Glibert Phone WO. 505-397-8206	SUNDRY NOTICES AND REPORTS ON WELLS							
Type of Well: Gas Well Other T&A'd SECTION 31								
Oil Well Gas Well Other T&A'd SECTION 31 2. Name of Operator OCCIDENTAL PERMIAN, LTD. 8. Well No. 121 3. Address of Operator 1017 W STANOLIND RD. 9. Pool name or Wildcat HOBBS (G/SA) 4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMFM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653" GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PILOS ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CHANGE PLANS OTHER: OTHER REACTIVATE Well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed words) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955*. 3. Deepen well from 4189" to 4380". Existing open hole 4075" to 4189". 4. Stimulate open hole we'2500 g 15% NEFF HCL acid. 5. RIH W/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021". 6. 130 jts 2-78" Duoline tips. 7. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. Rig Up Date: 08/12/2004 Rig Down Plant NAME Robert Gilbert Phone NO. 505-397-8206						IOBBS (G/SA) U	NIT	
3. Address of Operator 1017 W STANOLIND RD. 4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING ALTERING CASING COMMENCE DRILLING OPNS. PLUG & ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDON THE POPARILLY ABANDON CHANGE PLANS OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103. 13. RUPU Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103. 14. RUPU Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103. 15. RUPU Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103. 16. RUPU Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed word) SEE RULE 1103. 17. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. 18. RUPU Clean Location. 18. RUPU Clean Location. 18. RUPU Clean Location. 18. RUPU Clean Location. 19. Packer set @4021'. 19. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. 19. RUPU Clean Location. 19. Packer set @4021'. 19. RU						31		
4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUIG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/T Guiberson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-78" Duoline thg. 7. Circ csg w/10abrson G-6 pe kpt, XL on/off tool w/1						. 121		
4. Well Location Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB CHANGE PLANS COMMENCE SERULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/T' Guiberson G-6 pp kpr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7:8" Duoline tob. 7. Circ csg w/130 bbl ptr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	3. Address of Operator 1017 W STANOLIND RD.					ne or Wildcat		
Unit Letter E : 1980 Feet From The NORTH Line and 990 Feet From The WEST Line Section 31 Township 18-S Range 38-E NMPM LEA County						G/SA)		
Section 31 Township 18-S Range 38-E NMPM LEA County 10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. RUPU. 14. Stimulate open hole w2500 g 15% NEFE HCL acid. 15. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 16. 130 jis 2-7/8" Duoline bg. 17. Circ csg w130 bbil pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 18. RDPU. Clean Location. 18. RUPU. Clean Location. 19. THE WO Completion Specialist DATE 08/31/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	4. Well Location				······································			
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3653' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: CASING OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RIPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/T Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tog. 7. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. Rig Up Date: 08/12/2004 Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Type OR PRINT NAME Robert Gilbert TITLE WO Completion Specialist DATE 08/31/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	Unit Letter E : 1980	Feet From The NORT	H Line and	990	Feet From The	WEST	Line .	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ABANDON COMMENCE DRILLING OPNS. PLUG & ABANDON PULL OR ALTER CASING OTHER: CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jis 2-7/8" Duoline fbg. 7. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Type OR PRINT NAME Robert Gilbert Title WO Completion Specialist DATE 08/31/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	Section 31	A			38-E N	MPM	LEA County	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: Re-Activate well to Injector X 1. RUPU. 2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955*. 3. Deepen well from 4189* to 4380°. Existing open hole 4075* to 4189°. 4. Stimulate open hole w/2500 g 159% NEFE HCL acid. 5. RIH w/T" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206			er DF, RKB, RT G	R, etc.)				
PERFORM REMEDIAL WORK ABANDON REMEDIAL WORK ABANDON ABANDON REMEDIAL WORK ABANDON COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955*. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbil pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206			cate Nature of	Notice, Rep				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955' 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206			_		SUBSEQUENT	REPORT OF:		
CASING TEST AND CEMENT JOB OTHER: Re-Activate well to Injector X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WILL WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	PERFORM REMEDIAL WORK		REMED	IAL WORK		ALTERING (CASING	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	TEMPORARILY ABANDON	CHANGE PLANS	СОММЕ	NCE DRILLI	NG OPNS.	PLUG & AB	ANDONMENT	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" 'Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	PULL OR ALTER CASING		CASING	TEST AND C	CEMENT JOB			
1. RUPU. 2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	OTHER:		OTHER:	Re-Ac	tivate well to Injec	etor	X	
2. Drill out CIBP @3955'. 3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ esg w/130 bbl pkr fluid. Tst esg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206								
3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'. 4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	1. RUPU.							
4. Stimulate open hole w/2500 g 15% NEFE HCL acid. 5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	2. Drill out CIBP @3955'.							
5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'. 6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	3. Deepen well from 4189' to 4380'. Existing open hole 4075' to 4189'.							
6. 130 jts 2-7/8" Duoline tbg. 7. Circ csg w/130 bbl pkr fluid. Tst csg to 600 psi for 30 min and chart for the NMOCD. 8. RDPU. Clean Location. Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	5. RIH w/7" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple. Packer set @4021'							
Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 Title WO Completion Specialist DATE 08/31/2004 Type OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206								
Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206								
Rig Up Date: 08/12/2004 Rig Down Date: 08/23/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	8. RDPU. Clean Location.				$\left(\stackrel{O}{e} \right)$	03/1/20	ti)	
Rig Down Date: 08/23/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206					\{\bar{\pi}\}.	2-405	4	
Rig Down Date: 08/23/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	Die IIe Deter 09/12/2004				\sqrt{c}	HO HOUSE	57/	
SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206					\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.		N I	
SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	-				•	Eline of the		
SIGNATURE TITLE WO Completion Specialist DATE 08/31/2004 TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206								
TYPE OR PRINT NAME Robert Gilbert Phone NO. 505-397-8206	D14-11	s true and complete to the best of	of my knowledge a	ind belief.				
		Yell	TITLE	WO Com			08/31/2004	
LINK STORE DV STORE LIKET	TYPE OR PRINT NAME Robert Gilbe (This space for State Use)	ert				Phone NO.	505-397-8206	

OF DESTRICT SUPERVISOR/GENERAL MANAGER DATE

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

