## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240		St. Francis Dr. NM 87505	WELL API NO. 30-025-	-26832
DISTRICT II	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410		· · · ·	7 7	. 37
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		NORTH HOBBS (G/SA) UNIT Section 24		
1. Type of Well:	TECHTON TONTEROIT (TOIL C-1	101) for such proposais.)	8. Well No. 242	
Oil Well Gas Well Other Injector  2. Name of Operator		212		
Occidental Permian Ltd.			9. OGRID No. 157984	,
3. Address of Operator	NIM 99240 505/20	7 0200	10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, 4. Well Location	NM 88240 303/39	97-8200		
Unit Letter N : 1300	Feet From The SOUTH		t From The WEST	Line
Section 24	Township 18-S	Range 37-E	NMPM	LEA County
	11. Elevation (Show whether DF, RF 3667' GL	KB, RT GR, etc.)		
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Groun		earest fresh water well	Distance from nearest sur	rface water
Pit Liner Thickness mil	Below-Grade Tank: Volume			race water
THE EMOT THICKNESS IIII		bois, Constituction wa	iciiai	
12. Chec NOTICE OF INT	k Appropriate Box to Indicate Na ENTION TO:		Other Data SEQUENT REPORT OF	::
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING V
				CASING X
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OP		=
		COMMENCE DRILLING OPI	NS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING	CHANGE PLANS  Multiple Completion	COMMENCE DRILLING OPI	NS. PLUG & AE	=
PULL OR ALTER CASING OTHER:	Multiple Completion	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER:	NS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING OTHER:	Multiple Completion	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER:	NS. PLUG & AB	BANDONMENT
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen	Multiple Completion  Decrations (Clearly state all pertinent do For Multiple Completions: Attach w t. Run 300' 4.5" ULT FJ @4300'. I	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: etails, and give pertinent dates, relibore diagram of proposed of	PLUG & AE T JOB  including estimated date of strompletion or recompletion.  8' to 3300'.	BANDONMENT
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals	Multiple Completion  Derations (Clearly state all pertinent derations: Attach with the completions: Attach with the completions and 4.5" ULT FJ @4300'. Fee 4120-26, 4234-42, 4247-50, and 4	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: etails, and give pertinent dates, relibore diagram of proposed of Run CBL/CCL/GR from 429 268-78 using 2 spf and 180 of	plug & AB T JOB plug & AB T including estimated date of st completion or recompletion T to 3300'. The plug & AB T JOB plug & A	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals	Multiple Completion  Derations (Clearly state all pertinent derations: Attach with the completions: Attach with the completions and 4.5" ULT FJ @4300'. Fee 4120-26, 4234-42, 4247-50, and 4	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: etails, and give pertinent dates, relibore diagram of proposed of Run CBL/CCL/GR from 429 268-78 using 2 spf and 180 of	plug & AB T JOB plug & AB T including estimated date of st completion or recompletion T to 3300'. The plug & AB T JOB plug & A	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/124 4. RIH w/Guiberson UNI VI pc pkr	Multiple Completion Derations (Clearly state all pertinent do. For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. F. 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/124 4. RIH w/Guiberson UNI VI pc pkr	Multiple Completion  Decrations (Clearly state all pertinent do For Multiple Completions: Attach w t. Run 300' 4.5" ULT FJ @4300'. I	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.	Multiple Completion Derations (Clearly state all pertinent do. For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. F. 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004	Multiple Completion Derations (Clearly state all pertinent do. For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. F. 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.	Multiple Completion Derations (Clearly state all pertinent do. For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. F. 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004	Multiple Completion Derations (Clearly state all pertinent do. For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. F. 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER:  etails, and give pertinent dates, relibore diagram of proposed of the complex of the comple	plug & AE  T JOB  including estimated date of strompletion or recompletion  8' to 3300'.  deg spiral plug & AE  By Pkr setto 4193'.	arting any
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/12: 4. RIH w/Guiberson UNI VI pc pk: 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004	Multiple Completion Derations (Clearly state all pertinent deray For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  The completion of the completion o	COMMENCE DRILLING OPPORTUGE CASING TEST AND CEMENT OTHER:  etails, and give pertinent dates of proposed of the composition of proposed of the composition of the comp	including estimated date of strompletion or recompletion of strompletion of strompletion of strompletion of strompletion of strompletion of recompletion of strompletion of st	arting any  293037  293037  2004  ELECTRONIC DESCRIPTION OF THE PROPERTY OF TH
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pks 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  Complete to the Miles of the State	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER:  etails, and give pertinent dates vellbore diagram of proposed of Run CBL/CCL/GR from 429 268-78 using 2 spf and 180 of ople. 136 jts 2-7/8" Duoline to the for the NMOCD.	including estimated date of strompletion or recompletion of recompletion of strompletion of recompletion of re	arting any  293037  293037  2004  ELECTRONIC DESCRIPTION OF THE PROPERTY OF TH
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/12: 4. RIH w/Guiberson UNI VI pc pk: 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004	Multiple Completion  Derations (Clearly state all pertinent derections). Attach with the Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  To XL on/off tool w/1.875 ss "F" nip trong to 570 psi for 30 min and chart true and complete to the best of my known.	COMMENCE DRILLING OPPORTUGE CASING TEST AND CEMENT OTHER:  etails, and give pertinent dates of proposed of the composition of proposed of the composition of the comp	including estimated date of strompletion or recompletion of recompletion of strompletion of recompletion of re	arting any  293037  293037  2004  ELECTRONIC DESCRIPTION OF THE PROPERTY OF TH
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pks 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  Complete to the Miles of the State	commence delicition of the National Commence o	sincluding estimated date of strompletion or recompletions and spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plant	arting any  29 30 37  20 455  20 50 50  20 50
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pks 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004  I hereby certify that the information above is constructed or closed according to NMOCD guidelines.  SIGNATURE	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  The completion of the complete to the best of my known and complete to the best of my known as general permit with the complete to the best of my known as general permit with	COMMENCE DRILLING OPPLICATION CASING TEST AND CEMEN OTHER:  etails, and give pertinent dates wellbore diagram of proposed of the complete diagram of the complete	including estimated date of strompletion or recompletion of recompletion of strompletion or recompletion of strompletion or recompletion of re	arting any  29 30 37  204  55  60  204  55  60  204  60  204  60  60  60  60  60  60  60  60  60
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/12/4. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004  I hereby certify that the information above is constructed or closed according to NMOCD guidelines.  SIGNATURE TYPE OR PRINT NAME Robert Gilb.	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  The complete to the best of my known and complete to the best of my known as general permit with the complete to t	commence delicition of the National Commence o	sincluding estimated date of strompletion or recompletions and spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plants are spiral plants are spiral plants. Along the spiral plant	arting any  29 30 37  20 455  20 50 50  20 50
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals: 3. Stimulate perfs 4220-4278 w/124. RIH w/Guiberson UNI VI pc pkr. 5. Load csg w/100 bbl pkr fluid. Ts. 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004  I hereby certify that the information above is constructed or closed according to NMOCD guidelines.  SIGNATURE  TYPE OR PRINT NAME Robert Gilb.	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  The completion of the complete to the best of my known and complete to the best of my known as general permit with the complete to the best of my known as general permit with	COMMENCE DRILLING OPPLICATION CASING TEST AND CEMEN OTHER:  etails, and give pertinent dates wellbore diagram of proposed of the complete diagram of the complete	including estimated date of strompletion or recompletion of recompletion of strompletion or recompletion of strompletion or recompletion of re	arting any  29 30 37  204  55  60  204  55  60  204  60  204  60  60  60  60  60  60  60  60  60
PULL OR ALTER CASING OTHER:  13. Describe Proposed or Completed Or proposed work) SEE RULE 1103.  1. RUPU. Pull Injection equipmen 2. Perforate the following intervals 3. Stimulate perfs 4220-4278 w/12/4. RIH w/Guiberson UNI VI pc pkr 5. Load csg w/100 bbl pkr fluid. Ts 6. RDPU. Clean Location.  Rig Up Date: 09/11/2004 Rig Down Date: 09/17/2004  I hereby certify that the information above is constructed or closed according to NMOCD guidelines.  SIGNATURE TYPE OR PRINT NAME Robert Gilb.	Multiple Completion  Derations (Clearly state all pertinent de For Multiple Completions: Attach w. t. Run 300' 4.5" ULT FJ @4300'. For 4120-26, 4234-42, 4247-50, and 450 g 15% NEFE HCL acid.  The completion of the complete to the best of my known and complete to the best of my known as general permit with the complete to the best of my known as general permit with	COMMENCE DRILLING OPPLICATION CASING TEST AND CEMEN OTHER:  etails, and give pertinent dates wellbore diagram of proposed of the complete diagram of the complete	including estimated date of strompletion or recompletion of recompletion of strompletion or recompletion of strompletion or recompletion of re	arting any  29 30 37  204  55  60  204  55  60  204  60  204  60  60  60  60  60  60  60  60  60

