Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources		Form C-103 Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Avc., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-10751
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fc, NM 87505		0. State Off & Gas Dease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name
PROPOSALS.)		TEXAS STATE
1. Type of Well:		8. Well Number
Oil Well Gas Well Other		2
 Name of Operator LANEXCO, INC. Address of Operator 		9. OGRID Number 0103046
4. Well Location		10. Pool name or Wildcat JALMAT TANSILL Y SR(PRO GAS)
Unit Letter I : 1980 feet from the S line and 330 feet from the E line		
Section 16 Township 23S Range 36E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whethet CR, R		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK Z ALTERING CASING		
	COMMENCE DR	
PULL OR ALTER CASING DULTIPLE COMPLETION	CASING TEST AI CEMENT JOB	
OTHER:	OTHER:	D 3031-153
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
WELL DATA: 10 3/4" set at 256'. Cmt.circ. 7" 20# at 3077' 200 sx around shoe (est. TOC 2127) Perforated at 1245' and pumped 200 sx cement. (est. TOC 295).		
PROPOSAL: Rig up unit. Pull production equipment. Set COB¼ at 3000'± Dump 35ft. cmt. on top. RIH and circ. 10# mud.		
Spot 30 sx at salt section. Spot 30 sx at 1295'-1195'		
Perf. and squeeze 50 sx at 308'-208' and tag. Spot		
10 sx at 60 ft. to surface. Install dry hole marker.		
Remove all equipment	from locati	on.
This will start as soon as the	plugging com	pany is available.
I hereby certify that the information above is true and complete to the	ha hast of my Imagelada	o and halfaf
DA and DA		
SIGNATURE R dent the Land on TITLI	<u> PRESIDENT</u>	DATE 11/2/04
Type or print name ROBERT W. LANSFORD (This space for State use) APPPROVED BY Hauf W. Win & CFIELD REPRESENTATIVE II/STAFF MANAGES DATE NOV 0.8.2001		
	EPRESENTATIVE IVS	Arr was
APPPROVED BY Hand W. W. W. TITLE Conditions of approval, if any	B	DATE NOV 0 8 2004
THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE		

.

BEGINNING OF PLUGGING OPERATIONS.