

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

5. Lease Designation and Serial No.
LC 054667

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

EL PASO TOM FEDERAL#9

9. API Well No.

30-025-11882

10. Field and Pool, or Exploratory Area

JALMAT TANSILL YATES

11. County or Parish, State
LEA 7 RIVER(GA)

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

LANEXCO, INC.

3. Address and Telephone No.

1105 WEST KANSAS, JAL, NM 88252

505-395-3056

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 660' FWL

S - 33, TWP 25-S, R-37E

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up unit. Pull production equipment. Set 7" CIBP at ²⁹⁵⁰2500 ft. Dump 50 ft. cement on CIBP. Circulate the hole with brine water and gel. ^{Tag} ~~Set 50 ft. plug from 500-450.~~ ¹⁰⁰ ~~Set 50 ft. plug from 260-210.~~ (Surface casing at 235) Set ⁶⁰30 ft. surface plug. Cut off wellhead, install dry hole marker. Remove all aquipment. Plow up the location. Work ¹²³⁴expected to start as soon as the plugging company can schelule, after approval by the BLM

Perforate @ 285' & Squeeze With Sufficient Cement (70 SX.) To Have Solid

Perforate @ 1200' & Squeeze With Sufficient Cement (40 SX.) To Have Solid 100' Plug From 1200-1100'

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed

Title PRODUCTION SUPT.

Date 10-20-04

(This space for Federal or State office use)

Approved by

DAVID R. GLASS

Title

Date

OCT 29 2004

Conditions of approval, if any: