State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025	5-30263
<u>DISTRICT II</u>	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			Section 32	
1. Type of Well:			8. Well No. 313	
Oil Well X Gas Well Other				
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS,	NM 88240 505/39	7-8200	101100111111111111111111111111111111111	HODDS (G/SA)
4. Well Location	1111 005.0		1	
Unit Letter B : 500	Feet From The NORTH	Fee	t From The EAST	Line
Section 32	Township 18-S	Range 38-I	NMPM	LEA County
	11. Elevation (Show whether DF, RK 3639' GR	(B, RT GR, etc.)		
_				
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Groun	d Water Distance from ne	earest fresh water well	Distance from nearest su	ırface water
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction Ma	terial	
12. Chec	k Appropriate Box to Indicate Nat	ture of Notice Report or (Other Data	
NOTICE OF INT			SEQUENT REPORT O	F:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING	<u></u>
	CHANGE PLANS	COMMENCE DRILLING OP	=	ABANDONMENT
TEMPORARILY ABANDON				BANDONWILLIA
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEN	II JOB []	
OTHER:		OTHER:		
13. Describe Proposed or Completed Or	perations (Clearly state all pertinent de	etails, and give pertinent dates	, including estimated date of s	starting any
proposed work) SEE RULE 1103	For Multiple Completions: Attach w	ellbore diagram of proposed	completion or recompletion.	
1 DUDII Dull and decides assistant				
 RUPU. Pull production equipm Stimulate 4052-4229 w/1680 g X 		acid		7181920
1. RUPU. Pull production equipment. 2. Stimulate 4052-4229 w/1680 g Xylene and 3000 g 15% NEFE HCL acid 3. Run Reda ESP equipment. Size for 500 BFD. 4. 130 jts 2-7/8" tbg. Intake set @4105'. 5. Install QCI wellhead connection. 6. RDPU. Clean Location. Rig Up Date: 10/25/2004				
4. 130 jts 2-7/8" tbg. Intake set @4			640	15
5. Install QCI wellhead connection			37	000 Hopps WIN WIN
6. RDPU. Clean Location.			100	Hobbs
D' 11 D			A.,	MAY A SA
Rig Up Date: 10/25/2004				FRANCE AON S
Rig Down Date: 10/27/2004			/@	NON AN
			100	
I hereby certify that the information above is	true and complete to the best of my know	ledge and belief. I further certify	that any pit or below-grade tank-l	ias been/will be &
constructed or		_		TO LA
closed according to NMOCD guidelines	, a general permit	or an (attached) alternativ	e OCD-approved	
SIGNATURE Tobut	thut	TITLEWorkover Comp	pletion Specialist DAT	E 10/31/2004
TYPE OR PRINT NAME Robert Gilb	ert E-mail address:	robert_gilbert@oxy.com	TELEPHONE NO.	505/397-8206
For State Use Only	1,11	UC EIEI H BEBHESEN IN	a things in hit a king a san the first and t	3 559
APPROVED BY Land	1, Wink	TITLE	ATIVE WOTAFF MANAC	TE
CONDITIONS OF APPROVAL IN ANY:				