	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30 025 03427
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE 🔀 FEE 🗌
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B 1399
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	SHELL STATE
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR SUCH	······································
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well	Gas Well Other	7
2. Name of Operator	NO I D	9. OGRID Number
HAL J. RASMUSSEN OPERATI 3. Address of Operator	NG, L.P.	00 98 09
, <u>-</u>	I AND TENAS TOTAL	10. Pool name or Wildcat
550 W. TEXAS SUITE 200, MID	LAND, IEXAS /9/01	WILSON YATES SEVEN RIVERS
4. Well Location	4. Ext.	
Unit LetterF_:_1980_feet from theNORTH line and1907feet from theWESTline		
Section 7 Township 21-S Range 35-E NMPM LEA County		
	11. Elevation (Show whether DR, RKB, RT, GR, e	
	Die tallen (She'n whether Die, Rub, Ri, Ori, e	510.)
Pit or Below-grade Tank Application	or Closure	
Pit type STEEL Depth to Ground	water40Distance from nearest fresh water well	Distance Community of the Control of
I		
		Construction Material
12. Check	Appropriate Box to Indicate Nature of Notice	ce. Report or Other Data
		, F
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	THE THE PARTY OF T	ORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE	DRILLING OPNS. P AND A 💢 📉
PULL OR ALTER CASING		
0-11-		
OTHER:		
	OTHER:	
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details.	and give pertinent dates, including estimated date
13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent details.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
 Describe proposed or com of starting any proposed v or recompletion. 	pleted operations. (Clearly state all pertinent details, vork). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed v or recompletion. SET CIBP @ 3600' TOPPED	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed v or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed w or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed w or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 1260'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or com of starting any proposed w or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 1260'. D 50 SX CEMENT, TAG TOC @ 300'.	Attach wellbore diagram of proposed completion
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162',	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'.	Attach wellbore diagram of proposed completion
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'.	Attach wellbore diagram of proposed completion
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162',	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'.	Attach wellbore diagram of proposed completion 030 sqqqH
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 1260'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT.	Attach wellbore diagram of proposed completion 000 000 000 000 000 000 000
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. O 50 SX CEMENT. O 50 SX CEMENT.	Attach wellbore diagram of proposed completion 030 030 sqqqh 031 031 031 031 031 031 031 03
13. Describe proposed or come of starting any proposed or or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 162', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. Her H	Attach wellbore diagram of proposed completion 000 000 000 000 000 000 000
13. Describe proposed or come of starting any proposed or or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 162', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. O 50 SX CEMENT. O 50 SX CEMENT.	Attach wellbore diagram of proposed completion 030 030 sqqqh 031 031 031 031 031 031 031 03
13. Describe proposed or come of starting any proposed or or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 162', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. Her H	Attach wellbore diagram of proposed completion 030 sqqqh 031 031 032 030 sqqqh 031 031 031 032 033 033 034 035 035 036 037 037 038 038 038 038 038 038
13. Describe proposed or come of starting any proposed we or recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 162', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. Her H	Attach wellbore diagram of proposed completion 030 sqqqh 031 031 032 030 sqqqh 031 031 031 032 033 033 034 035 035 036 037 037 038 038 038 038 038 038
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. Her H	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 2000 030 030 030 030 030 030 030 030 03
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG SET 25 SX SURFACE PLUG Approve Liability surface r	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT.	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 030 1400 600 1400
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG SET 25 SX SURFACE PLUG Approve Liability surface r	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT.	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 030 1400 600 1400
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUGATION Approve Liability surface related to the surface of the surface	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines	Attach wellbore diagram of proposed completion 030 sqqoH co 031.7774 200 6500 edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG SET 25 SX SURFACE PLUG Approve Liability surface r	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. O', TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 1745'. D 30 SX CEMENT, TAGGED TOC @ 300'. D 50 SX CEMENT. O', TAGGED TOC @ 300'. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT. D 50 SX CEMENT.	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 030 1400 600 1400
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUGATION Approve Liability surface relationship of the constructed of surface tank has been/will be constructed as SIGNATURE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines TITLE AGENT	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 05 06 07 08 09 09 09 09 09 09 09 09 09 09 09 09 09
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 150', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG Approve Liability surface relationship of the constructed of surface relationship of the c	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will be a sto plugging of the Well Bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines TITLE AGENT AYLOR E-mail address: ttaylor@tetra	Attach wellbore diagram of proposed completion 030 sqqoH SqqoH CO
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUGATION Approve Liability surface relationship of the constructed of surface tank has been/will be constructed as SIGNATURE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will be a sto plugging of the Well Bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines TITLE AGENT AYLOR E-mail address: ttaylor@tetra	Attach wellbore diagram of proposed completion 030 sqqoH SqqoH CO
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUG Approve Liability surface relationship of the constructed of the surface relationship of the constructed of SIGNATURE Type or print name TOMMY T	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will be a sto plugging of the Well Bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines TITLE AGENT AYLOR E-mail address: ttaylor@tetra	Attach wellbore diagram of proposed completion 030 sqqoH SQUENCE OS 6222 edge and belief. I further certify that any pit or below- t or an (attached) alternative OCD-approved plan . DATE 11/19/2004 tec.com Telephone No. 432 570 5382
13. Describe proposed or comof starting any proposed wor recompletion. SET CIBP @ 3600' TOPPED SET 25 SX CEMENT @ 2830 PERF'D @ 1850', SQUEEZE PERF'D @ 1380', SQUEEZE PERF'D @ 450', SQUEEZE PERF'D @ 162', SQUEEZE SET 25 SX SURFACE PLUGATION Approve Liability surface results of the surface results	pleted operations. (Clearly state all pertinent details, york). SEE RULE 1103. For Multiple Completions: W/ 25 SX CEMENT. Y, TAGGED TOC @ 2640'. D 30 SX CEMENT, TAG TOC @ 1745'. ED 30 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT, TAG TOC @ 300'. D 50 SX CEMENT. He will be a sto plugging of the Well Bore. under bond is retained until estoration is completed. In above is true and complete to the best of my knowledge or closed according to NMOCD guidelines TITLE AGENT AYLOR E-mail address: ttaylor@tetra	Attach wellbore diagram of proposed completion 030 sqqoH 031.7774 000 sqqoH 000 co 031.7774 0

1.