	42.				•	F C 102		
	State of New Market			0		Form C-103		
Distrect	Office District Energy, Minerals an			Resources _		Revised March 25, 1999		
	1625 N. French Dr., Hobbs, NM 87240			1	WELL API NO.	25_20556		
District [[				VISION -	30-025-20556			
Bill South Fin District (II	Control 1 1195 'Ci (0010' 1 1110 0.0.)		outh Pacheco	1 .	5. Indicate Type			
	1000 Dia D 0.4 Amen NR 97410				STATE			
District IV	District IV Sama Pe,			<u> </u>		Gas Lease No.		
2040 South Pa	checo, Santa Fe, NM 875	05			K-86			
		TICES AND REPORTS O			. Lease Name o	r Unit Agreement Name:		
(DO NOT USI	THIS FORM FOR PRO	POSALS TO DRILL OR TO DEE	EPEN OR PLUG BA	CKTOA				
PROPOSALS.		PLICATION FOR PERMIT* (FOR	UM C-101) FOR SUC	<b>H</b>	Mesa (	Queen Unit		
	1. Type of Weil:							
Oil Well		Other						
	2. Name of Operator							
	Xeric Oil & Gas Corporation					17		
	3. Address of Operator				Pool name or \	Wildcat		
	P. O. Box 352, Midland, TX 79702				Mesa	Queen		
4. Weil Lo								
			•					
Unit	Letter M	: 330 feet from the	South	line and990_	feet from	n the West line		
Secti	ion 17	Township 16	S Range 3	32E N	MPM Lea	County		
		10. Elevation (Show w						
		A	4358' GR					
	11. Check A	Appropriate Box to Ind	icate Nature o	f Notice, Rep	ort or Other I	)ata		
·		NTENTION TO:	1	SUBSE	QUENT REP	ORT OF		
OFFICEN DI		PLUG AND ABANDON	(S) DEME	EDIAL WORK		ALTERING CASING		
FENFORW R	EMEDIAL MONK	, PEDG AND ABANDON	THE PARTY NAME OF THE PARTY NA	DIAL HOM				
TEMPORARIL	Y ARANDON	CHANGE PLANS	COM	MENCE DRILLIN		PLUG AND		
		,				ABANDONMENT		
PULL OR ALT	er casing 🔲	· · · - ·		IG TEST AND				
		COMPLETION	CEME	NT JOB				
OT IED			OTHE	<b>.</b>				
OTHER:								
12. Describe	proposed or complete	ed operations. Clearly stat	te all pertinent de	eaus, and give p	trunent dales, in	Formased completion		
of starting	any proposed work).	. SEE RULE 1103. For M	untiple Complete	ons: Auach Wei	Dore diagram of	proposed completion		
or recomp	iation.			THE COMMIS	SION MUST BE	NOTIFIED 24		
1)	MIRU Pulling	Unit & lay down rods	or tubing.		R TO THE BEC			
2)		jet cut 4½" casing @ 6	_		PERATIONS FO			
•				TO BE APPRO				
3)	) POOH laying down w/4/2 casing.							
4)	4) RDMO Pulling Unit.							
5)								
6) Spot Plug #1 @ 3400' w/10 sx Class C + 2% CaCl & tag.								
•								
7)					Class C + C	10/ C-C1 9-		
8)	Spot Plug #3 @	3 50' inside 41/2" casing	g stub & circul	late out w/25 s	sx Class C + 2	2% CaCl &		
	tag.							
9)	<del>-</del>	ug @ 100' w/20 sx Cl	lass C + 2% C	aCl.				
10)		install dry hole marke		<del></del>				
•		1						
hereby certify that	the information abou	ve is true and complete to the	he best of my kno	owledge and beli	ef.			
	10/		•	•				
GNATURE /	MI	TITLE	<u>Treasure</u>	r	DAT	E 10/19/01		
	- ///	<u> </u>			915-			
pe or print name	KyleLewis				915- Telephone No	-683-3650		
	Kyle Lewis				915- Telephone No	-683-3650		
			^	<u></u>	Telephone No	-683-3650		
his space for State		TITLE	ÔRIGINA	al signed b <b>ý</b>	Telephone No	00T 2.3 2000		
This space for State PPPROVED BY_	e use)	TITLE			Telephone No	00T 2.3 2000		
ype or print name This space for State PPPROVED BY Conditions of appro	e use)	TITLE	GAR	AL SIGNED B <b>Y</b> Y W. WINK JENGE WANGES	Telephone No	00T 2.3 2000		