

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-9683

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	Anderson Ranch Unit
3. Address of Operator	8. Farm or Lease Name
P. O. Box 460, Hobbs, N.M. 88240	Anderson Ranch Unit
4. Location of Well	9. Well No.
UNIT LETTER <u>E</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM	20
THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> N.M.P.M.	10. Field and Pool, or Wildcat
	Anderson Ranch Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- ① MIRU, spot 40' class "H" cmt on top of CIBP @ 9650', CIBP set 3-14-86.
- ② Chemically cut 5 1/2" production csg @ 4300'. PooH & land recovered esg.
- ③ Spot 100' class "H" cmt across 8 5/8" intermediate casing shoe & top of remain prod. csg. 50' above in Intermediate + 50' below in 5 1/2" prod. string. This plug must be tagged.
- ④ Spot 100' class "H" cmt plug at the top of salt from 1300'-1200'
- ⑤ Place 50' class "H" surface plug. Cut off all csg to final restored ground leve. Cover well w/ 2' diameter x 4" thick cmt. cap. Install well abandonment marker. Rig down

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry L. Vogel TITLE Administrative Supervisor DATE 3-21-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

DATE MAR 25 1986

NMOC-40665(3) Chev. File