

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-28393
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-3657
7. Lease Name or Unit Agreement Name State of New Mexico "T"
8. Well Number 4
9. OGRID Number 025773
10. Pool name or Wildcat Baum Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Dominion Oklahoma Texas E&P, Inc.

3. Address of Operator
14000 Quail Springs Parkway, Ste. 600, Oklahoma City,

4. Well Location
OK 73134
Unit Letter P : 660 feet from the South line and 660 feet from the East line
Section 32 Township 13S Range 33E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4243' GR

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
feet from the line and feet from the line Steel pit on loc 6517 circ. into.

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. 11-18-04 MIRU. 2. 11-19-04 Pulled 61 jts. of 2-7/8" tbg. Hit tight spot, could not pull T.A.C. thru. Okayed w/ NMOCD Billy Prichard to cut tbg. @ T.A.C. and leave in hole 1/2 jt. 2-7/8" X 5-1/2" T.A.C. 9 jts. S.N. left in hole. 3. 11-22-04 Spot 25 sx cmt. @ 9700' WOC. 4. 11-23-04 Tag T.O.C. @ 9800'. 5. Spot 25 sx cmt. 9700' WOC & tag TOC w/ WL @ 9703'. 6. Spot 25 sx cmt. WOC & tag @ 9658' on 11-24-04. 0 PSI. 7. 11-24-04 Could not get well to circ. 8. 11-29-04 Perf. well @ 7296', pressure tested perfs. (cont.)

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Roger Massey TITLE Agent DATE 12/10/04
Type or print name Roger Massey E-mail address: Telephone No. 432-530-0907

(This space for State use)

APPROVED BY Hayden Link TITLE DATE
Conditions of approval, if any:

OCD FIELD REPRESENTATIVE II/STAFF MANAGER DEC 22 2004

Page 2

Dominion Oklahoma Texas Exp & Prod.

State of NM T #4

P&A

@ 1000# PSI. 9. 11-29-04 Spot 25 sx cmt. from 7346 to 7125' WL tag.
10. Cut & pull 5-1/2" csg. cut @ 4137'. 11. 12-01-04 Spot 45 sx cmt. @ 4202'.
12. 12-02-04 Tag TOC @ 4036'. 13. 12-02-04 Spot 35 sx cmt. @ 1700'. 14. Spot
35 sx cmt. @ 450', WOC & tag @ 335'. 15. 12-02-04 Spot 10 sx cmt. from 60' to surf.
12-02-04 RDMO. Cut off wellhead, install dry hole marker, & clean location.