• • • •	State of New Mexico		Form C-103	
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and Natural Resources		May 27, 2004	
District II OII CONSE	OIL CONSERVATION DIVISION		<u>25-09303</u>	
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.		5. Indicate Type	e of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		STATE	X FEE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & O	Gas Lease No.	
SUNDRY NOTICES AND REPORT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR T DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name STATE A A/C	or Unit Agreement Name:		
PROPOSALS.) 1. Type of Well:		8. Well Number	•	
Oil Well Gas Well X Other		o. Wen ramou	005	
2. Name of Operator		9. OGRID Num	9. OGRID Number	
MISSION RESOURCES CORPORATION		1	148381	
3. Address of Operator		10. Pool name	10. Pool name or Wildcat	
1331 LAMAR, SUITE 1455 HOUSTON, TEXAS 77010-3039		JALMAT; TAN, YA	ATES, 7-RVRS(GAS) 79240	
4. Well Location				
Unit Letter G: 1980 feet from	the NORTH line a	nd feet i	from the <u>EAST</u> line	
Section 10 Township	23S Range 36	SE NMPM	County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3461 'GR				
Pit or Below-grade Tank Application or Closure				
Pit typen/a Depth to Groundwater149 ' Distance from nearest fresh water well1000 '+ Distance from nearest surface water1000 '+				
Pit Liner Thickness:n/a mil Below-Grade Ta	nk: Volume <u>500</u> bbls; Co	nstruction Material Steel	(Frac Tanks)	
12. Check Appropriate Box to NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANG		SUBSEQUENT R		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE	DRILLING OPNS.	PLUG AND	
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TES		ABANDONMENT	
OTHER:	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. I		Attach wellbore diagram		
or recompletion. Add Perforations & Frac. Please see attached Procedure with Wellbore	a Schamatics	(3141516 Pe	2005 C. VED	
			0878 8 4 8 C	
I hereby certify that the information above is true and comp	olete to the best of my kno	wledge and belief. I furth	ner certify that any pit or below-	
grade tank has been/will be constructed or closed according to NMO SIGNATURE		permitor an (attached) a atory Coordinator	Internative OCD-approved plan DATE	
Type or print name Nancy K. Gatti	E-mail address:	nancy.gatti@mrc	corp.com	
For State Use Only			lephone No. 713-495-3128 \JAN 1 9 2005	
ADDROVED BY	PETRO	LEUM ENGINEER	idi ii i	

Conditions of Approval, if any:

Mission Resources Corp. AAC-3 #5 Jalmat Field Lea County, NM December 13, 2004

Work Over Procedure

- 1. MIRU work over rig. Pull tubing.
- 2. RU e-line unit.
- 3. Perforate Tansil and 7 Rivers from 2941' to 3326'.
- 4. Break down and acidize each NEW perf with PPI tool.
- 5. RIH and set packer on 3-1/2" tubing. RD work over rig.
- 6. Frac well per recommendation.
- 7. Flow and test well. Put back to sales.
- 8. Put well back on pump when well loads up.



