Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District 1	Energy, Minerals and Natural Resources	WELL API NO. May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION	30-045-32532
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOT	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR, USE "APPLIC	SALS TO DRILL OR TO DEEPEN OF FEUG BACK TO A CATION FOR PERMIT" (FORM C 101) FOR SUCH	Schwerdtfeger A
PROPOSALS.)		(APD filed with BLM NMNM 077112) 8. Well Number
1. Type of Well: Oil Well	Gas Well Other O	2 M
2. Name of Operator BP AMERICA PRODUCTION	COMPANY	9. OGRID Number
3. Address of Operator	SOMPANY S	7 10. Pool name or Wildcat
P.O. BOX 3092 HOUSTON, TX	77079-2064	Basin Dakota & Blanco Mesaverde
4. Well Location	BUI GISIN	
		1280 feet from the West line
Section 31	Township 28N Range 08V 11. Elevation (Show whether DR, RKB, RT, GR, e	
	5911'	
Pit or Below-grade Tank Application		
Pit typeDepth to Groundw		Distance from nearest surface water
Pit Liner Thickness: mil		Construction Material
12. Check	Appropriate Box to Indicate Nature of Notice	ce, Report or Other Data
NOTICE OF IN	ITENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	_
TEMPORARILY ABANDON DULL OR ALTER CASING	<u>-</u>	ORILLING OPNS.□ PAND A □
TOLE ON ALTEN GAGING	_	
OTHER: DOWNHOLE COMMING		
	pleted operations. (Clearly state all pertinent details, ork). SEE RULE 1103. For Multiple Completions:	
or recompletion.	,	
On 08/12/04 RP America Production	on Company submitted an application for permit to	drill and complete the subject well into the Basis
On 08/12/04 BP America Production Company submitted an application for permit to drill and complete the subject well into the Basis Dakota; produce the well in order to establish a production rate, isolate the zone, then add the Blanco Mesaverde and commingle		
production Downhole. APD was approved 12/22/2004. BP now seeks NMOCD approval to Downhole commingle production in the		
subject well as per procedure on rev	erse side of this Form.	
	anco Mesaverde (72319) Pools are Pre-Approved fo	
	ng royalty interest owners are the same in the propose	ed commingled pools; therefore no further
notification of this application is ne	cessary.	
	on a fixed percentage. We will complete in the Basis	
	roduction rate; drill out the bridge plug and commin zones and MV rate will be subtracted from the total	
will be performed on the combined	zones and MIV rate will be subtracted from the total	well stream to establish the DK rate.
Commingling Production Downho	le in the subject well from the proposed pools v	vill not reduce the value of the total remaining
production I hereby certify that the information	above is true and complete to the best of my knowle	day and haliaf. I fourther contifu that any nit on halow
grade tank has been/will be constructed or	r closed according to NMOCD guidelines [], a general permit	t or an (attached) alternative OCD-approved plan .
SIGNATURE MIRRY A	ava TITLE Regulatory Ana	ulyst DATE 12/31/2004
	TITLE Regulatory Ana	DATE 12/31/2004
Type or print name Cherry Hlava	E-mail address: hlavacl@bp.com	Telephone No. 281-366-4081
For State Use Only	CEPUTY OIL 8 GAS IN	SSECTION WITH TO JAN - 1 200E
APPROVED BY:	TITLETITLE	DATE 4 4003
Conditions of Approval (if any):	\mathcal{U}^{\bullet}	
		(over)
		/

- 1. Run TDT/CBL
- 2. Perforate DK
- 3. Frac the DK (Slick Water)
- 4. RU SU. Clean out DK frac, perform flow test, collect DK gas sample, and obtain 12-hour BHPBU

The second of th

and the state of t

ing and the second of the seco

- 5. Set bridge plug to isolate MV from DK formation
- 6. Perforate and frac (2- Stage N2 Foam) the MV Formation
- 7. Clean out MV frac, perform flow test for production allocation and collect MV gas sample
- 8: Drill out isolation plug, commingle MV/DK and clean out wellbore to PBTD. And the second of the s
- 10. Put well on Line