Office District I	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 May 27, 2004		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO. 30–025–2549		
District II 1301 W. Grand Ave., Artesia, NM 88210				5. Indicate Type of Lease		1
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE FEE		ŀ
strict IV Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fc, NM 87505				E-1923		
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Phillip State		
1. Type of Well: Oil Well 🔯 Gas Well 🗌 Other				8. Well Number 1		
2. Name of Operator Hal J. Rasmussen Operating, Inc.				9. OGRID Number		
3. Address of Operator 550 W. Texas Ste. 200 Midland, TX79701				10. Pool name or Wildcat Wilson Yates 7 Rivers Assoc.		
4. Well Location Unit Letter G	: 1980 feet from the	North	line and $\frac{1}{2}$	980 fee	t from the East line	
Section 14	Township 21		inge 34E	NMPM	County Lea	
	11. Elevation (Show wh					1
	3690 GL					•
Pit or Below-grade Tank Application Pit type Steel Depth to Ground	water 120 Distance from nea		none ni		none	ĺ
Pit Liner Thickness: m				onstruction Materi		
						i
12. Check	Appropriate Box to Inc	dicate N	ature of Notice,	Report or Ot	her Data	
NOTICE OF I	NTENTION TO:		SUB	SEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK		=	REMEDIAL WOR		☐ ALTERING CASING ☐	
TEMPORARILY ABANDON			COMMENCE DR		=	.*.
PULL OR ALTER CASING	MULTIPLE COMPL	u .	CASING/CEMEN	11306 [J 020	
OTHER:			OTHER:		sqqoH TY	4.1 4.1
13. Describe proposed or con			pertinent details, an		t dates, including estimated date	
13. Describe proposed or com of starting any proposed v			pertinent details, an		<u> </u>	
 Describe proposed or come of starting any proposed voor recompletion. 	vork). SEE RULE 1103. F		pertinent details, an		t dates, including estimated date	
13. Describe proposed or com of starting any proposed v	vork). SEE RULE 1103. F		pertinent details, an		t dates, including estimated date	
13. Describe proposed or composed or composed or completion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt.	work). SEE RULE 1103. F 3550'. MLF. 3550' - 3325', TA	or Multip	pertinent details, and le Completions: A	ttach wellbore d	t dates, including estimated date	
13. Describe proposed or composed or starting any proposed or or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & squeen	work). SEE RULE 1103. F 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180	OC & ta	pertinent details, and le Completions: A	ttach wellbore d	t dates, including estimated date liagram of proposed completion	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & squee 5. Perforate @ 320'	work). SEE RULE 1103. F 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt	or Multip	pertinent details, and le Completions: A sag. 1700', WOC & 5-1/2'' csg.	tag. & circula	t dates, including estimated date liagram of proposed completion te cmt. to surface	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & squee 5. Perforate @ 320'	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or composed or composed or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque (5. Perforate @ 320' on 5-1/2" x 8-5/8	work). SEE RULE 1103. F 3 3550'. MLF. 3550' - 3325', W eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave	or Multip OC & ta OO' - down cmt. (pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 3 surface on	tag. & circula inside of	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC &	
13. Describe proposed or com of starting any proposed or or recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w 3. Spot 25 sx. cmt. 4. Perforate & sque 5. Perforate @ 320' on 5-1/2" x 8-5/8 6. RDMO. Cut off we	work). SEE RULE 1103. F 3550'. MLF. 3550' - 3325', We eze 35 sx. cmt 180 pump 85 sx. cmt. 3" annulas. Leave 11head & anchors,	or Multip OC & ta OO' - . down cmt. (instal	ag. 1700', WOC & 5-1/2" csg. 2 surface on	tag. & circula inside of markers, a	te cmt. to surface 5-1/2" csg., WOC & nd clean location.	tag
13. Describe proposed or compostarting any proposed wor recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque 5. Perforate @ 320' on 5-1/2" x 8-5/8 6. RDMO. Cut off we.	a 3550'. MLF. 3550' - 3325', We have 35 sx. cmt 180, pump 85 sx. cmt. """ annulas. Leave 11head & anchors,	or Multip OC & ta OO' - down cmt. (instal	ag. 1700', WOC & 5-1/2" csg. 2 surface on 11 dry hole	tag. & circula inside of markers, a	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC & and clean location.	tag
13. Describe proposed or compostarting any proposed wor recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque 5. Perforate @ 320' on 5-1/2" x 8-5/8 6. RDMO. Cut off we.	a 3550'. MLF. 3550' - 3325', We have a 35 sx. cmt 180, pump 85 sx. cmt. B' annulas. Leave annulas. Leave annulas. Leave annulas. Leave annulas.	or Multip OC & ta OO' - down cmt. (instal	pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 2 surface on l1 dry hole in lag. 1 dry hole in lag. 1 dry hole in lag. 2 surface on lag. 2 surface on lag. 3 surface on lag. 4 surface on lag. 4 surface on lag. 4 surface on lag. 5 surface on lag. 6 surface on lag. 7 surface on lag. 8 surface on l	tag. & circula inside of markers, a	te cmt. to surface 5-1/2" csg., WOC & nd clean location.	tag
13. Describe proposed or compostarting any proposed wor recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque 5. Perforate @ 320' on 5-1/2" x 8-5/8 6. RDMO. Cut off we.	a 3550'. MLF. 3550' - 3325', We have a 35 sx. cmt 180, pump 85 sx. cmt. B' annulas. Leave annulas. Leave annulas. Leave annulas. Leave annulas.	or Multip OC & ta OO' - down cmt. (instal	pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. 2 surface on l1 dry hole in lag. 1 dry hole in lag. 1 dry hole in lag. 2 surface on lag. 2 surface on lag. 3 surface on lag. 4 surface on lag. 4 surface on lag. 4 surface on lag. 5 surface on lag. 6 surface on lag. 7 surface on lag. 8 surface on l	tag. & circula inside of markers, a	t dates, including estimated date liagram of proposed completion te cmt. to surface 5-1/2" csg., WOC & and clean location.	tag
13. Describe proposed or compostarting any proposed wor recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & sque 5. Perforate @ 320' on 5-1/2" x 8-5/8 6. RDMO. Cut off we.	a 3550'. MLF. 3550' - 3325', We have a series of the ser	or Multip OC & ta OO' - down cmt. (instal	pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. a surface on l1 dry hole in lagent Agent	tag. & circula inside of markers, a	te cmt. to surface 5-1/2" csg., WOC & nd clean location.	tag.
13. Describe proposed or compostarting any proposed wor recompletion. 1. Set 5-1/2" CIBP (2. Circulate hole w. 3. Spot 25 sx. cmt. 4. Perforate & squeety squeety squeety squeety on 5-1/2" x 8-5/8 (6. RDMO. Cut off we. 1. RDMO. Cut off we. 1. RDMO. The squeety	a 3550'. MLF. 3550' - 3325', We have a 35 sx. cmt 180, pump 85 sx. cmt 180, pump 85 sx. cmt. B' annulas. Leave annulas.	or Multip OC & ta OO' down cmt. (instal instal TITLE_A E-mail ac	pertinent details, and le Completions: A lag. 1700', WOC & 5-1/2" csg. a surface on l1 dry hole in lagent Agent	tag. & circula inside of markers, a	te cmt. to surface 5-1/2" csg., WOC & nd clean location. further certify that any pit or belowalternative OCD-approved plan DATE 3/3/05	tag