Office District 1 Energy, Minerals and Natural Resource	Form C-103
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II OH CONGERNATION DIVIGION	т 30-025-33306
District III 1220 South St. Francis Dr	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Phillips, J.R.
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other	13
2. Name of Operator Chevron USA Inc	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
15 Smith Rd, Midland, TX 79705	10. I doi name of Wildeat
4. Well Location	
Unit Letter E: 1700 feet from the North line an	d 940 feet from the East line
Section 6 Township 20-S Range 37-E	
11. Elevation (Show whether DR, RKB, RT, G	R, etc.)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be	attached)
Pit Location: UL E Sect 6 Twp 20S Rng 37E Pit type Steel Depth to Ground	
Distance from nearest surface water Below-grade Tank Location ULSect	TwpRng;
17C^feet from the North line and 940 feet from the East line (Steel Tank)	
	· · · · · · · · · · · · · · · · · · ·
12. Check Appropriate Box to Indicate Nature of No	
	SUBSEQUENT REPORT OF:
	WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	E DRILLING OPNS. ☐ PLUG AND ☐
	—
PULL OR ALTER CASING MULTIPLE CASING TE	ABANDONMENT ST AND
PULL OR ALTER CASING MULTIPLE CASING TE CEMENT JO	ABANDONMENT ST AND
PULL OR ALTER CASING	ABANDONMENT OB
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta	ABANDONMENT ST AND OB Ils, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JO OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion.	ABANDONMENT ST AND OB ils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988. Spot 258x plug 2988-2800 (Furnant 7 RVRS Queen March 11).	ABANDONMENT ST AND OB Lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion CONSERVATION DIVISION MUST
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet) MECOLE 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sy, plug 2400-2200 (R Sat)	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet) MECOLE (BP COLE AS Spot 25sx, plug 2400-2200 (B-Salt)). 4. Spot 25sx, plug 2400-2200 (B-Salt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag.	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet) MECOLE 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sy, plug 2400-2200 (R Sat)	ABANDONMENT ST AND OB Lils, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion CONSERVATION DIVISION MUST
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN DITTION OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet MacCilla Spot 25sx, plug 2988-2800 (Eumont, 7 RVRS Queet MacCilla Spot 25sx, plug 2400-2200 (B-Satt). 4. Spot 25sx, plug 2400-2200 (B-Satt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker.	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet MECOLS 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sx, plug 2400-2200 (B-Salt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker. I hereby certify that the information above is true and complete to the best of my kno grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet MacCilla 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sx, plug 2400-2200 (B-Satt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker. I hereby certify that the information above is true and complete to the best of my kno grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet MECOLS). 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sx, plug 2400-2200 (B-Salt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker. I hereby certify that the information above is true and complete to the best of my kno grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE CASING TE CEMENT JOURN OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet) M5 COL 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sx, plug 2400-2200 (B-Salt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker. I hereby certify that the information above is true and complete to the best of my know grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per SIGNATURE TITLE Con	ABANDONMENT ABAND
PULL OR ALTER CASING MULTIPLE CASING TE CEMENT JOTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @2988, Spot 25sx plug 2988-2800 (Eumont, 7 RVRS Queet MacOll 3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL. 4. Spot 25sx, plug 2400-2200 (B-Salt). 5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag. 6. Spot 30sx Plug 300-Surf (Surf) WOC Tag. 7. Install dry hole marker. I hereby certify that the information above is true and complete to the best of my kno grade tank has been/will be constructed or closed according to NMOCD guidelines , a general per SIGNATURE TITLE Control Type or print name Title Control Type or print name CASING TE CEMENT J. CHERNT J. TITLE Control Casing Tement J. CASING TE CEMENT J. CHERNT J. BE NO. BEGINN TITLE Control Casing Tement J. Title Casing Tement J. Titl	ABANDONMENT ABAND
PULL OR ALTER CASING	ABANDONMENT ABAND

PLUGGING & ABANDONMENT WORKSHEET (STRING CSNG) **OPERATOR** CHEURON USA ILC. LEASENAME PHILLIPS # WELL 13- H SECT TWN RNG 6-E 2-06 37-E E/W L **FROM** 1700 (N)S L 940 FORMATION @ TD BLINEBELL TD: 6000 FORMATION @ PBTD EUMON FT 7 RUES PBTD: MLF QUEEN SIZE SET @ TOC TOC DETERMINED BY 85kg SURFACE 25/2 1150 SURF Ciec @ 1150 INTMED 1 TOC SURF INTMED 2 PROD 5112 ٥٥٥٥ SueF Ciec SIZE TOP BOT TOC DETERMINED BY WrE LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 PERFS 3038 - 3164 INTMED 2 OPENHOLE MLF PROD CIBP 2988 ' 35 CMT * REQUIRED PLUGS DISTRICT I 08888444 PLUG EUMONT, 7 RUES, QUEEN TYPE SACKS DEPTH RUSTLER (ANHYD) PLUG CMINT YATES CIBP @5416 35 CMT EXAMPLES QUEEN GRAYBURG PLUG # 1 OH 25 SXS 9850' BLINEBRY SHOE 50 SXS 8700'-8800 PLUG#2 SAN ANDRES PLUG #3 CIBP/35' 5300 CIBP 25 SXS 5300 CAPITAN REEF PLUG#3 PLUG#4 STUB 50 SXS 4600-4700 BLINEBRY PLUG # 7 RETNR SQZ 200 SXS 400 DELAWARE PLD0## SURF 10 SXS 0-10 BELL CANYON 2988 CHERRY CANYON PLUG #1 CIBP 25 PLUG#2 B.SALT 2400 BRUSSIY CANYON 15 85/85 PLUGES 30 1200 BONE EPRING PLUG # 4 Suef 30 300 OLORIETA PLUG # 5 PLUG # 6 BLINEBRY 7 8 00.19 TUBB PLUGER DRINKARD PLUO 6 9 ABO PLUG # 10 wc PLUGE PENN PLUO # STRAWN PLUG S PLUO # ATOKA WOLROW TD 6000 DEVONIAN

2