## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1625 N French Dr , Hobbs, NM 88240  HOBBS OCD 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-07361
JUN 0 3 2011	5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	7. I was a land of the same of News
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 19
1 Type of Well	8 Well No. 131
Oil Well Gas Well Other Injector	
2 Name of Operator Occidental Permian Ltd.	9 OGRID No 157984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	<del></del>
Unit Letter         L         2310         Feet From The         South         330	Feet From The West Line
Section 19 Township 18-S Range 3	8-E NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3667' DF	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from pegreet surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction	Vialeriai
12. Check Appropriate Box to Indicate Nature of Notice, Report, of NOTICE OF INTENTION TO:	or Other Data BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TENT ON THE MEDICE WORK	· ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	DPNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEN	DPNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEN OTHER. Clean out/plug back/squeeze/acid treat X OTHER:	DPNS. PLUG & ABANDONMENT ENT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEN OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details)	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEN OTHER. Clean out/plug back/squeeze/acid treat X OTHER:	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEN OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed.  1. Kill well. 2. POOH w/injection equipment.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid. 8. Perform scale squeeze.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid.	PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of propose 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid. 8. Perform scale squeeze. 9. Run back in hole with injection equipment.	DPNS. PLUG & ABANDONMENT ENT JOB tes, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed to 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6. Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid. 8. Perform scale squeeze. 9. Run back in hole with injection equipment. 10. Test casing and chart for the NMOCD. 11. Return well to injection.	DPNS. PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any ed completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent deproposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6 Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid. 8. Perform scale squeeze. 9. Run back in hole with injection equipment. 10. Test casing and chart for the NMOCD. 11. Return well to injection.	DPNS. PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any ed completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed to 1. Kill well. 2. POOH w/injection equipment. 3. Clean out to PBTD @4310'. 4. Plug back w/pea gravel to 4175'. Cap with 10' of cement. Tag new PBTD @4165'. 5. Set CICR and squeeze perfs. 6. Test squeeze. 7. Acid treat well w/2000 gal of 15% NEFE HCL acid. 8. Perform scale squeeze. 9. Run back in hole with injection equipment. 10. Test casing and chart for the NMOCD. 11. Return well to injection.	DPNS. PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any and completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completion of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Complet	DPNS. PLUG & ABANDONMENT  ENT JOB  tes, including estimated date of starting any and completion or recompletion.
TEMPORARILY ABANDON	DPNS. PLUG & ABANDONMENT  Tent JOB  Tes, including estimated date of starting any sed completion or recompletion.  The provided completion of the provided c
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING Multiple Completion CASING TEST AND CEM OTHER. Clean out/plug back/squeeze/acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completion of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed work) SEE RULE 1103. For Multiple Complet	DPNS. PLUG & ABANDONMENT  Tent JOB  Tes, including estimated date of starting any sed completion or recompletion.  Test including estimated date of starting any sed completion or recompletion.
TEMPORARILY ABANDON	DPNS. PLUG & ABANDONMENT  Test, including estimated date of starting any ed completion or recompletion.  Description of the completion of