1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals & Natural Resources

Form C-101 May 27, 2004

RECEIVED Submit to appropriate District Office

Oil Conservation Divsiion

1220 S. St. Francis Dr. Santa Fe, NM 87505

SEP 2 0 2005

OCD-AHTEBIA | AMENDED REPORT

APPLIC	CATION	FOR	PER	RMIT	ΓO DR	ILL, RE-H	ENTE	R, DEEPEN,	PLUGRAC	'K OR A	מת	70	NE
1		. (Operate	or Name a	nd Address			,	LEUGDAG	² OGRID N	ımber	20	INE.
OXY USA WTP				р						19246			
P.O. Box 50		land,	TX	79710-	0250				30- 015-	3434	nber S		
35/	rty Code				4	⁵ Propert DXY Bypass		ato			⁶ Well N	١.	
		⁹ Propos	ed Poo	ol 1		on Dypuss	T 30	<u>ace</u>	10 Proposed	Pool 2	1		
Undesigna	ted Malag	a Morr	OW,	West	···	80925							
	γ					⁷ Surface	Loca	tion					
UL or lot no.	Section 16	Townshi	1	Range	Lot. Id			North/South Line	Feet from the	East/West lin	ne	County	у
[16	24S 8		28E	D = 44 =			south	990	west		Edd	<u>ly</u>
UL or lot no.	Section	Townshi		Range	Lot. Id			Different Fro					
	Section	1 O W HSHI	•	Kalige	Lot. Id	n Feet from	i the	North/South Line	Feet from the	East/West li	ne	County	y
					A	dditional V	Vell L	ocation	<u> </u>	<u> </u>			
11 Work Typ			¹² W	ell Type Co	de	13 Cable	-	¹⁴ Lea	se Type Code	15 Grou	ınd Level	Elevation	a .
16 Multi	•		17 pr	G oposed Dep		18 Form	₹		· V-5979		3035	•	
N	0			12900'			row	17 (Contractor N/A		⁰ Spud Da 10/01/		
Depth to ground	water			Ţ	Distance f	rom nearest fresl	n water v	vell	Distance from near			05	
Pit: Liner: Syn	thetic	mi	ls thick	k Clar	y 🗆	Pit Volume		bbls Drilling Meth					
•	op System	_		- 0	, —	THE VOIGING		. —					
	op 0)5:0m			21,		10:	Fresh W			il-based		Gas/Air	<u>- </u>
Hole Si				<u>_</u>				ment Program					
			asing S		Casing weight/foot			Setting Depth Sacks of		nt	Estima	ted TOC	3
17-1/2			3-3/		48#		-	650'	675sx	sur	face-	circu	late
12-1/4	·		9-5/8	}"	36#		 	2700'	755sx	sur	face-	circu	late
8-3/4			7"		26#		 	10000'	1240sx	sur	surface-circulate		late
6-1/4			-1/2	·	11.6#		96	00-12900'	325sx	9600'-circulate		ate	
22 Describe the n	massed areas	num If ah	1		DEFEN				· · · · · · · · · · · · · · · · · · ·				
Describe the blowd	out prevention	program,	is appi , if any	. Use addi	tional shee	N or PLUG BAC is if necessary.	CK, give	the data on the pre-	sent productive zo	ne and propos	ed new p	roducti	ve zone.
						•							
													,
						See Attac	hment						
							į						
23 I hereby certify t	that the inform	nation aive	an abou	ua ia terra a	md1-4	- 4 - 4 - 1		7-					
²³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief. I further certify that the drilling pit will be					13	OIL CO	ONSERVATI	ON DIVI	SION				
constructed according to NMOCD guidelines a general permit, or an (attached) alternative OCD-approved plan					Appro	ved by:							
Signature:					1	<u> </u>		W. GUN					
Printed name: David Stewart					Title:			I SUPE	RVIS	JH			
	. Regulate						Appro	val Date: SEP	2 2 2005 Ex	piration Date	SEF	, 22	200
E-mail Address: 0 Date:	david_ste	wart@ox	Ť										
حراء	(05		Pho		-685-57	17		ions of Approval:		 _			
• • • • • • • • • • • • • • • • • • • •	<u> </u>		L	432	-003-5/	1/	Attach	ed 🔲					ľ

OXY USA WTP LP OXY Bypass 16 State #1 900 FSL 990 FWL SWSW(M) SEC 16 T24S R28E Eddy County, NM State Lease No. V-5979

PROPOSED TD: 12900' TVD

المحار

BOP PROGRAM: 0-650' None

> 650-2700' 13-3/8" 3M annular preventer, to be used as

divertor only.

2700-129001 11" 5M blind pipe rams with 5M

preventer and rotating head below 8500'.

CASING: Surface: 13-3/8" OD 48# H40 ST&C new casing set at 650'

17-1/2" hole

Intermediate: 9-5/8" OD 36# K55 ST&C new casing from 0-2700'

12-1/4" hole

7" OD 26# K55-S95 LT&C new casing from 0-10000' Production:

8-3/4" hole 5100'-K55 4900'-S95

Liner: 4-1/2" OD 11.6# HP-110 LT&C casing @ 9600-12900'

6-1/8" hole

Surface - Circulate cement with 425sx HES Light PP cement with 2% CEMENT: $CaCl_2$ + .25#/sx Flocele followed by 250sx PP cement with 2% $CaCl_2$ + .25#/sx Flocele.

Intermediate - Circulate cement with 555sx IFC with .25#/sx Flocele followed by 200sx PP cement with 2% CaCl2.

Production - DV Tool @ +/- 5000', cement $1^{\rm st}$ stage with $460{\rm sx}$ IFH cement with .1% HR-7 followed by 200sx PP cement. Cement $2^{\rm nd}$ stage with 380sx IFH cement with .25#/sx Flocele followed by 200sx PP cement.

Liner - Cement with 325sx Super H cement with .5% HR-344 + .4% CFR-3 + 5#/sx Gilsonite + 1#/sx salt + .2% HR-7

Note: Cement volumes may need to be adjusted to hole caliper.

MUD: 0-650' Fresh water/native mud. Lime for pH control (9-10). Paper for seepage.

Wt 8.7-9.2 ppg, Vis 32-34 sec

650-2700' Fresh/*Brine water. Lime for pH control (10.0-

10.5). Paper for seepage.

Wt 8.3-9.0/10.0-10.1ppg, Vis 28-29 sec

*Fresh water will be used unless chlorides in

the mud system increases to 20000PPM.

2700-89001 Fresh water. Lime for pH control(9-9.5). Paper

for seepage.

Wt 8.3-8.5 ppg, Vis 28-29 sec

8900-10900' Cut brine. Lime for pH control (10-10.5).

Wt 9.6-10.0 ppg, Vis 28-29sec

10900-12900' Mud up with an Duo Vis/Flo Trol mud system.

Wt 9.6-10.0ppg, Vis 32-36sec, WL<10cc

SPACING UNIT: S/2

ESTIMATED FORMATION TOPS: Silver Bullet-1 - 3001521789 - 16-24-28 Morrow-12282' Atoka-11660' Strawn-11408' Wolfcamp-9392' Bone Spring-6123' Delaware-2580'

SPUD DATE: 10/1/05

ARCH SURVEY: N/A

DIRECTIONS TO LOCATION: From the junction of CR 716 & CR 720, go south on CR 716 for 0.7 miles to a 2-track road. Then east on the 2-track road for 500' to the proposed location.

WELLSITE LAYOUT: V-Door - South Pits - East

SURFACE OWNER: Pardue Ltd Co., P.O. Box 2018, Carlsbad, NM 88221

SURFACE LESSEE: N/A

LEASE RESPONSIBILTY STATEMENT: N/A

PRIVATE SURFACE OWNER'S AGREEMENT OR STATEMENT THAT AN AGREEMENT CONCERNING SURFACE USE: $\mathrm{N/A}$

MEAREST RESIDENCE OR OTHER STRUCTURE: .2 miles to the southwest

SOURCE OF CONSTRUCTION MATERIALS - Caliche for surfacing the well pad will be obtained from a private pit located in the SE corner of Sec 17.

H2S CONTINGENCY PLAN: 9/19/05

PIT PERMIT: 9/19/05

DIRECTIONAL SURVEY PLAN: N/A

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT II 811 South First, Artesia, NM 88210

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102 Revised March 17, 1999

Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT III 1000 Rio Brazos Rd., Axtec, NM 87410

DISTRICT IV

2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, New Mexico 87504-2088

☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number Pool Code		Pool Name		
30-015-	80925	Undesignated Malaga Morrow, West		
Property Code	Prope	Well Number		
	OXY BYPASS	"16" STATE	1	
OGRID No.	Operator Name		Elevation	
192463	OXY USA WTP L	imited Partnership	3035'	

Surface Location


UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
М	16	24 S	28 E		900	SOUTH	990	WEST	EDDY


Bottom Hole Location If Different From Surface

UL or lot No.	Section Town	ship Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acres 320	Joint or Infill	Consolidation	Code Or	der No.				

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

		· · · · · · · · · · · · · · · · · · ·	
	 		OPERATOR CERTIFICATION I hereby certify the the information contained herein is true and complete to the best of my knowledge and belief.
	 	 	Signature David Stevent
	 		David Stewart Printed Name Sr. Regulatory Analyst Title
	 		SURVEYOR CERTIFICATION I hereby certify that the well location shown
	 		on this plat was plotted from field notes of actual surveys made by me or under my supervison, and that the same is true and correct to the best of my belief.
990'	Lat - N32*12'47.0" Long - W104*05'52.8"	 	Date Surveyed Signature of Selating Professional Surveyor 7907 28 129 120 120 120 120 120 120 120
·.006 —			Certification Signal Jones 7977 Basin Survey S





Choke Manifold

SECTION 16, TOWNSHIP 24 SOUTH, RANGE 28 EAST, N.M.P.M., NEW MEXICO. EDDY COUNTY, FARMERS 2-TRACK ROAD 150' NORTH OFF SET 3035.3 0 150' WEST OGX RESOURCES, L.L.C. 3035.8 BYPASS "16" STATE #1 ELEV. = 3035'0 LAT.-N 3272'47.0" LONG.-W 104"05'52.8" 150' EAST OFF SET 3033.9 150' SOUTH OFF SET 3035.3' 100 100 200 FEET SCALE: 1" = 100' DIRECTIONS TO LOCATION: FROM THE JUNCTION OF CO. RD. 716 & CO. RD. 720, GO SOUTH ON 716 FOR 0.7 MILE TO 2-TRACK ROAD; THENCE EAST ON 2-TRACK ROAD FOR 500 FEET TO PROPOSED OGX RESOURCES, L.L.C. REF: BYPASS "16" STATE #1 / Well Pad Topo LEASE ROAD. BYPASS "16" STATE #1 LOCATED 900' FROM THE SOUTH LINE AND 990' FROM THE WEST LINE OF SECTION 16, TOWNSHIP 24 SOUTH, RANGE 28 EAST,


BASIN SURVEYS P.O. BOX 1786 - HOBBS, NEW MEXICO

Disk: KJG #8 - 5375A.DWG

W.O. Number: 5375 Drawn By: K. GOAD Date: 05-25-2005

N.M.P.M., EDDY COUNTY, NEW MEXICO.

Sheet Sheets Survey Date: 05-25-2005




BYPASS "16" STATE #1
900' FSL & 990' FWL
Section 16, Township 24 South, Range 28 East,
N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 — Office (505) 392-3074 — Fax basinsurveys.com

W .O. Number:	5375AA - KJG CD#5				
Survey Date:	05-25-2005				
Scale: 1" = 2000'					
Date: 05-25-	-2005				

OGX RESOURCES L.L.C.



BYPASS "16" STATE #1
900' FSL & 990' FWL
Section 16, Township 24 South, Range 28 East,
N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 - Office (505) 392-3074 - Fax basinsurveys.com

W.O. Number:	5375AA - KJG CD#5				
Survey Date:	05-25-2005				
Scale: 1" = 2000'					
Date: 05-25-	-2005				

OGX RESOURCES L.L.C. OXY USA WTP Limited Partnership PO Box 50250 Midland, TX 79710

Hydrogen Sulfide (H2S) Contingency Plan

For

OXY Bypass 16 State No. 1 900 ft FSL, 990 ft FWL Sec 16, T24S, R28E Eddy County, NM

And

McVay Drilling Co. Rig No. 8

TABLE OF CONTENTS

<u>ITEM</u>	<u>PAGE</u>
PREFACE	3
LOCATION MAP	4
RIG SKETCH	. 5
EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES	6
SPECIFIC EMERGENCY GUIDANCE - H2S Release - Well Control	
PUBLIC RELATIONS	13
PHONE CONTACTS - OP DOWNHOLE SERVICES GROUP	14
EMERGENCY PERSONELL NOTIFICATION NUMBERS	15
PHONE CONTACTS - OP PRODUCTION AND PLANT PERSONNEL	16
PHONE CONTACTS - OP HES PERSONNEL	16

PREFACE

An effective and viable Contingency Plan is intended to provide prior planning and guidance in responding to emergency incidents. The primary considerations in its development are protection of personnel, the public, company and public property, and the environment.


Although the plan addresses varied emergency situations which may occur, it recognizes that flexibility and the use of the organization's knowledge and experience is critical to safe resolution of emergency incidents. Response actions outlined in the plan provide a framework, which may be placed into operation without confusion. These actions should promote quick and decisive actions during the critical initial period and immediately following an emergency. As the response progresses, additional guidelines and procedures may need to be implemented as the situation dictates. In addition, all emergency incidents must be properly reported per the Oxy Incident Reporting and Notification Policy, state and federal requirements, etc.

This Contingency Plan is intended for use on Oxy Downhole Services Group projects and the operations within their area of responsibility, such as drilling, critical well work, etc.

A copy of the Plan shall be maintained in the Top Dog House, Rig Managers trailer, and Company Representative's trailer if applicable.




OXY USA WTP Bypass 16 St No. 1 Lat. 32°12'47.0"N Long. 104°05'52.8"W



Loving N.M.

From the junction of County Rd. 716 and County Rd. 720 go south on Co. Rd. 716 for 0.7 miles to a 2 track road. Go east on 2 track road for 500 feet to location.



EMERGENCY RESPONSE ACTIVATION AND GENERAL RESPONSIBILITIES

Activation of the Emergency Action Plan

- A. In the event of any emergency situation, all personnel on location should first ensure that the following items are initiated. After that, they should refer to the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document for further responsibilities:
 - 1. Notify the senior ranking contract representative on site.

2. Notify Oxy representative in charge.

3. Notify civil authorities if the Oxy Representative can not be contacted and the situation dictates.

4. Perform rescue and first aid as required (without jeopardizing additional personnel).

General Responsibilities

Oxy Permian Personnel:

- A. Operations Specialist: The Oxy Drilling/Critical Well Servicing Operations Specialist or contract personnel serving in that capacity will serve as Operations Chief Officer for all emergency incidents. The Operations Chief Officer is responsible for:
 - 1. Notification to the Downhole Services Team Leader of the incident occurrence.
 - 2. Notification to the local RMT/PMT leader of the incident occurrence, and the need for the designated local RMT/PMT Incident Commander to act in that capacity for the response effort.
 - 3. Sole control of all tactical activities directed toward reducing the immediate hazard, establishing situational control and restoring the operations to a non-emergency state.
- B. Local RMT/PMT Designated Incident Commander: The Oxy local RMT/PMT Designated Incident Commander will serve as the overall Incident Commander for the drilling or critical well servicing emergency incident. The Incident Commander is responsible for:
 - 1. Coordinating with the Downhole Services Team Leader for notification to the Oxy Crisis Management team of the incident occurrence.
 - 2. Establishing and managing the overall incident command structure and response from inception through restoration of normal activities in the area.
- C. Downhole Services HES Tech: The Downhole Services HES Tech (or his designate) is responsible for reporting to the incident as soon as reasonably possible, to provide support to the response effort as required by the Operations Chief Officer or the Incident Commander.

Contract Drilling Personnel will immediately report to their assigned stations and perform their duties as outlined in the appropriate Specific Emergency Guidance sections on pages ten (10) through twelve (12) in this document.

Other Contractor Personnel will report to the safe briefing area to assist Oxy personnel and civil authorities as requested when it is safe to do so and if they have been adequately trained in their assigned duties.

Civil Authorities (Law Enforcement, Fire, and EMS) will be responsible for:

- 1. Establishing membership in the Unified Incident Command.
- 2. As directed by the Incident Commander and the Unified Command, control site access, re-route traffic, and provide escort services for response personnel.
- 3. Perform all fire control activities in coordination with the Unified Command.
- 4. Initiate public evacuation plans as instructed by the Incident Commander.
- 5. Perform rescue or recovery activities with coordination from the Unified Command.
- 6. Provide medical assistance as dictated by the situation at hand.

H2S RELEASE

The following procedures and responsibilities will be implemented on activation of the H2S siren and lights.

All Personnel:

1. On alarm, don escape unit (if available) and report to upwind briefing area.

Rig Manager/Tool Pusher:

- 1. Check that all personnel are accounted for and their condition.
- 2. Administer or arrange for first aid treatment, and /or call EMTs as needed.
- 3. Identify two people best suited to secure well and perform rescue, and instruct them to don SCBA.
- 4. Notify Contractor management and Oxy Representative.
- 5. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.

Two People Responsible For Shut-in and Rescue:

- 1. Don SCBA and acquire tools to secure well and perform rescue, i.e., wrenches, retrieval ropes, etc.
- 2. Utilize the buddy system to secure well and perform rescue(s).
- 3. Return to the briefing area and stand by for further instructions.

All Other Personnel:

1. Isolate the area and prevent entry by other persons into the 100 ppm ROE. Additionally the first responder(s) must evacuate any public places encompassed by the 100 ppm ROE. First responder(s) must take care not to injure themselves during this operation. Company and/or local officials must be contacted to aid in this operation. Evacuation of the public should be beyond the 100 ppm ROE.

Oxy Representative:

- 1. Remain at the briefing area, assess and monitor personnel and overall situation for hazards or conditions that might warrant a change in the action plan.
- 2. Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Training

There will be an initial training session prior to encountering a known or probable H2S zone (within 3 days or 500 feet) and weekly H2S and well control drills for all personnel in each crew. The initial training session shall include a review of the site specific H2S Drilling Operations Plan and the Public Protection Plan (Contingency Plan). This plan shall be available at the well site. All personnel will be required to carry documentation that they have received the proper training.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO2). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police shall be the Incident Command of any major release.

Characteristics of H2S and SO2

Common Name	Chemical Formula	Specific Gravity	Threshold Limit	Hazardous Limit	Lethal Concentration
Hydrogen Sulfide	H ₂ S	1.189 Air = 1	10 ppm	100 ppm	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air = 1	2 ppm	N/A	1000 ppm

Contacting Authorities

Oxy Permian personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as; type and volume of release, wind direction, location of release, etc. Be prepared with all information available. The following call list of essential and potential responders has been prepared for use during a release. This response plan must be in coordination with the State of New Mexico's 'Hazardous Materials Emergency Response Plan' (HMER).

WELL CONTROL

The following procedures will be implemented when a loss of primary control is indicated. Indicators of loss of primary control are flow from the well, an increase in pit volume, or when the drilling fluid used to fill the hole on trips is less than the calculated pipe displacement volume. The emergency signal for well control procedures will be a single long blast of the rig air horn.

Kick While Drilling - Procedures And Responsibilities

Driller:

- 1. Stop the rotary and hoist the kelly above the rotary table.
- 2. Stop the mud pump(s).
- 3. Check for flow.
- 4. If flowing, sound the alarm immediately.
- 5. Ensure that all crew members fill their responsibilities to secure the well.
- 6. Record drill pipe and casing shut-in pressures and pit volume increase and begin kill sheet.

Derrickman:

- 1. Go to BOP/choke manifold area.
- 2. Open choke line valve on BOP.
- 3. Signal to Floorman #1 that the choke line is open.
- 4. Close chokes after annular or pipe rams are closed.
- 5. Record shut-in casing pressure and pit volume increase.
- 6. Report readings and observations to Driller.
- 7. Verify actual mud weight in suction pit and report to Driller.
- 8. Be readily available as required for additional tasks.

Floorman # 1:

- 1. Go to accumulator control station and await signal from Derrickman.
- 2. Close annular preventer and HCR on signal (if available, if not then close pipe rams).
- 3. Record accumulator pressures and check for leaks in the BOP or accumulator system.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman # 2:

- 1. Start water on motor exhausts.
- 2. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 3. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 4. Report to Driller, and be readily available as required for additional tasks.

Floorman #3:

1. Stand-by with Driller, and be readily available as required for additional tasks.

Tool Pusher/Rig Manager:

- 1. Notify Oxy Representative and report to rig floor.
- 2. Review and verify all pertinent information.
- 3. Communicate information to Oxy Representative, and confer on an action plan.
- 4. Finalize well control worksheets, calculations and preparatory work for action plan.
- 5. Initiate and ensure the action plan is carried out.
- 6. Communicate any changes in well or site conditions, or any indications that the action plan needs to be revised to the Oxy representative.

Oxy Representative:

1. Notify Operation Specialists or Team Leader and RMT Leader or Local Incident Commander, and Police, Fire Department, or other local emergency services as required.

Kick While Tripping - Procedures and Responsibilities

Driller:

- 1. Sound the alarm immediately when pipe displacement volume is less than 75% of calculated.
- 2. Position the upper tool joint just above rotary table and set slips.
- 3. Check for flow.
- 4. Ensure that all crew members fill their responsibilities to secure the well.
- 5. Record drill pipe and casing shut-in pressures and pit volume increase, and begin kill sheets.

<u>Derrickman:</u> (same as while drilling)

Floor Man # 1:

- 1. Install full opening valve (with help from Floorman #2) in top drill string connection.
- 2. Tighten valve with make up tongs.
- 3. Go to accumulator control station and await signal from Derrickman.
- 4. Close annular preventer and HCR valve on signal (if available, if not then close pipe rams).
- 5. Record accumulator pressures and check for leaks in the BOP and accumulator system.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floor Man # 2:

- 1. Assist installing full opening valve in drill string.
- 2. Position back-up tongs for valve make-up.
- 3. Start water on motor exhausts.
- 4. Notify Contractor Tool Pusher or Rig Manager of well control situation.
- 5. Check location for ignition sources and extinguish or turn off, and stop any welding in progress.
- 6. Report to Driller, and be readily available as required for additional tasks.

Floorman # 3, Rig Manager/Tool Pusher, and Oxy Representative: (same as while drilling)

PUBLIC RELATIONS

Oxy recognizes that the news media have a legitimate interest in incidents at Oxy facilities that could affect the public. It is to the company's benefit to cooperate with the news media when incidents occur because these media are our best liaison with the public.

Our objective is to see that all reports of any emergency are factual and represent the company's position fairly and accurately. Cooperation with news media representatives is the most reliable guarantee that this objective will be met.

All contract and Oxy employees are instructed <u>NOT</u> to make any statement to the media concerning the emergency incident. If a media representative contacts any employee, they should refer them to the designated Emergency Command Center where they should contact the Incident Commander or his designated relief for any information concerning the incident.

OXY PERMIAN DOWNHOLE SERVICES GROUP

	LOCATION	OFFICE»	HOME	CEL	PAGER
Manager Operations					
Hardesty, Steve	Midland	432-685-5880	432/694-6441	713-560-8095	entra da la la establica de la companya de la comp
Team Leader				1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
Pennington, Randy	Midland	432-685-5684	432/689-7642	432-556-0207	713-312-8186
			Toledo Bend =	318-590-2349	
Operations Specialist					
Fleming, Joe	Midland	432-685-5858	432/699-0875	432-425-6075	432-498-3281
Ray, Fred	Midland	432-685-5683	432/362-2857	432-661-3893	432-499-3432
HES Tech				1.5	
Thompson, Don	Midland	432-685-5719	432/684-3900	432-556-1505	(1) Remiser (1) 10 (1)

Emergency Notification Numbers

Public Authorities						
New Mexico State Police	Artesia	505/746-2704				
New Mexico State Police	Carlsbad	505/885-3137				
New Mexico State Police	Hobbs	505/392-5588				
Eddy County Sheriff's Office	Artesia	505/746-2704				
Eddy County Sheriff's Office	Carlsbad	505/887-7551				
Lea County Sheriff's Office	Hobbs	505/393-2515				
Local Emergency Planning Center	Eddy County	505/887-9511				
Local Emergency Planning Center	Lea County	505/397-9231				
New Mexico Oil & Gas Commission	Artesia	505/748-1283				
New Mexico Oil & Gas Commission	Hobbs	505/393-6161				
NM Emergency Response Center	Hobbs	505/827-9222				

Emen	gency Services	
Fire Fighting, Rescue, Ambulance, Police	Artesia	911
Fire Fighting, Rescue, Ambulance, Police	Carlsbad	911
Fire Fighting, Rescue, Ambulance, Police	Hobbs	911
Flight For Life	Lubbock	806/743-9911
Aerocare	Lubbock	806/7478923
Med Flight Air Ambulance	Albuquerque	505/842-4433

Other En	mergency Services	
Boots and Coots		1/800-256-9688
Cudd Pressure Control	Midland	432/699-0139
B.J. Services	Artesia	505/746-3569
Halliburton	Artesia	505/746-2757

OXY Permian Production and Plant Personnel OXY Permian Crisis Team Hotline Notification (713) 935-7210

LOCATION	OFFICE	FAX	CELL	PAGER
Houston	(281) 552-1147	(281) 552-1484	(713) 560-8038	
Midland	(432) 685-5802	(432) 685-5930	(432) 556-5016	
		Caroni (1571)		
Midland	(432)			
	685-5600			
LOCATION	OFFICE	FAX	CELL	PAGER
				2 (Albert 1997)
Hobbs	(505)	(505) 397-2671	(505) 390-6426	(505) 370-6836
	Midland Midland LOCATION	Houston (281) 552-1147 Midland (432) 685-5802 Midland (432) 685-5600 LOCATION OFFICE	Houston (281) (281) 552-1147 552-1484 Midland (432) (432) 685-5802 685-5930 Midland (432) 685-5600 FICE FAX	Houston

PERSON	LOCATION	OFFICE	FAX	CELL!	PAGER
HES Coordinators & Area of Resp	onsibility				
Frontier: Ricky Tyler	िर्शिक्षींभागर्थ	((4(32)) 685-5707	(432) 685-5742	((4(32)) 668-5790	
HES Techs & Area of Responsibil	lty.			of the second	
Hobbs RMT: Steve Bishop	Hobbs	(505) 397-8251	(505) 397-8204	(505) 390-4784	(877) 339-1954- 1118#
Frontier-New Mexico: Rick Kerby	Hobbs	(505) 393-2174	(505) 393-2671	(505) 390-8639	(505) 370-6527