2001011	State of New Me		Form C-103
	Energy, Minerals and Natural Resources		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-21671	
DI W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Fra	ncis Dr.	STATE STEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			OG-5373
SUNDRY NOTICES ANI	REPORTS ON WELLS	3	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO D			
DIFFERENT RESERVOIR. USE *APPLICATION FO PROPOSALS.)	R PERMIT" (FORM C-101) F	OK SUCH	State HT "B" SWD
1. Type of Well:			8. Well Number
Oil Well Gas Well Other			
2. Name of Operator			9. OGRID Number
		·	020989
3. Address of Operator			10. Pool name or Wildcat
P. O. Box 863, Kermit, Texas 79745			Upper Penn
4. Well Location			
	a	a mala sa	
Unit Letter D : 700 feet	from the North line	and <u>580</u> fee	et from the <u>West</u> line
Section 31	Township 12S	Range 34E	NMPM Lea County
	vation (Show whether Di		
11. Ele	Valion (Dhow whether Di	i, Iuid, III, OII, eic.	
Pit or Below-grade Tank Application (For pit or belo	w-grade tank closures, a fori	n C-144 must be attache	<u>ed)</u>
Pit Location: UL Sect Twp Rng	Pit type 1	Depth to Groundwater	Distance from nearest fresh water well
Distance from nearest surface waterBelo			· · · · · · · ·
feet from the line and feet			,
reer nom thenne andnee	Trom thenac		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
in one or in propi			
NOTICE OF INTENTI		SUB	SEQUENT REPORT OF:
			SEQUENT REPORT OF:
NOTICE OF INTENTI	AND ABANDON 🛛	SUB REMEDIAL WOR	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG	AND ABANDON ⊠ GEPLANS □	SUE REMEDIAL WOR COMMENCE DR	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING MULTI	AND ABANDON 🛛	SUB REMEDIAL WOR	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PULL OR ALTER CASING MULTICOMP	AND ABANDON 🖾 GE PLANS 🔲 PLE 🔲	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTI COMP OTHER:	AND ABANDON 🛛 GE PLANS 🔲 PLE LETION	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PULL OR ALTER CASING MULTI COMPOTHER: 13. Describe proposed or completed ope	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEE	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion.	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top.	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' – 35' cement on top. Circ 9.5# mud - POOH	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top.	AND ABANDON GE PLANS PLE LETION crations. (Clearly state all	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING MULTICOMPOTHER: 13. Describe proposed or completed operof starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @	AND ABANDON GE PLANS PLE LETION GRAPH STATE AND A	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER: Pertinent details, ar ple Completions: A	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PLUG PULL OR ALTER CASING MULTI COMPOTHER: 13. Describe proposed or completed operof starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surface	AND ABANDON GE PLANS PLE LETION GRAPH STATE AND ASSESSED A	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PLUG PLUG PULL OR ALTER CASING MULTICOMP OTHER: 13. Describe proposed or completed operof starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfater I hereby certify that the information above is	AND ABANDON GE PLANS PLE LETION GRAPH STATE GRAPH ST	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PLUG PLUG PULL OR ALTER CASING MULTICOMP OTHER: 13. Describe proposed or completed operof starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfater I hereby certify that the information above is	AND ABANDON GE PLANS PLE LETION GRAPH STATE GRAPH ST	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PLUG PLUG PULL OR ALTER CASING MULTICOMP OTHER: 13. Describe proposed or completed operof starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfater I hereby certify that the information above is	AND ABANDON GE PLANS PLE LETION GRAPH STATE AND ACE — install dry hole mar true and complete to the ording to NMOCD guidelines Complete to the comple	REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surface in the surf	AND ABANDON GE PLANS PLE LETION GRAPH STATE AND ACE — install dry hole mar true and complete to the ording to NMOCD guidelines Complete to the comple	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A ker. best of my knowled , a general permit	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHANG PULL OR ALTER CASING MULTI COMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfa I hereby certify that the information above is grade tank has been/will be constructed or closed acc SIGNATURE	AND ABANDON GE PLANS PLE LETION GRAPH State all GRULE 1103. For Multi So' in & 50' out of stub. ACC — install dry hole mar true and complete to the ording to NMOCD guidelines Solve TITL	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A ker. best of my knowled , a general permit	SEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG PLUG PLUG PLUG PLUG PULL OR ALTER CASING MULTI COMPOTHER: 13. Describe proposed or completed ope of starting any proposed work). SEI or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfa I hereby certify that the information above is grade tank has been/will be constructed or closed acc SIGNATURE	AND ABANDON GE PLANS PLE LETION GRAND G	COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, ar ple Completions: A ker. best of my knowled , a general permit	BSEQUENT REPORT OF: RK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG. TEMPORARILY ABANDON CHANGE PULL OR ALTER CASING MULTICOMP OTHER: 13. Describe proposed or completed ope of starting any proposed work). SET or recompletion. Set CIBP @ 9600' - 35' cement on top. Circ 9.5# mud - POOH Spot 25 sx 6000 - 5900' Spot 25 sx @ 4200 - 4100' & tag Pull 5-1/2" casing @ ± 2000'. Spot 40 sx @ Spot 35 sx @ 387 - 287'. Spot 10 sx @ surfate the surface of the surfa	AND ABANDON GE PLANS PLE LETION GRAND G	REMEDIAL WORK COMMENCE DR CASING TEST A CEMENT JOB OTHER: pertinent details, an ple Completions: A ker. best of my knowled,	SEQUENT REPORT OF: RK

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.