

Enervest Operating, LLC
1001 Fannin St., Suite 800
Houston, TX 77002

RE: Abandonment Reclamations and Remediation of Spills on Various Wells and Facilities

Findings:

Britt 13 (3002506000), the access road has had some traffic. This may have been the rancher or the pipeline company getting to and from a pipeline riser. We may not be able to do anything but allow the access to return to a two track road. The location has some excess caliche, though not hard packed. We can continue to monitor and see how it revegetates. The location is currently void of any vegetation, may not have been seeded yet. There is trash that needs to be removed from the outer edges of the location. There is some minor amounts of concrete on the western edge of the pad, couple of pipe joints in the NW corner, and two pipeline signs and posts on the east side of the location. Remove all debris, cement and pipe. The dry hole marker does not have the federal lease number. Need to add.

Britt 10 (3002505997), has some grasses growing on both the location and access. There has been some travel on the access, mostly recent. There is excess caliche on the road and pad. Maybe some oil contaminants around the DHM. Need to remove debris, to include a length of scrap pipe on the west side of the access, and a length of drilling cable on the east side of the access. Need to remove the two well signs and wood debris on the pad. There are some minor amounts of concrete from the reserve pit on the south side of the location, when addressing the excess caliche, spread some of the good clean oils over this area. The location needs to be contoured.

Britt 4 (3002505992), has a spill area, just northwest of the pad. It appears to have been an old battery site. The oil contaminants will need to be remediated. There are no indicators of salt contaminants. We can probably address by blending and tilling under, then bringing the good topsoil to surface and seed. If any backfill is needed, you can use any of the good caliche from the reclamations.

Britt 11 (3002505998) was abandoned 1/18/11 and has a reclamation due date of 7/17/11. Reclamation will be as per Notice of Intent to Abandon, Conditions of Approval. In this case remove any/all contaminants, trash and debris, poly flow lines, etc. Strip and remove all caliche, restoring the native soils to the surface. This should be contoured to blend with the surrounding landscape, ripped and seeded with the appropriate seed mix (private land, utilize the ranchers preferred seed mix). When reclaiming the location, remove the barricade to the #3 well and leave a two track access to the pipeline riser on the #3.

Britt 3 (3002505991), has some excess caliche, but also has some vegetation coming in and can be watched for a couple of years to see how the site progresses toward final abandonment. Do need to remove the well sign, debris, to include the yellow anchor marker, thread protectors, concrete, scrap pipe, poly line, wood debris, and some minor oil impact at the front end of the old caliche pit. There is a length of smaller pipe adjacent to the meter run that needs to be removed.

Britt A 6-1 (3002505937), is currently in the process of being reclaimed. The inspection found the location looking good. Issues identified significant amounts of oil contaminants off the location. These areas are to be remediated to a point the contaminants do not pose a threat to groundwater or in the restoration of the surface. We can probably get by with blending and tilling, and ultimately flipping.

There is a concrete slab and a second concrete feature that needs to be removed and/or disposed of on the north side of the location. There is a length of half buried barrels (looks like barrels, just longer) on the east side of the pad and some minor trash and debris off the location that needs to be removed.

Britt A 6-5 (3002505941), is a producing well. The location has a large concrete slab that should be removed as it is not functional for a pumping unit. There is also an area to south of the location that has been impacted by oil that needs to be remediated and/or removed.

Britt A-6 Tank Battery, has significant oil impacted areas to the east and to the west of the facility. These areas appear to be old disposal pits. It looks like the old pit areas were covered with clean material that revegetated, but due to wind erosion, has exposed hydrocarbons in low laying areas. Due to the size of the impacted area we will need plans for delineation and remediation of the two areas.

Britt A 6-2 (3002505937), is a producing well. There has been a spill off the location to the west. This area needs to be remediated and/or removed. The other issue would be the need for counterweight guards on the pumping unit.

If you have questions, please contact Jim Amos at 505-234-5909.

J. Amos
7/8/11