(August 2007) JAN 192(BUREAU OF LAND MANAGEM HOBSUNDER NOTICES AND REPORTS C Do not use this form for proposals to drill abandoned well. Use Form 3160-3 (APD) for	I625 N. Fr Hobbs, N ENT ON WELLS or to re-enter an	ench M 88	240 OM	RM APPROVED B No 1004-0137 res July 31, 2010
SUBMIT IN TRIPLICATE – Other instruction	ons on page 2.		7. If Unit of CA/Agreem	ent, Name and/or No.
1. Type of Well ☐ Gas Well ☐ Other		-	8. Well Name and No.	
2. Name of Operator Ridgeway Arizona Oil Corporation			9. API Well No. /	
3a. Address 3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area	
200 N. Loraine Suite 1440 Midland TX. 79701 432.687.0303			Chaveroo-San Andres	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) O-29-07S-33E 660 FSL 1980 FEL			11. Country or Parish, State Roosevelt Co. NM	
12. CHECK THE APPROPRIATE BOX(ES) TO	O INDICATE NATURE OF	F NOTIC	E, REPORT OR OTHER	R DATA
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent Activitize Alter Casing Casing Repair	Deepen [] Fracture Treat [] New Construction	Recla	uction (Start/Resume) Water Shut-Off umation Well Integrity mplete Other	
Subsequent Report	Plug and Abandon	=	orarily Abandon	
Final Abandonment Notice . Convert to Injection	Plug Back	Water	Disposal	
Attach the Bond under which the work will be performed or provide the following completion of the involved operations. If the operation results testing has been completed. Final Abandonment Notices must be filed or determined that the site is ready for final inspection.) Perfs - 4288-4406 - Csng-4.5 to 4453 ft Tubing 2.375 @ 4098 ft - w/- Workover Plan MIRU pulling unit POOH w/all downhole equipment - rods/pump/tubing RIH w/pkr - set @ 4188' +/- (100 ft. above top perf) - Pressure to 500 p If MIT fails, POOH w/pkr - spot casing leak/leaks - squeeze and drill ou If casing integrity is good - RIH w/RBP to set @ 4322' to attempt to sho RIH w/tubing - SN depth @ - 4260' +/- to perform swab test - if tests go If well does not test - POOH w/tubing - retrieve bridge plug Pick up work string and RIH w/CIBP set @ 4188' +/- and POOH w/WS Atthis point assecond sundrynotic casil bogeutmitted to add perfs uph Acidize and Frac - Swab test well APPROVED FOR	s in a multiple completion or nly after all requirements, in 4.5 pkr @ 4108 ft. psi for MIT ut - Perform MIT ut off water from lower Sa ood - RIH w/pump/rods a	r recompl ncluding r an Andre nd put o	etion in a new interval, a eclamation, have been c S	Form 3160-4 must be filed once
ENDING APR 1 2 2011	,		FOR REC	ORD ONLY
14. I hereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>)				
Andy Chalker	Title Operations	Manage	r	
Signature Andy Mightis	Date 12/20/2010) 		
	Date 12/20/2010			

Ì

、 、 、

•

.

 $\left| \right\rangle$