Submit 1 Copy To Appropriate District Office State of New District I Energy, Minerals and 1625 N. French Dr., Hobbs, NM 88240 HOBBS OF CONSERVAT District II 1301 W Grand Ave., Artesia, NM 88210 District III 1220 South St. 1000 Rio Brazos Rd , Aztec, NM 87410 1220 South St. District IV 1220 S. St. Francis Dr., Santa Fe, NM	Natural ResourcesOctober 13, 2009ION DIVISIONWELL API NO.Francis Dr.5. Indicate Type of LeaseSTATEFEE
SUNDRY NOTI DESERVED REPORTS ON WI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1 PROPOSALS.) 1. Type of Well: Oil Well Gas Well A Other	DR PLUG BACK TO A
2. Name of Operator OXY USA Inc.	9. OGRID Number 16696
3. Address of Operator P.O. Box 50250 Midland, TX 79710 10. Pool name or Wildcat Antelope Ridge Morrow	
4. Well Location Unit Letter <u>L</u> : 2000 feet from the <u>south</u> line and <u>860</u> feet from the <u>west</u> line	
Section 3 Township 24S Range 34E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3537 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE V V V	
OTHER:	OTHER: Set CIBP, RunCIT & TA
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
7/15/11 MIRU. Get ready to pull tubing. SD till Monday.	
7/18/11 Bleed well down and pick up on tubing string, had 2 7/8" tubing instead of 2 3/8", WO pipe rams, NU BOP, start to POOH w/ tbg	
7/19/11 POOH w/ tbg. RIH w/ CIBP & set @ 12,863'	
7/20/11 Circulate packer fluid. Pressure up to 700# for 10 min. Held good	
7/21/11 Could not do integrity test because the well has to be flanged up just as it will be when you leave. Begin pulling and laying down 2 7/8" tubing. Lay down 423 Jts 2 7/8" tubing. Close well in. SDON	
7/22/11 Finish laying down tubing. Nipple down BOP. Flange up well head. Load casing and work out air. Run chart @	
560# for 35min, Held OK. Close well in. RDM	
Spud Date: Rig Relea	se Date: This Approval of Temporary 22-2015 Abandonment Expires
I hereby certify that the information above is true and complete to	he best of my knowledge and belief.
1 det	Regulatory AdvisorDATEDATE
Type or print nameDavid Stewart E-mail add	dress: _david_stewart@oxy.com PHONE: _432-685-5717
5	
APPROVED BY	

,

AUG 1 5 2011





Rec MidRey, Blid 11