Submit I Copy To Appropriate Dist	nct Office	State of N	ew Mexico			For	m C-103	
<u>District I</u> - (575) 393-6161	Energy,	Minerals ar	nd Natural Resources		N. N.O.	Revised J	uly 18,2013	
District II - (575) 748-1283	5 N. FTENCH DT., HODDS, N.W. 88240				WELL API NO. 30.025.20195			
811 S. First St., Artesia, NM 88210				5. Indicate Type of Lease				
<u>Disrtict III - (</u> 505) 334-6178	440	1220 South S	St. Francis Dr.	STA	ATE $\square$	FEI	E 🗸	
1000 Rio Brazos Rd. Aztec, NM 87- <u>District IV - (505)</u> 476-3460	410	G . F	NN 6 07 5 0 5		il & Gas Lea			
1220 S. St. Francis Dr., Santa Fe, N	M 87505	Santa Fe,	NM 87505	o. State O	n & Oas Lea	sc No.		
	DRY NOTICES AND REPO	RTS ON WEI	LS	7 Lease N	Name or Unit	Agreement	Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT					Crown			
RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					8. Well Number			
1. Type of Well: Oil Well 🗸 Gas Well 🗌 Other					8. Well Number 01			
2. Name of Operator					9. OGRID Numer			
	Apache Corporati	on		873				
3. Address of Operator	·			10. Pool Name or Wildcat				
	s Airpark Lane, Ste. 300	0, Midland,	TX 79705	House; Blinebry, S/House; Tubb				
4. Well Location	_							
Unit Letter	B : 330	feet from th		2310	feet from t		ine	
Section	Township	20 S	Range 38E DR, RKB,RT, GR, etc.)	NMPM		County	Lea	
	11. Elevation (S		543' <b>GR</b>					
	12. Check Appropriate Bo	ox To Indica	te Nature of Notice, Re	port, or O	ther Data			
NOTICE	OF INTENTION TO:		SUBS	SEQUENT	REPORT	OF:		
PERFORM REMEDIAL WOR	RK PLUG AND ABA	NDON 🔀	REMEDIAL WORK		ALTERING	G CASING		
TEMPORARILY ABANDON	CHANGE PLAN	_	COMMENCE DRILLING	OPNS.	PANDA			
PULL OR ALTER CASING	☐ MULTIPLE COM	1PL ∐	CASING/CEMENT JOB		J			
DOWNHOLE COMMINGLE	님							
CLOSED-LOOP SYSTEM OTHER:			OTHER:					
13. Describe proposed or	completed operations (C	<u>ات</u> اearly state :		give nerti	nent dates i	including e	ctimated	
date of starting any propos		-	_			_		
proposed completion or re		.13.7.14 1	TAC. To Multiple Col	iipicuons.	Attach wei	ibore diagi	ani oi	
proposed completion of re	completion.							
Anache Corporation pro	oposes to P&A the above	e mentioned	d well by the attached	procedur	e Aclose	d loon sys	tem will	
	Ill fluids from this wellbo		_	-			Mill Will	
be used for a	iii iidida iioiii tiiia weiibo	ne and disp	osed of required by C	CD Rule	19.15.17.14	HINAC.		
				S	ee Attac	ned		
				- Condi	tions of	Approva	i	
Spud Date:			Rig Release Date:	Condi	uono oi		576 -	
*** 1 10 1 1 1					11. 0			
I hereby certify that the in	formation above is true an	d complete t	o the best of my knowle	edge and b	eliet.			
SIGNATURE	Guinn Burks	TITLE	Sr. Reclamation Fo	oreman	DATE	10/8/	20	
_		_			- 			
Type or print name	Guinn Burks	E-mail add.	guinn.burks@apache	corp.com	PHONE:	432-556	-9143	
For State Use Only	. A							
APPROVED BY:	MALL FINE	TITLE	Compliance Officer	٨	DATE	10/27/20		
Conditions of Approval (if a	<del>~~~~</del>	_	Computance Officer	A		10121120		



**LEASE NAME** Crown WELL# API# 30.025.20195 COUNTY LEA

	WELL BORE INFO.	
0		
706		
1413	11" Hole 8 5/8" 24 # @ 1587' w/ 550 sx, CIRC to surf	
2119		
2826		
3532		
4238	Csg leak @ 4413'-4445' / sqzd w/ 150 sx cmt	
4945		
5651	Perf Holes to sqz	
6358	Perf Holes to sqz TOC @ 5860'	
7064	7 7/8" Hole 4 1/2" 9.5 & 11.6# @ 7064' w/ 250 sx, TOC @ 5860'	

PBTD @ 6950' TD @ 7064'

Perfs @ 6039'-6104' Perfs @ 6140'-6195'

Perfs @ 6664'-6750'

CIBP @ 6950' (unknown if cmt)
Perfs @ 6973'-7004'



LEASE NAME	Crown
WELL#	1
API#	30.025.20195
COUNTY	LEA

#### PROPOSED PROCEDURE

PBTD @ 6950

TD @ 7064'

5. PUH & perf @ 300' & sqz/CIRC 90 sx Class "C" cmt from 300' to surf. (Water Board & Surf Plug)

4. PUH & perf @ 1637' & sqz 60 sx Class "C" cmt from 1637'-1437', WOC/TAG (Surf Shoe & Top of Salt)

3. PUH & perf @ 3155' & sqz 125 sx Class "C" cmt from 3155'-2704', WOC/TAG (7 Rvrs & Base of Salt)

2. PUH & perf @ 4317' & sqz 60 sx Class "C" cmt from 4317'-4117', WOC/TAG (San Andres)

1. MIRU P&A rig. RIH w/ tbg & verify CIBP @ 6950', CIRC w/MLF & spot 100 sx Class "C" cmt from 6950'-5540', WOC/TAG (Drinkard & Glorieta)

Perfs @ 6039'-6104' Perfs @ 6140'-6195'

Perfs @ 6664'-6750'

CIBP @ 6950' (unknown if cmt)

Perfs @ 6973'-7004'

0

706

1413

11" Hole 8 5/8" 24 # @ 1587' w/ 550 sx, CIRC to surf

2119

2826

3532

4238

Csg leak @ 4413'-4445' / sqzd w/ 150 sx cmt

4945

Perf holes to sqz @ 5210'

5651

Perf holes to sqz @ 5810' TOC @ 5860'

6358

7064

7 7/8" Hole 4 1/2" 9.5 & 11.6# @ 7064' w/ 250 sx, TOC @ 5860'

# CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify **NMOCD District Office I** (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

## Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing

#### DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

## SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)