Office Energy, Minerals and Natural Resources Octobe			
District I Energy, Minerals and Natural Resources Octobe	n C-103		
1025 11, 1101011 51., 110105, 1111 005 10	October 13, 2009 WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210  OIL CONSERVATION DIVISION  30-025-41725  5. Indicate Type of Lease			
District III 1220 South St. Francis Dr.	1		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV  Santa Fe, NM 87505  Santa Fe, NM 87505  6. State Oil & Gas Lease No.	<u> </u>		
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement	Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	N		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  North Monument G/SA Unit Blk.	5		
1. Type of well: Oil well 🔼 Gas well 📋	8. Well Number 399		
2. Name of Operator  9. OGRID Number 873			
Apache Corp.  3. Address of Operator  10. Pool name or Wildcat			
P O box Drawer D Monument NM 88265  Eunice Monument G/SA			
4. Well Location			
Unit LetterM_:_1180feet from theS line and205feet from theW	line		
	unty		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12 Olyala America Daniel III de Nationa Charles Depart on Other Date			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CAS	_		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A			
DULL OR ALTER CAONO DE MULTIPLE COMPLETE DE CACINO/CEMENT IOR DE			
PULL OR ALTER CASING			
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   DOWNHOLE COMMINGLE			
OTHER: OTHER: TA Retest	$\boxtimes$		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti	mated date		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estions of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram	⊠ mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti	⊠ mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estions of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.	⊠ mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estions of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.	mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estion of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.	⊠ mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estions of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.	mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estion of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.	⊠ mated date of		
OTHER:  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estion of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.	mated date of		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.	of		
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.	of NSION		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTERMENTATION Approval of TA EXPIRES: 10/29/2	nsion 21		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTERMINENT APPROVICTION  Well needs to be PLUGGED OR RETERMINENT APPROVICTION	NSION 21 ETURNET		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTERMINENT Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RETERMINENT APPROPRICTION.	NSION 21 ETURNET		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTERMINENTE Approval of TA EXPIRES: 10/29/2 Well needs to be PLUGGED OR RE	NSION 21 ETURNET		
DOWNHOLE COMMINGLE  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS-EXTE Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RE to PRODUCTION BY THE DATE STATED ABOVE:	NSION 21 ETURNET		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTERMINENT Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RETERMINENT APPROPRICTION.	NSION 21 ETURNET		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTE Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RETO TO THE DATE STATED ABOVE:  I hereby certify that the information above is true and complete to the best of my knowledge and belief.	NSION 21 ETURNED		
DOWNHOLE COMMINGLE  OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS-EXTE Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RE to PRODUCTION BY THE DATE STATED ABOVE:	NSION 21 ETURNED		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estion of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart. Release pressure. Request TA extension.  FINAL TA STATUS- EXTENTED APPROVAL OF TA EXPIRES: 10/29/Well needs to be PLUGGED OR RETORN BY THE DATE STATED ABOVE:  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE ALL MARKETS DATE 10/29/2020	NSION 21 ETURNET		
OTHER:  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esting of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTE Approval of TA EXPIRES: 10/29/Well needs to be PLUGGED OR RETO TO THE DATE STATED ABOVE:  I hereby certify that the information above is true and complete to the best of my knowledge and belief.	NSION 21 ETURNET		
DOWNHOLE COMMINGLE  OTHER:  TA Retest  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including esti of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram proposed completion or recompletion.  MIRU Sunset Hot Oiler.  Perform Bradenhead test.  Pressure up on casing to 560# for 32 minutes ending pressure 555#. Record test on chart.  Release pressure. Request TA extension.  FINAL TA STATUS- EXTE Approval of TA EXPIRES: 10/29// Well needs to be PLUGGED OR RE to PRODUCTION BY THE DATE STATED ABOVE:  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE A B B TITLE Foreman DATE 10/29/2020  Type or print name Joel Sisk E-mail address: _joel.sisk@apachecorp.com_PHONE: _575-441-0793	NSION 21 ETURNED		

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

		BRADENHEAD TE	or unither	45	, \		
Apache Coro					30-825-41725		
Apache Corp.					Well No.		
NM GSAU					_1	99	
UL - Lot Section To	orn≤bip Range	Surface Locat	iOD N/S Line	al Astarba N. A		_	
	residing Russe	1186	5	Zo5	EAV Line	County Leg	
		Well Statu	S			A THE RESIDENCE OF THE PROPERTY OF THE PROPERT	
YES TA'D WELL NO YES SHUT-IN NO INJ SWD (D				PRODUCER DATE			
110	I TES	jo Ini	SWD OIL	) <del></del>	BAS 10-	-29-20	
		OBSERVED I	DATA				
	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)	Prod Csng	(E)Tubing	
Pressure	4				20#		
Flow Characteristics							
Puff	(A)\ N	Y/N	Y/ 1	Ţ	(Y) N	CO2	
Steady Flow	Y /(B)	Y/N	YII	1	Y-/(N)	WTRGAS	
Surges	Y (W)	Y/N	Y / ?		Y /(N)	Type of field	
Down to nothing	N (V) N	Y/N	Y/1		M (A)	injected for Waterflood X	
Gas or Oil	Ø/N	Y/N	Y/		Y /(y/	\$\$Ugicar	
Water	Y(N)	Y/N	Y7	Ŋ	(Y) N		
acora e e e e e e e e e e e e e e e e e e e				. <del>•</del> •	•		
Remarks - Picase state for	each string (A.B.C.D.E) per	tinent information regarding b	leed down or continu	ious build up if a	pplies.		
Signature . John	1 Sich	tinent information regarding b	leed down or continu	OIL	CONSERVAT	ION DIVISION	
Signature . John Printed name: John	/ Liek LL Sisk	tinent information regarding b	iced down or continu	OIL (	CONSERVAT	CON DIVISION	
Signature . John Printed name: John Title Fore	Lieb LI Sisk man		leed down or continu	OIL	CONSERVAT	CION DIVISION	
Signature . John Printed name: John	Lieb LI Sisk man	checorp com	ieed down or continu	OIL (	CONSERVAT	TION DIVISION	

