Submit 3 Copies To Appropriate District Office HOBBS OCD Finergy Minerals and Natural Resources	Form C-103
District 1	May 27, 2004 WELL API NO.
District II 1301 W Grand Ave, Artesia, NM 88240 District III 1302 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	30-041-10041
1301 W Grand Ave, Artesia, NM 86240 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Milnesand Unit
1. Type of Well: Oil Well Gas Well D Other	8. Well No. 131
2. Name of Operator	9. OGRID Number
EOR Operating Company	257420 10. Pool name or Wildcat
3. Address of Operator 200 N. Loraine, Ste. 1440. Midland, TX 79701	Milnesand, San Andres
4. Well Location	Winnesand, San Andres
Unit Letter B : 660 feet from the N line and 198	0 feet from the E line
Section 7 Township 08-S Range 35-E	NMPM County Roosevelt
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
	The state of the s
Pit or Below-grade Tank Application or Closure	1
Pit type Depth to Groundwater Distance from nearest fresh water well	
	ls; Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, F	Report or Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE CASING/CEMENT	LING OPNS. 🔲 PAND A 🔻
COMPLETION	
OTHER: OTHER:	
OTHER: OTHER:	re pertinent dates, including estimated date of ellbore diagram of proposed completion or (2000'. closed well in.) mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 95'. Set packer @ 1290'. Sqz'd 40 sx escker @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut
OTHER: OTHER:	re pertinent dates, including estimated date of ellbore diagram of proposed completion or (2000'. closed well in.) mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 95'. Set packer @ 1290'. Sqz'd 40 sx eacker @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 18/15/11 MIRU plugging equipment. ND wellhead. NU BOP. RIH w/ tbg & CIBP to 2/08/16/11 RIH w/ CIBP to 4513'. Set CIBP. Pressured up to 500 psi. Circulated hole we on top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 3040'. Pressured up to 500 psi. Circulated hole we on top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 150 cement. (3100-2738). POH w/ tbg. WOC. TAgged plug @ 2743'. Perf'd csg @ 150 cement. & displaced to 1480'. 18/17/11 Tagged plug @ 1492'. POH. Perf'd csg. @ 455'. ND BOP and wellhead. Set predict of circulated to surface. WOC. topped off surface with 25 sx cement. Rigged down moved 08/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 1 off deadmen. Cleaned location. Moved off.	re pertinent dates, including estimated date of ellbore diagram of proposed completion or (200'. closed well in.) mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 95'. Set packer @ 1290'. Sqz'd 40 sx eacker @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut ore only. pending receipt (Well Plugging) eb Page under /ocd.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 15. MIRU plugging equipment. ND wellhead. NU BOP. RIH w/ tbg & CIBP to 20. (198/16/11 RIH w/ CIBP to 4513'. Set CIBP. Pressured up to 500 psi. Circulated hole woon top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 3040'. Pressured to 1480'. (198/17/11 Tagged plug @ 1492'. POH. Perf'd csg. @ 455'. ND BOP and wellhead. Set proceed to 1480'. (198/17/11 Tagged plug @ 1492'. POH. Perf'd csg. @ 455'. ND BOP and wellhead. Set proceed to 1480'. (198/17/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 198/23/11 Moved in backhoe and well backhoe	re pertinent dates, including estimated date of ellbore diagram of proposed completion or (200'. closed well in.) mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 95'. Set packer @ 1290'. Sqz'd 40 sx eacker @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut ore only. pending receipt (Well Plugging) eb Page under /ocd.
OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. 15. MIRU plugging equipment. ND wellhead. NU BOP. RIH w/ tbg & CIBP to 2 08/15/11 MIRU plugging equipment. ND wellhead. NU BOP. RIH w/ tbg & CIBP to 2 08/16/11 RIH w/ CIBP to 4513'. Set CIBP. Pressured up to 500 psi. Circulated hole w/ on top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 3040'. Pressu 25 sx cement. (3100-2738). POH w/ tbg. WOC. Tagged plug @ 2743'. Perf'd csg @ 150 cement & displaced to 1480'. 15. O8/17/11 Tagged plug @ 1492'. POH. Perf'd csg. @ 455'. ND BOP and wellhead. Set pcirculated to surface. WOC. topped off surface with 25 sx cement. Rigged down moved 08/23/11. Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 1 off deadmen. Cleaned location. Moved off. 1 hereby certify that the information above is true and complete to the best of my knowledge and belie has been/will be constructed or closed acgording to NMOCD guidelines, a general permit or an SIGNATURE. 1 hereby certify that the information above is true and complete to the best of my knowledge and belie has been/will be constructed or closed acgording to NMOCD guidelines, a general permit or an SIGNATURE.	re pertinent dates, including estimated date of ellbore diagram of proposed completion or 2000'. closed well in. mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 25'. Set packer @ 1290'. Sqz'd 40 sx packer @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut ore only. pending receipt Well Plugging) eb Page under /ocd. f. I further certify that any pit or below-grade tank in (attached) alternative OCD-approved plan
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: The proposed or completed operations. (Clearly state all pertinent details, and give starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach we recompletion. O8/15/11 MIRU plugging equipment. ND wellhead. NU BOP. RIH w/ tbg & CIBP to 20/08/16/11 RIH w/ CIBP to 4513'. Set CIBP. Pressured up to 500 psi. Circulated hole won top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 3040'. Pressured up to 500 psi. Circulated hole won top of Plug. POH to 3100'. WOC. Tagged plug @ 4137'. Perf'd csg @ 15th cement & displaced to 1480'. O8/17/11 Tagged plug @ 1492'. POH. Perf'd csg. @ 455'. ND BOP and wellhead. Set prescrulated to surface. WOC. topped off surface with 25 sx cement. Rigged down moved 08/23/11 Moved in backhoe and welder. Dug out cellar. Cut off wellhead. Welded on 1 off deadmen. Cleaned location. Moved off. Approved for plugging of well be Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD W Forms, www.cmnrd.state.nm.us Thereby certify that the information above is true and complete to the best of my knowledge and belie has been/will be constructed or closed acgording to NMOCD guidelines , a general permit or a significant of the constructed or closed acgording to NMOCD guidelines . TITLE . Significant construction of the constructed or closed acgording to NMOCD guidelines . TITLE . Significant construction of the constructed or closed acgording to NMOCD guidelines . TITLE . Significant construction of the construction of	re pertinent dates, including estimated date of ellbore diagram of proposed completion or 2000'. closed well in. mud laiden fluid. Spotted 25 sx cement red up on csg. RIH to 3100' and spotted 95'. Set packer @ 1290'. Sqz'd 40 sx eacker @ 30'. Sqz'd 150 sx cement and d off. Dry Hole Marker. Backfilled cellar. Cut ore only. pending receipt well Plugging) eb Page under /ocd. f. I further certify that any pit or below-grade tank in (attached) alternative OCD-approved plan DATE

AUG 3 0 2011