Submit I Copy To Appropriate District HOBBS OCD State of New Mexico	Form C-103		
District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.		
1625 N French Dr., Hobbs, NM 88240 <u>District II</u> - (575) 748-1283 SFP 9 Διθω	30-025-33920		
District II - (575) 748-1283 SEP 2 6120CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE		
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Monument "12" STATE		
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 8		
2. Name of Operator	9. OGRID Number		
Chevron USA INC	4323		
3. Address of Operator 15 Smith Road Midland, TX, 79705	10. Pool name or Wildcat Monument:Drinkard, NE		
4. Well Location			
Unit Letter <u>N</u> : <u>419</u> feet from the <u>South</u> line and <u>1801</u> feet from the <u>West l</u>	ine		
Section 12 Township 19S Range <u>36E</u> NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)		
3728' GL			
10 Charle Announced Day to Indiante Mature of Mati	Boundary Other Data		
12. Check Appropriate Box to Indicate Nature of Notic	e, report of Other Data		
	JBSEQUENT REPORT OF:		
	COMMENCE DRILLING OPNS. P AND A		
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of		
This well Monument '12' State #8, was recently perforated and acidized on 6738'-6804'(Details: 6738'-6742', 6744'-6750', 6782'-6786', 6788'-6799			
traces of oil seen after swabbing, and a decision was made to abandon t			
(48'above top of perf) followed by dumping 35' of cement on top. We plan to do a 30 minute MIT test after setting			
the CIBP and putting 35' of cement on top(Planned for Sep 23, 2011).(A call was made to the NMOCD Sep/23/2011			
to inform them of our intention, this is the supporting documentation).			
The C-103 form with the proposed Well Bore Diagram, will be emailed to ElidioL.Gonzales@state.nm.us, these			
document will also be faxed to (575) 393-0720 as mentioned on the OCD website.			
Conditions of Approval: Notify OCD district office			
24 hours prior to running the TA pressure test.			
Spud Date: Rig Release Date:			
I hereby certify that the information above is true and complete to the best of my knowl	edge and belief.		
SIGNATURE Attons TITLE EUNICE Produ	chin Fing. DATE Sep/23/2011		
	0 1		
Type or print name E-mail address:	PHONE:		
APPROVED BY: Company TITLE STAFF M			
$\sim O$	SEP 2 6 2011		

and the second second

.

Monument 12 State #8 Monument Field T19S, R36E, Sec.12, 1801' FWL 419' FSL Job: Supplemental procedure for temporarily plug and abandon (T&A)

Procedure:

Notify NMOCD of intent to temporarily plug and abandon the Monument '12' State #8

NMOCD phone: 575.393.6161

1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland office well files and computer databases as of June 7, 2011. Verify what is in the hole with the well file in the Eunice field office. Discuss with WEO Engineer, Workover Rep, OS, ALCR, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.

Ensure tubing elevators are callipered prior to PU tubing

NOTE: Currently there is a 5-1/2" HD compression packer set @ 6,638'. Fluid level is static and no traces of oil are seen during swabbing operations.

- 2. Kill well if needed. TOOH standing back 2-7/8" L-80 6.5# WS and LD 5-1/2" HD compression packer.
- 3. Perform JSA for wireline operations. MI & RU wireline truck. NU 5K lubricator on top of BOP. PU 5-1/2" CIBP and RIH on wireline.
- 4. Set CIBP at 6,690' (48' above top of Drinkard perfs).

NOTE: Use CCL (Wedge Dia-Log, Inc.) CBL dated June 5, 1997 for depth correlation.

- 5. Pressure test casing to 500 psi for 5 minutes. If casing does not hold pressure, discuss with Remedial Engineer.
- 6. Run wireline bailer with cement dumping 35' of cement (~ 4.7 cubic feet) on top of CIBP.
- 7. POOH wireline. RD&MO wireline unit.

- 8. Pressure test casing with 500 psi for 30 minutes (chart-recorded). If casing does not hold pressure, discuss with Remedial Engineer.
- 9. TIH with 2-7/8" WS OE, tag cement and record cement depth.
- 10. Circulate 160 bbls of packer fluid (1% concentration of corrosion inhibitor additive) around well. POOH & LD 2-7/8" WS.
- 11. ND BOP, NU 7-1/16" x 2-7/8" B-1 flange tubing head w/ 2" valve on top. RD & MO pulling unit.
- 12. Perform MIT with an NMOCD representative on-site. Give NMOCD 48 hours notice before performing MIT. Pressure test as per MIT requirements. Turn in any charts and documentation to Denise Pinkerton (JLBM@chevron.com)

Contacts:

Engineering:	Mohmmad Siddiqui	<u>Office</u> 432-687-7727	<u>Cell</u> 630-930-1189
	Denise Wann	432-687-7380	432-238-4238
Geology:	Caleb Osborn	432-687-7436	432-254-0056
D&C:	Hector Cantu		432-557-1464
Operations:	Bobby Hill Danny Lovell Shannon Richardson	575-394-1245 575-394-1242 575-394-1222	575-631-9108 575-390-0866 575-631-9049
Peak Completions:	Randy Good		575-631-7543
Schlumberger:	Hobbs Office	575-393-6186	
Baker Petrolite:	Dexter Nichols	-	575-390-4356

.



.

,