Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr , Hobbs, NM 88240 HOBBS OCD	WELL API NO.
District II . 1301 W Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-04120
District III SFP 3 0 2011 1220 South St. Francis Dr	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aziec, Nivi 8/410 Sonto Eo, NIM 97505	STATE FEE S
1220 S. St. Francis Dr. Santa Fe. NM	6. State Oil & Gas Lease No.
87505 RECEIVED	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA: Unit Blk 13
PROPOSALS)	8. Well Number
1. Type of Well: Oil Well Gas Well Other	5
2. Name of Operator	9. OGRID Number
Apache Corporation	873
3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705	Eunice Monument; G/SA
4. Well Location	
Unit Letter <u>E</u> : <u>1980'</u> feet from the <u>N</u> line and	feet from the <u>W</u> line
Section 35 Township 19S Range 36E NMPM	County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3636' DF	
Pit or Below-grade Tank Application □ or Closure □	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance	e from nearest surface waterN/A
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Constru	uction Material
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check rippropriate Box to indicate return of reduce,	Report of Other Bata
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RK ALTERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DE	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER: drill out & add Plugs	
	l i
	d give pertinent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764* 	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 	
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 	tach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75/kx85/kx12. Cut off wellhead and anchors. Clean location. Install P&A marker.	tach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker.	rach wellbore diagram of proposed completion Cap well off w/3sx cmt. RDMO
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75/xx85/xx12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv	cach wellbore diagram of proposed completion Cap well off w/ 3sx cmt. RDMO
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv	cach wellbore diagram of proposed completion Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Younder bond is retained pending receipt
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv	cach wellbore diagram of proposed completion Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Younder bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at COT Well Plugging)
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv	cach wellbore diagram of proposed completion Cap well off w/ 3sx cmt. RDMO
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in7%x88%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approve Liability of C.103 which m Forms, we have the surface in the surfa	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. I under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under reww.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in7%x8%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approved Liability of C-103 which means of the surface in th	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. If under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under sww.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' − Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt − Tag @ 2,320'. Perf @ 1,295' − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' − Circ 175sx cmt to surface in75/6x85/6x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approve Liability of C-103 which meroms, we have certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ 1.	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. If under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under sww.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg – Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' – Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt – Tag @ 2,320'. Perf @ 1,295' – Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' – Circ 175sx cmt to surface in7%x8%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approved Liability of C-103 which means of the surface in th	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. If under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under sww.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764′ 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764′ − Tag @ 3,281′. Perf @ 2,529′ 9/19/11Sqz 75sx cmt − Tag @ 2,320′. Perf @ 1,295′ − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164′. Perf @ 272′ − Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv Liability of C-102 which m Forms, v I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ SIGNATURE TITLE P&A Tech	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. y under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under www.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/23/11
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' − Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt − Tag @ 2,320'. Perf @ 1,295' − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' − Circ 175sx cmt to surface in7%x88%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approve Liability of C-103 Which m Forms, we have detailed that has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURE TITLE P&A Tech Type or print name: Greg Bryant E-mail address:	cach wellbore diagram of proposed completion Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Younder bond is retained pending receipt Gubsequent Report of Well Plugging) ay be found at OCD Web Page under Seww.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attor recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764′ 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764′ − Tag @ 3,281′. Perf @ 2,529′ 9/19/11Sqz 75sx cmt − Tag @ 2,320′. Perf @ 1,295′ − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164′. Perf @ 272′ − Circ 175sx cmt to surface in75%x85%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approv Liability of C-102 which m Forms, v I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ SIGNATURE TITLE P&A Tech	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. y under bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under www.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/23/11
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' − Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt − Tag @ 2,320'. Perf @ 1,295' − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' − Circ 175sx cmt to surface in7%x8%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approvate Liability of C-102 which m Forms, which m Forms, which m shows been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ SIGNATURE TITLE P&A Tech Type or print name: Greg Bryant E-mail address: For State Use Only	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Toucher bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under (www.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/23/11 Telephone No. 432-563-3355
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' − Tag @ 3,281'. Perf @ 2,529' 9/19/11Tag TOC @ 1,164'. Perf @ 272' − Circ 175sx cmt to surface in7%x8%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Labelity of C-103 which m Forms, w I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit □ SIGNATURE TITLE P&A Tech Type or print name: Greg Bryant E-mail address: For State Use Only APPROVED B	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Younder bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under or www.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/23/11 Telephone No. 432-563-3355
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion. 9/15/11MIRU. RIH Tbg − Tag @ 3,764' 9/16/11Circ hole w/ MLF. Spot 70sx cmt @ 3,764' − Tag @ 3,281'. Perf @ 2,529' 9/19/11Sqz 75sx cmt − Tag @ 2,320'. Perf @ 1,295' − Sqz 75sx cmt. 9/20/11Tag TOC @ 1,164'. Perf @ 272' − Circ 175sx cmt to surface in7%x8%x12. Cut off wellhead and anchors. Clean location. Install P&A marker. Approvate Liability of C-102 which m Forms, which m Forms, which m shows been/will be constructed or closed according to NMOCD guidelines ⋈, a general permit □ SIGNATURE TITLE P&A Tech Type or print name: Greg Bryant E-mail address: For State Use Only	Cap well off w/ 3sx cmt. RDMO ed for plugging of well bore only. Toucher bond is retained pending receipt (Subsequent Report of Well Plugging) ay be found at OCD Web Page under (www.cmard.state.nm.us/ocd. e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/23/11 Telephone No. 432-563-3355