Spikmut I Copy To Appropriate District State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W Grand Ave, Artesia, NM 8840BBS OCOLL CONSERVATION DIVISION	WELL API NO. 30-025-29133
1301 W Grand Ave, Artesia, NM 8 10 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 CT 20 2011 Santa Fe, NM 87505	STATE S FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	LG-1543
SUNDRY NO REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State DW
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8. Well Number (
2. Name of Operator	9. OGRID Number
OXY USA WTP LP 3. Address of Operator	192463 10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	
4. Well Location	Mescaleno Escape Bone Sprins
Unit Letter M: 990 feet from the South line and	feet from thewestline
Section 12 Township 185 Range 33 8	
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)
Lolo' GR	
12. Check Appropriate Box to Indicate Nature of Noti	ica Papart or Other Data
12. Check Appropriate Box to indicate Nature of Noti	ice, Report of Other Data
	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	
	DRILLING OPNS. PANDA / 🔼
PULL OR ALTER CASING MULTIPLE COMPL CASING/CENDOWNHOLE COMMINGLE	WENT JOB
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 	e Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 	e Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 	e Completions: Attach wellbore diagram of 3208', circ hole w/ 10# MLF, spot
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cm 	2 Completions: Attach wellbore diagram of 2 3208', circ hole w/ 10# MLF, spot 2 mt w/ 2% CaCl2, PUH, WOC, RIH &
 Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 	2 Completions: Attach wellbore diagram of 2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC, RIH &
 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface 	e Completions: Attach wellbore diagram of 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & DBOP, top off csg, RDPU.
 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface 	2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & b. NDBOP, top off csg, RDPU.
 13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approv. Liability of Cx10.	e Completions: Attach wellbore diagram of 2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & DBOP, top off csg, RDPU. The ed for plugging of well bore only. The ed for plugging of well bore only.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approviate the surface of C-10.	2 3208', circ hole w/ 10# MLF, spot 2 3208', circ hole w/ 10# MLF, spot 2 3208', circ hole w/ 10# MLF, spot 3 tw/ 2% CaCl2, PUH, WOC. RIH & 4. NDBOP, top off csg, RDPU. 3 (Subsequent Report of Well Plugging) 3 (Subsequent Report of Well Plugging) 3 av be found at OCD Web Page under
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approviately and the surface of C-10.	e Completions: Attach wellbore diagram of 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & DBOP, top off csg, RDPU.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approviate the completion of C-10.	2 3208', circ hole w/ 10# MLF, spot 2 3208', circ hole w/ 10# MLF, spot 2 3208', circ hole w/ 10# MLF, spot 3 tw/ 2% CaCl2, PUH, WOC. RIH & 4. NDBOP, top off csg, RDPU. 3 (Subsequent Report of Well Plugging) 3 (Subsequent Report of Well Plugging) 3 be found at OCD Web Page under
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approvint Liability of C-10. Rig Release Date: Rig Release Date:	2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & b. NDBOP, top off csg, RDPU. Tred for plugging of well bore only. by under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approvint Liability of C-10. Rig Release Date: Rig Release Date:	2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & b. NDBOP, top off csg, RDPU. Tred for plugging of well bore only. by under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approving Liability of C-10. Rig Release Date: Approving Liability of C-10. Which is Forms,	2 3208', circ hole w/ 10# MLF, spot 1 tw / 2% CaCl2, PUH, WOC. RIH & 2. NDBOP, top off csg, RDPU. 1 ted for plugging of well bore only. 1 ty under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) 1 may be found at OCD Web Page under 2 www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approving Liability of C-10. Rig Release Date: Approving Liability of C-10. Which is Forms,	2 3208', circ hole w/ 10# MLF, spot 1 th w/ 2% CaCl2, PUH, WOC. RIH & 2. NDBOP, top off csg, RDPU. 1 the spot of the spot only. 2 the spot of well bore only. 3 (Subsequent Report of Well Plugging) 3 may be found at OCD Web Page under 3 www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approv Liability of C-10. Spud Date: Rig Release Date: Approv Liability of C-10. Whitch in Forms, I hereby certify that the information above is true and complete to the best of my know SIGNATURE TITLERegulatory Advis	2 3208', circ hole w/ 10# MLF, spot 1 w/ 2% CaCl2, PUH, WOC. RIH & 2. NDBOP, top off csg, RDPU. 1 red for plugging of well bore only. 2 y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) 2 may be found at OCD Web Page under 3 www.cmnrd.state.nm.us/ocd. 2 Pledge and belief. 2 DATE 10 (19(1))
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approvint Liability of C-10. Spud Date: Rig Release Date: Approvint Spud Date: TitleRegulatory Advis Type or print nameDavid Stewart, E-mail addressdavid_stewart E-mail addressdavid_stewart	2 3208', circ hole w/ 10# MLF, spot 1 tw / 2% CaCl2, PUH, WOC. RIH & 2. NDBOP, top off csg, RDPU. 1 ted for plugging of well bore only. 1 ty under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) 1 may be found at OCD Web Page under 2 www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approving Liability of C-10 Whitch in Forms,	2 3208', circ hole w/ 10# MLF, spot at w/ 2% CaCl2, PUH, WOC. RIH & b. NDBOP, top off csg, RDPU. The defor plugging of well bore only. ay under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) may be found at OCD Web Page under www.cmnrd.state.nm.us/ocd. Pledge and belief. DATE LO (19() art@oxy.com PHONE: _432-685-5717
13. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion. 10/14/2011 MIRU, unseat pump, POOH w/ rods and pump. 10/17/2011 NDWH, NUBOP, Rel TAC, POOH w. tbg. RIH & set CIBP @ 50sx CL C cmt, PUH, WOC. 10/18/2011 RIH w/ & tag cmt @ 2735', PUH to 1343', spot 25sx CL C cmt tag cmt @ 1112', PUH to 437', circ 50sx CL C cmt to surface Approv Liability of C-10. Spud Date: Rig Release Date: Approv Liability of C-10. Whitch in Forms, I hereby certify that the information above is true and complete to the best of my know SIGNATURE TITLERegulatory Advis	2 3208', circ hole w/ 10# MLF, spot 1 w/ 2% CaCl2, PUH, WOC. RIH & 2. NDBOP, top off csg, RDPU. 1 red for plugging of well bore only. 2 y under bond is retained pending receipt 3 (Subsequent Report of Well Plugging) 2 may be found at OCD Web Page under 3 www.cmnrd.state.nm.us/ocd. 2 Pledge and belief. 2 DATE 10 (19(1))