•	New Moxico on Content Variation, Distinct I 1625 N. French Drive									
× .[Form 3160-5 (August 1999) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000						
		5. Lease Serial No. NMNM89889								
	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name				
	SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well					 If Unit or CA/Agreement, Name and/or No. 103145X 				
	X Oil Well □ Gas Well □	Well 🗌 Other				8. Well Name and No. WTYSRU 943				
	2. Name of Operator Chesapeake Operating, Inc.					9. API Well No. 30-025-33004				
	3a. Address 3b. Phone No P. O. Box 11050 Midland TX 79702-8050 (432)687-2			iclude area code) 2	10. Field and Pool, or Exploratory Area					
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2310' FSL & 990' FEL, Sec. 9, T20S, T33E			West Teas Yates-7 Rivers 11. County or Parish, State Lea New Mexico						
	12. CHECK AI	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
	TYPE OF SUBMISSION	TYPE OF ACTION								
	X Notice of Intent	AcidizeAlter Casing	DeepenFracture Treat	Production (StaReclamation	urt/ Resume)	Water Shut-Off Well Integrity				
	Subsequent Report	Casing Repair	New Construction	•	X.	Other Pre Workover				
	Final Abandonment Notice	Change PlansConvert to Injection	 Plug and Aband Plug Back 	on 🗌 Temporarily Al						
	13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)									
	OBJECTIVE: MOVE ANI	/	1234567891077 12 12 12							
	Procedure, per the attach	ed.			118293037	KIPP 2005 Received Hobbs OCD Color Hobbs				
	14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Brenda Coffman Regulatory Analyst									
	Stenative Drenda Jaman			Date 04/05/2005						
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
0	Approved by GREIG. AGD.	DAVID R. GLAM		Title	Date	APR 0 6 2005				
W	Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.									
W	ited States any false, fictitious or									

W. Teas Unit #943 WORKOVER PROCEDURE

GENERAL INFORMATION

Location: 2310' FSL & 990' FEL, Sec 9 – T20S – R33E <u>API No.:</u> 30-025-33004

WELL INFORMATION

String OD	<u>Weight & Grade</u>	Depth	<u> </u>	<u>Drift</u>	<u>Burst</u>	TOC
8-5/8"	24# J-55	0'-1310'	8.097"	7.972"	2950	0'
5-1/2"	15.5# K-55 LTC	0' - 3358'	4.950"	4.825"	4810	0'

Perfs: Yates 3051 – 3250' (OA) Seven Rivers 3270 – 77'

TD/PBTD: 3358'/ 3284'

Pre-workover: Move and set Lufkin 320 from WTU 621.

- 1) MIRU workover unit. POOH w/ rods and PC rotor. POOH with 2-7/8" tubing and PC stator.
- 2) Move in wireline truck. Set a 5.5" CIBP at 3200'. Bail 1 sx of cement on plug.
- RIH w/ BP, short MA, and SN hydro-testing 2-7/8" tubing. Run a TAC above the top set of perforations. Land intake ~ 3170'. RIH w/ 1-1/2" insert pump on a Class D 76 rod taper, 33.8% of the string being 7/8". Space out, land pump and hang off on. PWOP.