Submit 3 Copies To Approp	oriate District	State of New Me	xico		Form C-103
Office E District I	Energy	, Minerals and Natur	ral Resources	WELL API NO.	May 27, 2004
1625 N. French Dr., Hobbs, District II	NM 88240 HARRE AAD		DIMIGION	30-025-06184	
District II HOBBS OF CONSERVATION DIVISION District III 1220 South St. Francis Dr.				5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410007 2 8 2011 Santa Fe NM 87505			STATE X		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & Gas 015823	Lease No.
SUI	NDRY NOTRECENSOD RI			7. Lease Name or 1	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)				Eunice Monument	
1. Type of Well: Oil	Well Gas Well] Other	:	8. Well Number	12
2. Name of Operator				9. OGRID Number	r 003044
Burgundy Oil & Gas of 3. Address of Operator				10. Pool name or V	Wildcat
	003 Midland, TX 79701				Grayburg-San Andres
4. Well Location				<u> </u>	
Unit Letter_	F:1980f	eet from theNorth_	line and19	80feet from t	heWestline
Section		ownship 20 South			ea County
	25403	on (Show whether DR,	RKB, RT, GR, etc.)		
	3540' application or Closure	Dr			
	oth to GroundwaterDist	ance from nearest fresh w	ater well Dista	ance from nearest surfac	ce water
Pit Liner Thickness:		ide Tank: Volume		nstruction Material	
	2. Check Appropriate	Box to Indicate N	ature of Notice.	Report or Other I	— Data
			1		•
NOTI PERFORM REMEDIA	ICE OF INTENTION	TO: ABANDON □	REMEDIAL WOR	SEQUENT REP	'ORTOF: ALTERING CASING □
TEMPORARILY ABAN	<u> </u>		COMMENCE DRII		P AND A
PULL OR ALTER CAS			CASING/CEMENT		
	rn to Production	\boxtimes	OTHER:		
OTHER: Retu	osed or completed operatio	ns. (Clearly state all p	pertinent details, and	l give pertinent dates	s, including estimated date
OTHER: Retu	osed or completed operation proposed work). SEE RU	ns. (Clearly state all p	pertinent details, and	l give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion	osed or completed operation proposed work). SEE RU on.	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	l give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP	osed or completed operation proposed work). SEE RU	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	l give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30	osed or completed operation proposed work). SEE RU on. Output @ 3600'& push to bottom 650' - test csg to 500 # 610'	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	l give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5	osed or completed operation proposed work). SEE RU on. Oward 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	I give pertinent dates ach wellbore diagran	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5	osed or completed operation proposed work). SEE RU on. Output @ 3600'& push to bottom 650' - test csg to 500 # 610'	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	l give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5 5) Acidize well w	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	I give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x 5 5) Acidize well w 6) Swab test 7) Put on rod pure	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl	ns. (Clearly state all p LE 1103. For Multipl	pertinent details, and	I give pertinent dates ach wellbore diagran	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x 5 5) Acidize well w 6) Swab test 7) Put on rod pur The Oil (osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl on p & potential Conservation Division	ns. (Clearly state all pLE 1103. For Multipl	pertinent details, and	I give pertinent dates ach wellbore diagrar	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours	ns. (Clearly state all pLE 1103. For Multipl	pertinent details, and	I give pertinent dates rach wellbore diagran	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl on p & potential Conservation Division	ns. (Clearly state all pLE 1103. For Multipl	pertinent details, and	I give pertinent dates ach wellbore diagran	s, including estimated date
OTHER: Retu 13. Describe proportion of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test w/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours	ns. (Clearly state all pLE 1103. For Multipl	pertinent details, and	I give pertinent dates rach wellbore diagran	s, including estimated date
13. Describe propos of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5 5) Acidize well w 6) Swab test 7) Put on rod pur The Oil (MUST BE Prior to the	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test v/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation	ns. (Clearly state all pLE 1103. For Multipl	pertinent details, and le Completions: Att	ach wellbore diagran	s, including estimated date in of proposed completion
13. Describe proposed starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5 5) Acidize well w 6) Swab test 7) Put on rod pur The Oil C MUST BE Prior to the	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test v/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation in the complete structure information above is true.	ns. (Clearly state all pLE 1103. For Multiple) n and complete to the be	pertinent details, and le Completions: Att	e and belief. I further	s, including estimated date in of proposed completion
13. Describe proposed starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test v/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation	and complete to the beg to NMOCD guidelines	est of my knowledge	e and belief. I further	s, including estimated date in of proposed completion of proposed plan of the completion of proposed plan of the completion of proposed plan of the completion of the completion of proposed completion of pro
13. Describe proposed starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x 5 5) Acidize well w 6) Swab test 7) Put on rod pur The Oil C MUST BE Prior to the	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test v/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation in the complete structure information above is true.	and complete to the beg to NMOCD guidelines	est of my knowledge	e and belief. I further	s, including estimated date in of proposed completion of proposed plan of the completion of proposed plan of the completion of proposed plan of the completion of the completion of proposed completion of pro
13. Describe proposed starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test of 1000 gal 15% Hel on the potential Conservation Division C NOTIFIED 24 Hours beginning of operation information above is true constructed or closed according to the constructed or closed accordi	and complete to the beg to NMOCD guidelines	est of my knowledge a general permit	e and belief. I further or an (attached) alternat	s, including estimated date in of proposed completion certify that any pit or belowtive OCD-approved plan ATE10/25/11_
13. Describe propos of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600' - 30 4) RIH w/ pkr x x x x x x x x x x x x x x x x x x x	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test ov/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation constructed or closed according C information above is true constructed or closed according C indy K. Campbell E-100 proposed according C indy K. Campbell E-100 proposed work).	and complete to the beg to NMOCD guidelines [TITLE_ mail address: ccampb	pertinent details, and le Completions: Att	e and belief. I further or an (attached) alternate tantDA	s, including estimated date in of proposed completion certify that any pit or below-tive OCD-approved plan ATE10/25/11_ 432-684-4033
13. Describe propos of starting any or recompletion 1) Drill out CIBP 2) Set CIBP @ 3 3) Perf 3600° - 30 4) RIH w/ pkr x s 5) Acidize well w 6) Swab test 7) Put on rod pur The Oil C MUST BE Prior to the I hereby certify that the grade tank has been/will be SIGNATURE Type or print name	osed or completed operation proposed work). SEE RU on. 2 @ 3600'& push to bottom 650' – test csg to 500 # 610' SA 3550' & swab test ov/ 1000 gal 15% Hcl on a potential Conservation Division C NOTIFIED 24 Hours beginning of operation constructed or closed according Cindy K. Campbell E-clindy K. Campbe	Ins. (Clearly state all place in the least of the least o	est of my knowledge a general permit	e and belief. I further or an (attached) alternate tantDA	s, including estimated date in of proposed completion certify that any pit or belowtive OCD-approved plan ATE10/25/11_

Burgundy Oil & Gas of New Mexico, Inc.

Eunice Monument Unit No. 12

Unit Letter F, Sec. 19, T-20-S, R-37-E

Lea Co., New Mexico

API#: 30-025-06184

Equipment & Design:

Burgundy Oil & Gas of New Mexico, Inc. will use a closed loop system in the process of returning this well to production. The following equipment will be on location:

(1) 160 bbl steel reverse tank

Operations & Maintenance:

During each day of operation, the rig's crew will inspect and closely monitor the fluids contained within the steel tank and visually monitor any release that may occur. Should a release, spill or leak occur, the NMOCD District 1 office Hobbs (575-393-6161) will be notified, as required in NMOCD's rule 19.15.29.8.

Closure:

After plugging operations, fluids and solids will be hauled and disposed at Sundance Disposal, permit number NM-01-0003. Secondary site will be CRI, permit NM-01-0006.