	Submit 1 Copy To Appropriate District Office	State of New M	exico	Form C-103
	District I - (575) 393-6161	Energy, Minerals and Nat		October 13, 2009
	1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	·		WELL API NO.
	811 S. First St., Artesia, NM 882 1010BBS	OC DIL CONSERVATION	DIVISION	30-025-09136
	District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fra	ncis Dr.	5. Indicate Type of Lease STATE X FEE
	District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, C. T 2 8 87505	2011 Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
	SUNDRY NOTIC	ES AND REPORTS ON WELLS	<u> </u>	7. Lease Name or Unit Agreement Name
	(DO.NOT USE THIS FORM FOR PRODUCT DIFFERENT RESERVOIR. USE "APPLICA	USE DRILL OR TO DEEPEN OR PL	UG BACK TO A	
	PROPOSALS.)	•		SEVEN RIVERS QUEEN UNIT 8. Well Number: 037
	2. Name of Operator LINN OPERATING, INC.	as Well Other INJECTION		9. OGRID Number 269324
	3. Address of Operator			10. Pool name or Wildcat
	600 TRAVIS, SUITE 5100, HOUST	ON, TEXAS 77002		EUNICE;SEVEN RIVERS-QUEEN,
	4. Well Location	, i i i i i i i i i i i i i i i i i i i		500111
	Unit LetterO; 990	feet from theS	line and 2	310 feet from the E line
	Section 34	Township 22S	Range 36	E NMPM LEA County
		11. Elevation (Show whether DR 3,496' GR	, RKB, RT, GR, etc.	
		·		
	12. Check Ap	propriate Box to Indicate N	lature of Notice,	Report or Other Data
	NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:
	PERFORM REMEDIAL WORK 🔲		REMEDIAL WOR	
		CHANGE PLANS	COMMENCE DR	
	PULL OR ALTER CASING III DOWNHOLE COMMINGLE III		CASING/CEMEN	Т ЈОВ
			,	
	OTHER:	П		
	OTHER: 13. Describe proposed or complete	ed operations. (Clearly state all	OTHER: pertinent details, an	d give pertinent dates, including estimated da
	OTHER: 13. Describe proposed or complete). SEE KULE 19.15.7.14 NMA(pertinent details an	d give pertinent dates, including estimated dat mpletions: Attach wellbore diagram of
	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom). SEE RULE 19.15.7.14 NMA(apletion.	pertinent details, an C. For Multiple Co	d give pertinent dates, including estimated da mpletions: Attach wellbore diagram of
	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recon RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10	pertinent details, an C. For Multiple Co	mpletions: Attach wellbore diagram of
	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980'). SEE RULE 19.15.7.14 NMA(ipletion. کی CMT ON TOP الک مراحد الحداد المراحد المراحد (COVERS 50' ABOVE & BEL	pertinent details, an C. For Multiple Co	mpletions: Attach wellbore diagram of
	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28). SEE RULE 19.15.7.14 NMA(ipletion. کی CMT ON TOP (COVERS 50' ABOVE & BELG 80'	pertinent details, an C. For Multiple Co LF OW THE BASE OI	mpletions: Attach wellbore diagram of F SALT).
F¢S	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.2 → Cile Feole w/ M (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30'	Dertinent details, an C. For Multiple Co LF DW THE BASE OF OW THE TOP OF	mpletions: Attach wellbore diagram of F SALT) SALT)
F¢E ZSQ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530'). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.7 → Cille Feolew/W (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE &	Dertinent details, an C. For Multiple Co LF DW THE BASE OF OW THE TOP OF	mpletions: Attach wellbore diagram of F SALT) SALT)
F¢E ZSQ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.7 → Cille Feolew/W (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE &	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified
F¢E ZSQ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.7 → Cille Feolew/W (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE &	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified
F#F GZ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion of recom RIH & SET A CIBP AT 3610' W/ 35 3 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.2 → Cile feelew/M (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified
F#F GZ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.7 → Cille Feolew/W (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE &	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified
F#F GZ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion of recom RIH & SET A CIBP AT 3610' W/ 35 3 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.2 → Cile feelew/M (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified
ġŹŹ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion of recom RIH & SET A CIBP AT 3610' W/ 35 3 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10.7 → Cille Feelew/W (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & 1 UP LOCATION Rig Release E	Dertinent details, an C. For Multiple Co DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric	mpletions: Attach wellbore diagram of F SALT). SALT) DE) servation Division Must be notified or to the beginning of plugging operation
ġŹŹ	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 F WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338''& CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN Spud Date:	b) SEE RULE 19.15.4.14 NMA(ipletion. SXS CMT ON TOP (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION Rig Release E Dive, is true and complete to the be	pertinent details, an C. For Multiple Co LF OW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified or to the beginning of plugging operation
r Z S Q	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 F WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338''& CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN Spud Date:	b) SEE RULE 19.15.4.14 NMA(ipletion. SXS CMT ON TOP (COVERS 50' ABOVE & BEL 80' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION Rig Release E Dive, is true and complete to the be	pertinent details, an C. For Multiple Co LF OW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified or to the beginning of plugging operation
259 259	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion of recom RIH & SET A CIBP AT 3610' W/ 35 3 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN Spud Date: I hereby certify that the information ab SIGNATURE MARK MARKER & CALLA	b) SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP IO → Cile - heale w/ W (COVERS 50' ABOVE & BEL 30' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION Rig Release E Ove, is: true and complete to the be Mac	Dertinent details, an C. For Multiple Co LF DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric L est of my knowledg	F SALT) SALT) DE) servation Division Must be notified or to the beginning of plugging operation e and belief.
259 259	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom RIH & SET A CIBP AT 3610' W/ 35 F WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338''& CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN Spud Date:	b) SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP IO → Cile - heale w/ W (COVERS 50' ABOVE & BEL 30' (COVERS 50' ABOVE & BEL 30' ACE (COVERS 50' ABOVE & UP LOCATION Rig Release E Ove, is: true and complete to the be Mac	Dertinent details, an C. For Multiple Co LF DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric L est of my knowledg	mpletions: Attach wellbore diagram of F SALT) SALT) DE) servation Division Must be notified or to the beginning of plugging operation e and belief. ALIST III_DATE OCTOBER 27, 2011
₽ ₽₽₽ \$ \$ 1 1 1 1	OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion of recom RIH & SET A CIBP AT 3610' W/ 35 3 WOC & TAG NO LOWER THAN 35 RIH & SET A 25 SX PLUG AT 2980' WOC & TAG NO LOWER THAN 28 RIH & SET A 25 SX PLUG AT 1530' WOC & TAG NO LOWER THAN 14 RIH TO 338' & CIRC CMT TO SURF SET DRYHOLE MARKER & CLEAN Spud Date: I hereby certify that the information ab SIGNATURE MARK MARKER & CALLA). SEE RULE 19.15.7.14 NMA(ipletion. SXS CMT ON TOP 10	Dertinent details, an C. For Multiple Co LF DW THE BASE OF OW THE TOP OF BELOW CSG SHO The Oil Cons 24 hours pric L est of my knowledg	mpletions: Attach wellbore diagram of F SALT). SALT) DE) servation Division Must be notified or to the beginning of plugging operation e and belief. ALIST III_DATE OCTOBER 27, 2011 PHONE: 281-840-4272

OCT 3 1 2011

•

Wellbore Diagram

Former Name

Lease & Well No.	Seven Rivers Queen Unit #37	
Field Name	Langlie Mattix	_
Location	990' FSL & 2,310' FEL; T: 22S R: 36E Sec: 34	
<u>K.B Elevation</u> D.F. Elevation Ground Level	3,496	

		Surfa	ce Casing		
Size (OD)	8 5/8*	Weight	24.0#	Depth	288'
Grade		Sx, Cmt,	200 sx	TOC	Unknown
		Destur	ion Casing		
	<u> </u>	<u>21000001</u>	ion Casing		
Size (OD) Grade	5 1/2"	Weight	14.0#	Depth	3,750

Production Tubing					
Size (OD)	2 7/8"	Weight	13-20#	Depth	3,614'
Grade		<u>Sx. Cmt.</u>	Unknown	TOC @	Surface

Well History

2/20/57 - Spud Well

- 2/21/57 Set 8-5/8" csg string @ 288"; Cmtd w/ 200 sx cmt;
- 3/3/57 Set 5-1/2" cst string @ 3,750'; Cmtd w/ 300 sx cmt;
- 3/4/57 Perfd 3,644 52', 3,678 88' & 3,700 30' @ 4 spf; Spotted 500 gals acid on perfs & frac'd same in 2 stgs, Stg 1 - 7,000 gals lease crude + 10,500# sd + 100 BS, Stg 2 - 3,000 gals lease crude + 4,500# sd; put wel 1 on production
- 7/21/64 deepened well f/ 3,751 82'; RIH w/ pkr & set same @ 3,728'; Acdz w/ 1,000 gals acid & attempted to frac same; Backsidecommunication occurred around esg shoe when attempting to frac; POH w/ cased hole pkr & run open hole pkr; set same @ 3,750', communication occurred again; RIH and fished pkr rubbers, put well back on production
- 12/10/71 POH w/ rods & tbg; Perfd # 3,527, 38', 51', 58', 72', 90', 3,602' & 11' @ 1 spf; Set RBP @ 3,625' & acdz perfs w/ 1,500 gals 15% LSTNE acid; frac'd same w/ 40,000 gals H2O + 60,000# sd; POH w/ RBP & RIH w/ production equipment
- 4/17/72 Perfd f/ 3,521', 32', 44', 55', 73', 85', 3,602' & 14' @ l spf; Acdz same w/ 1,500 gals 15% HCl & frac'd same w/ 40,000 gals 9# brine + 50,000# 20/40 sd;
- 11/26/73 tagged fill @ 3,705' (77' total); Made bit & scraper run to 3,705' & POH; RIH w/ RBP & pki & set same @ 3,665' & 3,446', respectively; Sq2d perfs f/ 3,521 3,652' w/ 150 sx; Rev out 28 sx cmt; WOC, RIH w/ bit & tag @ 3,452'; Drld out cmt f/ 3,593 3,656'; Tstd sq2 to 1,000 psi for 30 mins, held ok; Clnd out frac sd f/ 3,705 3,782', RIH w/ inj. Tbg + pkr & set same at 3,660',
- 3/5/74 well commenced injection

6/17/82 - POH w/ mj Tbg and pkr, clnd out 25' of fill, RIH w/ inj. Tbg & pkr & set same @ 3,646' 5/11/01 - well reported to lose pressure on backside test;

11/14/06 - POH w/ inj. Tbg and pkr, RIH w/ 2-7/8" IPC tbg + tension pkr w/ pump out sleeve; Set pkr @ 3,614'; Pumped 71 bbis Cl 'C' emt followed by 20 bbls of fresh H2O displacment; Did not circulate emt, RIH w/ perf guns & perf 4 sqz holes @ 1,950'; Pumped emt & eire emt to surface

Formation Record	Depth
Anhydrite	1,380
Top of Salt	1,480'
Base of Salt	2,930'
Yates	3,100'
7 Rivers	3,370
Queen	3,684'



Plug Back Depth	3,780'
Total Depth	3,782

LINN OPERATING, INC. SEVEN RIVERS QUEEN UNIT #037 UNIT O, SEC 34, T-22-S, R-36-E LEA COUNTY, NM API#: 30-025-09136 Item #4 Form C-144 CLEZ Attachment

Equipment & Design:

D&L Meters and Instrument Service, Inc. will use a closed loop system in the plugging and abandonment of this well. The following equipment will be on location:

(1) 500 bbl steel tank

Operations & Maintenance

During each day of operation, the rig's crew will inspect and closely monitor the fluids contained within the steel tank and visually monitor any release that may occur. Should a release, spill or leak occur, the NMOCD District 1 office Hobbs (575-393-6161) will be notified, as required in the NMOCD's rule 19.15.29.8.

<u>Closure</u>

After plugging and abandonment operations, fluids and solids will be hauled and disposed at CRI's (Control Recovery Inc.) location, permit number NM 01-0019. Secondary site will be Gandy-Marley Disposal, permit number NM 01-0006.

Wellbore Diagram

Lease & Well No.	Seven Rivers Queen Unit #37			
Field Name	Langlie Mattix			
Location	990' FSL & 2,310' FEL; T: 22S R: 36E Sec. 34			
K.B. Elevation D.F. Elevation Ground Level	4,006'			

		Surfa	e Casing		
Size (OD)	8 5/8"	Weight	24.0#	Depth	288'
Grade		Sx. Cmt.	200 sx	TOC@	Unknown
		Product	ion Casing		
Size (OD)	5 1/2"	Weight	14.0#	Depth	3,750'
<u>Grade</u>		Sx. Cmt.	300 sx	<u> </u>	Unknown

Production Tubing						
Size (OD)	2 7/8*	Weight	13-20#	Depth	3,614'	
Grade		Sx. Cmt.	Unknown	<u>TOC @</u>	Surface	

P&A Procedure

RIH & set a CIBP at 3610' w/ 35 sxs cmt on top.

WOC & tag no lower than 3510'.

RIH & set a 25 sx plug at 2980' (covers 50' above & below the base of sait). WOC & tag no lower than 2880'.

RIH & set a 25 sx plug at 1530' (covers 50' above & below the top of salt) WOC & tag no lower than 1430'.

RIH to 338° & circ cmt to surface (covers 50' abover & below csg shoe) Set dryhole marker & clean up location.

Formation Record	Depth
Anhydrite	1,380'
Top of Salt	1,480'
Base of Salt	2,930
Yates	3,100
7 Rivers	3,370'
Queen	3,684'

