| Submit 1 Copy To Appropriate District State of | of New Mexico | Form C-103 |
|--|--|--|
| Office District I – (575) 393-6161 | als and Natural Resources | Revised August 1, 2011 |
| 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 | | WELL API NO. 30-025-37849 / |
| 811 S. First St., Artesia, NM 88210 | RVATION DIVISION | 5. Indicate Type of Lease |
| 1000 Dio Drazos Dd. Azteo, NM 97410 | uth St. Francis Dr. | STATE 🛛 / FEE 🗌 |
| District IV – (505) 476-3460 Santa | Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | |
| SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOR | EEPEN OR PLUG BACK TO A | 7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit 2 |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other | | 8. Well Number 19 |
| 2. Name of Operator | | 9. OGRID Number |
| Name of Operator ConocoPhillips Company | | 217817 🗸 |
| 3. Address of Operator _{3300 N} "A" St | | 10. Pool name or Wildcat |
| Midland, TX 79705 | | Vacuum; Glorieta |
| 4. Well Location Unit Letter B: 685' feet from the North line and 1550' feet from the East line | | |
| Section 32 Township | | NMPM County LEA |
| | whether DR, RKB, RT, GR, etc.) | TVM VI |
| | | |
| | | |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | |
| NOTICE OF INTENTION TO: | SUBS | SEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK \ \ PLUG AND ABANDO | | |
| TEMPORARILY ABANDON CHANGE PLANS | ☐ COMMENCE DRIL | LING OPNS. P AND A |
| PULL OR ALTER CASING MULTIPLE COMPL | ☐ CASING/CEMENT | JOB |
| DOWNHOLE COMMINGLE | | |
| | | |
| OTHER: change out pump type | | |
| 13. Describe proposed or completed operations. (Clea | arly state all pertinent details, and | give pertinent dates, including estimated date |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 | arly state all pertinent details, and | give pertinent dates, including estimated date appletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. | orly state all pertinent details, and 5.7.14 NMAC. For Multiple Com | ppletions: Attach wellbore diagram of |
| Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to complete the complete of the complet | orly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. | repletions: Attach wellbore diagram of COOH with rods, tubing, and pump, scan |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion.Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f | only state all pertinent details, and 5.7.14 NMAC. For Multiple Componvert from a rod pump to ESP. for inspection. RIH with bit, scrap | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly |
| Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. n well is ready to put on production submersible pump @ +/- 5984 | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 | onvert from a rod pump to ESP. for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perf. In well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to w Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to contubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Spud Date: | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need graph. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to catubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need graph. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to contubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Spud Date: | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need graph. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Spud Date: Ri I hereby certify that the information above is true and compared to the co | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need graph. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Spud Date: Ri Thereby certify that the information above is true and composition of the composition of | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP, for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 ppsi while RIH. Replace as need of submersible pump while RIH. Replace as need of the best of my knowledge of the staff Regulatory Technician states. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. DATE 12/15/2011 |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Specialist structures are supported by the structure of the structur | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with neware that motor is above top perf. In well is ready to put on production submersible pump @ +/- 5984 psi while RIH. Replace as need graph. Replace as need graph. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '.' ed. DATE 12/15/2011 |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Spud Date: Ri Thereby certify that the information above is true and composition of the composition of | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP. For inspection. RIH with bit, scraping, scraper and bit. RIH with neware that motor is above top perf. In well is ready to put on production of submersible pump @ +/- 5984 psi while RIH. Replace as need of the perf. Replace as need of the perf. The performance of the performa | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. DATE 12/15/2011 hillips.com PHONE: (432)688-9174 |
| 13. Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 19.15 proposed completion or recompletion. Currently the well is still producing. Job proposal is to cutubing while COOH. Replace as needed. Send rods in f 5000 psi while RIH. Replace as needed. COOH with tub 3/8" capillary string. Land end of pump @ +/- 5984', ens before RDMO WSU. Contact Production Specialist whe Pump:Run new Baker Hughes designed ESP. Land end Tubing:Scan tubing while COOH and test tubing to 5000 Specialist structures are supported by the structure of the structur | arly state all pertinent details, and 5.7.14 NMAC. For Multiple Component from a rod pump to ESP, for inspection. RIH with bit, scraping, scraper and bit. RIH with newer that motor is above top perform well is ready to put on production submersible pump @ +/- 5984 ppsi while RIH. Replace as need of submersible pump while RIH. Replace as need of the best of my knowledge of the staff Regulatory Technician states. | COOH with rods, tubing, and pump, scan per and tubing to +/- 6050', testing tubing to we Baker Hughes designed ESP, tubing, and Ensure that the pump is operating correctly on. '. ed. DATE 12/15/2011 hillips.com PHONE: (432)688-9174 |