Submit I Copy To Appropriate District State of New Mexico	Form C-103
Office <u>District 1</u> – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <b>HOBBS OCD</b>	WELL API NO. 30-005-00813
OIL CONSERVATION DIVISION	5. Indicate Type of Lease
$\frac{\text{District III}}{1000 \text{ Rio Brazos Rd., Aztec, NM 8741}} \text{JAN 2 6 2012} 1220 \text{ South St. Francis Dr.} Santa Fe, NM 87505$	STATE X FEE
$\frac{District IV}{1220 \text{ S. St. Francis Dr., Santa Fe, NM}}$	6. State Oil & Gas Lease No.
87505 BECEN/ED	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Rock Queen Unit
PROPOSALS) 1. Type of Well: Oil Well 🕅 Gas Well 🗌 Other	8. Well Number 23
2. Name of Operator Celero Energy II, LP	9. OGRID Number
3. Address of Operator 400 W. Illinois, Ste. 1601	247128 /
Midland, TX 79701	Caprock; Queen
4. Well Location	
Unit Letter A : 660 feet from the N line and 660 feet from the E line	
Section 22 Township 13S Range 31E	NMPM County Chaves
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DR	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	т јов 🔲
OTHER: OTHER: TA	X
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> </ol>	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.	mpletions: Attach wellbore diagram of
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> <li>1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &amp; w/ seat nipple, 4' perf sub &amp; homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's &amp; 100 memory of the section of the secti</li></ul>	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole.
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> <li>1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &amp; w/ seat nipple, 4' perf sub &amp; homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's &amp; TOH &amp; LD DC's. PU 5 ½" scraper &amp; TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c</li> </ul>	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion.</li> <li>1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &amp; w/ seat nipple, 4' perf sub &amp; homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's &amp; 100 memory of the section of the secti</li></ul>	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.</li> <li>1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &amp; w/ seat nipple, 4' perf sub &amp; homemade wire catcher. PU 4 ¾" RR bit, 6- 3 ½" DC's &amp; TOH &amp; LD DC's. PU 5 ½" scraper &amp; TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP &amp; TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/</li> </ul>	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cint on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary Abandonment Expires	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6- 3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary //18/201 Abandonment Expires/18/201 Spud Date:	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cint on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary Abandonment Expires	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co         proposed completion or recompletion.         1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &         w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c         2921'. Get off CIBP & TOH. Dump bail 35' of cimt on top of plug. WOC 2 hrs. TIH w/         MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no         This Approval of Temporary //18//201         Abandonment Expires         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowledge	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3. ge and belief.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¼" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cint on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary Abandonment Expires Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE And Advantant Structure TITLE Regulatory Analyst	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3 ge and belief. DATE 01/24/2012
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co         proposed completion or recompletion.         1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH &         w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¼" RR bit, 6-3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c         2921'. Get off CIBP & TOH. Dump bail 35' of cint on top of plug. WOC 2 hrs. TIH w/         MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no         This Approval of Temporary //18/201         Abandonment Expires         Spud Date:         Rig Release Date:         I hereby certify that the information above is true and complete to the best of my knowledge         SIGNATURE       Juan         Type or print name       Lisa Hunt	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3 ge and belief. DATE 01/24/2012
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6- 3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary Abandonment Expires/18/201 Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE August TITLE Regulatory Analyst Type or print name Lisa Hunt E-mail address: <u>lhunt@celeroene</u> For State Use Only	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3. Be and belief. DATE 01/24/2012 PHONE: (432)686-1883
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 1/13 - 1/18/12 - Pulled 1 ¼" polish rod w/ liner. Had no rods connected to it. NDWH & w/ seat nipple, 4' perf sub & homemade wire catcher. PU 4 ¾" RR bit, 6- 3 ½" DC's & TOH & LD DC's. PU 5 ½" scraper & TIH to 2947'. Circ well. LD 6 jts. TOH w/ 5 ½" c 2921'. Get off CIBP & TOH. Dump bail 35' of cmt on top of plug. WOC 2 hrs. TIH w/ MIT. Test for 30 mins. Pressure to 660# and held. Original chart is attached. Well is no This Approval of Temporary Abandonment Expires/18/201 Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE August TITLE Regulatory Analyst Type or print name Lisa Hunt E-mail address: <u>lhunt@celeroene</u> For State Use Only	mpletions: Attach wellbore diagram of NUBOP. TOH w/ 74 jts 2 3/8" 4.7# J-55 tbg FIH w/ 88 jts 2 7/8" WS to 2948'. Circ hole. sg scraper. TIH w/ 5 ½" CIBP & set @ 2 7/8" WS & circ hole w/ inhibited FW. Ran w TA'd for 1 year. 3. ge and belief. DATE 01/24/2012

MAN 2 6 2012



سيسيد والمراجع