State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

p

FILE IN TRIPLICATE	
FILE IN TRIPLICATE HOBBS OCD OIL CONSERVATION DIVISION DISTRICT I 1220 South St. Francis Dr.	WELL API NO 30-025-29893
1625 N French Dr , Hobbs, NM 8824AN 27 2012 Santa Fe, NM 87505	5 Indicate Type of Lease
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X
DISTRICT III RECEIVED	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	South Hobbs (G/SA) Unit
1 Type of Well Oil Well X Gas Well Other	8 Well No 222
2 Name of Operator Occidental Permian Ltd.	9 OGRID No 157984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4 Well Location	• From The Million Lung
Unit Letter L 2019 Feet From The South 817 Fee	t From The West Line
Section 34 Township 18-S Range 38-I	S NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) '3625' GL	
Pit or Below-grade.Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	NS PLUG & ÁBANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	
OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	including estimated data of starting any
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
1. Kill well.	
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. 	
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. 	completion or recompletion.
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. 	completion or recompletion.
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. 	completion or recompletion.
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. 	completion or recompletion.
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. 	completion or recompletion.
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running	CD Hobbs MIT Test & Chart
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office according to NMOCD guidelines , a general permit or an (attached) alternativ plan	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office according to NMOCD guidelines , a general permit or an (attached) alternativ plan SIGNATURE MULTICE Administrative 	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office 24 hours prior to running I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012
1. Kill well. 2. POOH & lay down tubing & ESP equipment. 3. Clean out to 4080'. 4. RIH w/CIBP set @4050'. Cap w/35' of cement. 5. Test casing and chart for the NMOCD. 6. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office 24 hours prior to running office according to NMOCD guidelines, a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012 TELEPHONE NO 806-592-6280
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office and belief I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012
1. Kill well. 2. POOH & lay down tubing & ESP equipment. 3. Clean out to 4080'. 4. RIH w/CIBP set @4050'. Cap w/35' of cement. 5. Test casing and chart for the NMOCD. 6. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office 24 hours prior to running office according to NMOCD guidelines, a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012 TELEPHONE NO 806-592-6280
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office and belief I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012 TELEPHONE NO 806-592-6280
 Kill well. POOH & lay down tubing & ESP equipment. Clean out to 4080'. RIH w/CIBP set @4050'. Cap w/35' of cement. Test casing and chart for the NMOCD. Install TA wellhead. Top open perf @4140' Condition of Approval : Notify O office 24 hours prior to running office 24 hours prior to running office and belief I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE	CD Hobbs MIT Test & Chart that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 01/25/2012 TELEPHONE NO 806-592-6280

.